

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0572/2024/KS
DATE : 25-Jul-24
WIP : 24619

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MS LAU MENG HONG REGINA
ADDRESS : 11 ARNASALAM CHETTY ROAD
#13-10
SINGAPORE 239949
TELEPHONE : HP +65 96781112
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : MPC24B00066600
VEHICLE NO : SJW 168 K
MODEL CODE : BMW 330I
MODEL YEAR : 18/6/2019
ENGINE NO : 10145616B42B20B
CHASSIS NO : WBA5R12000AK72053
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Jul-24
PLACE OF ACCIDENT : 53 UBI ROAD 1, SINGAPORE 408698

55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHA@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJW 168 K.

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND FRONT PARKING AID.	S/N \$	360.00	80.
2	TO REMOVE AND TRANSFER RHS HEADLIGHT CONTROL UNIT AND POWER MODULE	S/N \$	350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	800
4	TO RESRPAY FRONT BUMPER AND BONNET	\$	1,850.00	800
6	TO SUPPLY AND RE-APPLY PAINT PROTECTION FILM	S/N \$	2,100.00	? ✓ 2,100.00
7	TO SUPPLY AND RE-APPLY PAINT COATING	S/N \$	400.00	? ✓ 400.00
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	292.00	200.
TOTAL LABOUR CHARGES		:	\$ 7,452.00	

PREMIUM AUTOMOBILES



55, UBI ROAD 1, SINGAPORE 408695
TEL: 6396 2323 FAX: 6341 1183
EMAIL: NORA.KHAU@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJW 168 K.

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Dented</i>	1	\$ 2,850.00 ✓	2,280.00
2	FRONT BUMPER SIDE GUIDE - LH / RH <i>new</i>	2	\$ 654.00 ✓	
3	FRONT BUMPER UPPER SIDE GUIDE - LH / RH <i>new</i>	2	\$ 106.00 ✓	
4	FRONT BUMPER SUPPORT - LH / RH <i>new</i>	2	\$ 96.00 ✓	
5	AIR DUCT BRACKET <i>Not new</i>	1	\$ 1,438.00 ✓	
6	RADIATOR GRILLE <i>Cracked</i>	1	\$ 600.00 ✓	480.00
7	BONNET <i>Dented</i>	1	\$ 3,300.00 ✓	2,640.00
8	BONNET LOGO <i>New</i>	1	\$ 181.00 ✓	144.80
9	FRONT BUMPER CENTER COVER <i>new</i>	1	\$ 305.00 ✓	244.00
10	COOLANT INFO STICKER <i>new</i>	1	\$ 71.00 ✓	56.80
11	BONNET SEAL <i>?</i>	1	\$ 135.00 ?X	
12	COVER OF CENTRE ENGINE COMPARTMENT <i>new</i>	1	\$ 375.00 ✓	
13	FRONT NO PLATE <i>Cracked</i>	S/N	\$ 150.00 ✓	80.
14	SUNDRIES <i>?</i>		\$ 700.00 ?X	
TOTAL SPARE PARTS		:	\$ 10,961.00	
TOTAL LABOUR CHARGES		:	\$ 7,452.00	
GRAND TOTAL		:	\$ 18,413.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED. REMARKS (X) = NOT APPROVED



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *r*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not authorized, 04 days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT