

FALCON AIR AUTO SERVICES PTE LTD

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709559

Date : 23/07/2024

Vehicle Num. : SMF 5822B

Make/Model : HYUNDAI ELANTRA

Chassis/Eng# :

Accident Date : 23/07/2024

Claim No. :

Reference :

Policy No. :

not Authorized
in
means
25/7/24
4/5 \$ 4400
the photo Henry
5 days.

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LIST ITEMS :				
1.	1PC	FRONT BUMPER	498.20	593.00 ✓
2.	2PCS	FRONT BUMPER SIDE RETAINER	35.00	70.00 X
3.	2PCS	FRONT BUMPER SIDE BRACKET	28.00	56.00 X
4.	2PCS	HEADLAMP	1,384.00	2,768.00 ✓
5.	1PC	N/S HEADLAMP LOWER BRACKET		38.00 X
6.	1PC	N/S FRONT FENDER		1,440.00 X
7.	1PC	N/S FRONT FENDER INNER SHIELD		165.00 X
8.	1PC	RADIATOR GRILLE ASSY	529.20	665.00 ✓
9.	1PC	RADIATOR SUPPORT PANEL	802.30	950.00 ✓
10.	1PC	BONNET		2,254.00 X
11.	1PC	FRONT BUMPER REINFORCEMENT	582.30	696.00 ✓
12.	1PC	FRONT BUMPER SPONGE		131.00 ✓
13.	1PC	N/S RADIATOR AIR GUIDE		45.00 X
14.	1PC	N/S FOG LAMP COVER		98.00 X
List TotalS\$:				9,969.00
20.00% Discount S\$:				1,993.80
				7,975.20

SPECIAL NETT ITEMS :				
1.	1SET	FRONT BUMPER CLIP	30	50.00

CONTINUE / ...

FALCON AIR AUTO SERVICES PTE LTD

Page 2 / 2

Tel No. :

LIBERTY INSURANCE PRIVATE LIMITED
51 CLUB STREET #03-00 LIBERTY HOUSE
SINGAPORE 069428

Attention : Motor Claim Department

Contact : 62218611 Fax No. : 62241047

Estimate : ES709559

Date : 23/07/2024

Vehicle Num. : SMF 5822B

Make/Model : HYUNDAI ELANTRA

Chassis/Eng# :

Accident Date : 23/07/2024

Claim No. :

Reference :

Policy No. :

S/N	Quantity	Particular	Unit Price	Amount S\$
2.	1SET	FRONT BUMPER RIVET 11		
3.	1SET	N/S FRONT FENDER INNER SHIELD CLIP 11		50.00
4.	1PC	FRONT NUMBER PLATE 126		50.00
5.	1PC	FRONT NUMBER PLATE SEAL 121		50.00
Special Nett Total S\$:				250.00
LABOUR :				
TO CHECK LIGHT AND WIRING				20 50.00
TO VACCUM, REOIL AND REGAS AIR CON				100 120.00
TO BREAK SEAL AT LTA / RESEAL AT VICOM				30 100.00
LABOUR/PANEL BEATING				580 800.00
SPRAY PAINTING				800 1,000.00
Labour Total S\$:				2,070.00

E. & O.E.

Total S\$: 10,295.20
=====

for FALCON AIR AUTO SERVICES PTE LTD

TAMPINES BRANCH

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts
- Parts prices are subject to confirmation
- Third party survey is on a "Without Fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be repaired
- is subject to final approval from the insurer

Acknowledged by Repairer
Signature
Date

P- 4939
202
3951.20
77
1530
5488.20
202
4446.