Your Ref: TO BE ADVISED
Our Ref: 2024-3952/RC/PC



17/09/2024

LKK – for Mindef Singapore SBS Transit Ltd 205 Braddell Road Singapore 579701

> Mainline +65 6284 8866 Facsimile +65 6287 0311

www.sbstransit.com.sg

Company Registration No: 199206653M

Dear Hsiao Tong

ACCIDENT INVOLVING SG5021U & MID21536 ON 24/07/2024

We understand that you are the handler of vehicle no. MID21536, which was involved in the above accident with our bus no. SG5021U.

We are of the opinion that the accident was caused by the negligent driving of the driver. As a result of the accident, we have been put to loss and expense as follows:

| Cost of repair | \$ 244.40 | |
|----------------|--------------|-------------------|
| Loss of use | \$ 458.52 | (458.52 x 1.00) |
| Total | \$ 702.92 | |

We enclose the following supporting documents: -

| ☐ A copy of the GIA/ Police Report of SG5021U | ☐ Survey Report & Survey Bill |
|---|-------------------------------|
| ☐ A copy of the Certification for Bus Repair | ☐ GIA/LTA Search fee |
| ☐ Coloured Photographs / Scene Photographs | □ Others, |

We trust that you will settle this claim promptly to avert legal costs and interest charges. To this end, please treat this as notice in accordance with the protocol for Non-Injury Motor Accident litigation.

We look forward to hearing from you early in order to resolve this matter amicably at minimum cost to you.

Yours faithfully, Priscilla Chan Group Claims Unit DID: 63837026

Email: chanfl@sbstransit.com.sg

Please scan QR code to read SBS Transit Ltd Data Protection Policy:



The information contained in these documents may be privileged and confidential and is intended for the exclusive use of the addressee designated above. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error, please notify the sender immediately.





Accident Report



Certificate of Bus Repair

 Depot
 HG
 Bus No
 SG5021U

 Driver
 35342
 Accident Date
 Jul 24, 2024

Date IN Aug 12, 2024 **Date Out** Aug 12, 2024

| Registration Date | Model/Manufacturer | Chassis No. |
|-------------------|--------------------------------|-------------------|
| Jan 12, 2016 | Volvo B9TL Eu5, DD, AC, 3 Axle | YV3S4P920GA174845 |

| Stock | Description | Quantity | Total Material Cost |
|-------|-------------|----------|---------------------|
| Code | | | (S\$) |

Stock items not used in Work Order

| | | TOTAL FOR PARTS | S\$ | 0.00 |
|----------|---|--|-----|--------|
| S/N | S/N Labour / Spray Painting / Contractor Cost | | | Amount |
| 1 | 1 Workshop Labour | | S\$ | 188.00 |
| 2 | Contractor's Repair Charges | | S\$ | 0.00 |
| | | | | |
| | TOTAL LAB | OUR / SPRAY PAINTING / CONTRACTOR COST | S\$ | 188.00 |
| | | Repair cost of Advertisement / Livery | S\$ | 0.00 |
| | | TOTAL DAMAGE | S\$ | 188.00 |
| | | Overheads | S\$ | 56.40 |
| | | Towing Charges | S\$ | 0.00 |
| Repair P | eriod: 0.00 Days | Loss of Use | S\$ | 0.00 |
| | | TOTAL LOSS | S\$ | 244.40 |

| Name Gender | UNKNOWN Female |
|---|--|
| PASSENGER 7 | |
| Name Gender | UNKNOWN Male |
| DETAILS OF POLICE ACTION | |
| Was the accident reported to the police? Police Station Name Police Station Phone No Police Station Address Was notice of intended Prosecution given? | Yes Woodlands Division Headquarters (Phone) +65-18004660000 1 Woodlands St 12 Singapore 738622 |
| vvas notice of intended Frosecution given? | No |

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

On the mentioned date and time, I was informed by IS Gendrick Tan that I had involved in an accident with vehicle MID21536 on 24 July, at 11:13am at bus stop 59739. Upon reflecting on the events of that day, I recalled that on 24/7/24, a grp of military trucks had passed by my stationary bus at the mentioned bus stop. I was engaged in loading and unloading passengers at this bus stop. This particular bus stop only can accommodate one bus at a time. While performing my duties, I noticed an elderly passenger waiting at the bus stop. To ensure safe boarding, I decided to position the front door of my bus closer to the curb. During this maneuver, I did not notice any contact between my bus and the military vehicles. At no point did any of the military truck drivers approach me regarding an accident, nor did I observe any damages to rear of SG5021U. Given my lack of awareness of any collision or accident, I did not report to OCC. 20-30Pax onboard. No injury reported. That's all.

ATTACHMENT(S)

Are accident photos available for attachment?

Was there any video captured by Car Camera?

Reasons for not uploading a video of the accident

No

Yes

confidentiality issue

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number MID21536 Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Government Name of Driver **UNKNOWN** Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident Left view mirror damaged No. Of Passenger (Including Driver)

SBS Transit West District

Sketch Plan

| I/O In charge | : Ans clay toon |
|-------------------|-----------------|
| Report No : | AL-1014-4237 |
| Date & Time Acc : | |
| 意外日期與時間 | |
| Bus No: 巴士 車牌 ; | SBS 565021U |
| Svc No: 路線: | 117 |
| BC No: 工牌號碼: | 35342 |
| BC Name: 姓名: | Tay be Eng |
| Signature: 簽名: | 9 |
| Date: 日期: | 5-8-24 |

