

SMRT Accident Vehicle Repair Estimates

SMRT Autor 60 Woodland

FAX Number

Estimator Te Accident Res

Date Genera

User ID

A16

Remarks

	Section A - Accident Details				
Registration Number	SHD6433D				
Case Reference Number	TAX/07/24/2079				
Registration Date	1/11/2017				
Company Type	Strides Premier Taxi Pte Ltd				
Make	TOYOTA				
Model	PRIUS4				
Name of Driver	TEIN JUN WEI (DENG JUNWEI)				
Type of Accident	Side Swipe				
Accident Date and Time	25/7/2024 7:25 AM				
Accident Reported Date and Time	25/7/2024 9:27 AM				
Is Surveyor Required?	No				
Survey by		LKK Auto Consultants hence notify			
Vehicle is Towed Back?	No	the Repairer of the following:			
Towed Back Date and Time		To resurvey before/after spray painting			
Replacement Vehicle issued?	No	 To display damaged part(s) during resurvey 			
Job Card Number	24121929	Parts prices are subject to confirmation			
Special Instruction to ARC, if any	TP/LEFT PORTION	Third party survey is on a "Without Prejudice" basis			
Prepared Date and Time	25/7/2024 9:45 AM	No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and			
Chassis Number		is subject to final approval from Insurance Company			
Mileage					
Work Shop		Acknowledged by Repairer			
Repair Completion Date and Time		Signature:			
	Section B - Summary of Repair Estimates	Date:			

Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable \$0.00			
Total Labour Cost	\$676.00				
Total Spray Cost	\$1,038.00	\$0.00			
Total Spare Part Cost	\$3,203.70	\$0.00			
Total Other Cost	\$600.00	\$0.00			
TOTAL COST	\$5,517.70	\$0.00			
Lump Sum Total	\$5,500.00	\$0.00			
Number of Repair Days	4.0				
Prepared / Adjusted By	Boon Chew Tay				
ARC / Surveyor Sign Off Date	25/07/2024 10:01 AM	21			
Signature	2	Stee (1)			

Section C - Quotation and Accident Invoice Details Quotation Number Invoice Number **Quotation Date** Invoice Date Invoice Amount Prepared Date



SMRT Accident Vehicle Repair Estimates

SMRT Autor
60 Woodland
FAX Number
Estimator Te
Accident Reg

Date Genera

User ID

			Sect	ion D - Det	ails of Repair I	Estimates			
Part 1 - Labo	ur Works								
Job Scope				Quotation f	rom AR			Adjusted by Survey	or, if applica
TO REPAIR LH PORTION			\$676,00				250		
Total Labour				\$676.00					
Part 2 - Spray	y Painting & I	Panel Beating Rela	ated Works						
								Adjusted by Surveyor, if applie	
Job Scope			Quotation from ARC						
TO RESPRAY FRONT DOOR LH				\$378.00				200	
TO RESPRAY VIEW MIRROR				\$220.00				50	
TO RESPRAY FRONT PILLAR LH				\$220.00				X	
TO RESPRAY CENTRE PILLAR LH Total Spray Painting & Panel Beating				\$220.00 \$1,038.00				190	
			t Danais Balatad Evnan					Carrier aller and an arrange	
Part 3 - Other Costs - Accident and Accident Repair Related Expension Scope				Quotation from ARC				Adjusted by Surveyor, if applica	
O WASH AND	VACUUM			\$60.00				X	
TO CHECK WIRING AND SYSTEM FUNCTION				\$120.00				30	
TO APPLY RUST-PROOFING ON AFFECTED AREA			\$200.00				10		
	R DOOR MECH			\$120,00				50	
	SUNDRY PART	S		\$100.00				Х	
otal Other Co				\$600.00					
	Parts / Mate		Dard Marris	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor
art Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	rinai riice (\$)	Estimator Approved	Sulveyor
			STICKER LOGO (FRT	1.00	\$60,00	0.00	\$60.00	Replace / /	28
		8794047440	MIRROR ASSY, OUTER REAR VIEW , LH	1.00	\$1,454.40	25.00	\$1,090.80	Replace X	
		8794547060A1	COVER, OUTER MIRROR, LH	1.00	\$117.80	25.00	\$88.35	Replace Y	
		6700247162	PANEL SUB-ASSY, FRONT DOOR LH	1.00	\$1,407.80	25.00	\$1,055.85	Replace	00
100		6872012151	HINGE ASSY, FRONT DOOR, UPPER LH	1.00	\$105.50	25.00	\$79.13	Replace X	
11000191		6874012120	HINGE ASSY, FRONT DOOR, LOWER LH	1.00	\$120.00	25.00	\$90.00	Replace X	
		6980221010	DOOR FRONT WINDOW REGULATOR SUB- ASSY, LH	1.00	\$257.80	25.00	\$193.35	Replace ?	
		8572047140	DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR, LH	1.00	\$996.60	25.00	\$747.45	Replace χ	
K. L. Ed	100	6861047040	CHECK ASSY, FRONT DOOR	1.00	\$199.40	25.00	\$149.55	Replace X	
		6786247050	WEATHERSTRIP, FRONT DOOR LH	1.00	\$250.70	25.00	\$188.02	Replace X	
		6131247040	PILLAR, CENTER BODY, OUTER LH	1.00	\$349.50	25.00	\$262.13	Replace X R	
		6101447010	PILLAR, FRONT BODY, LH	1.00	\$378.90	25.00	\$284.17	Replace X	
Total		0.0%			\$5,698.40		\$4,288.80	1	
dded Spare	Parts / Materi	ial Usage After Su	rveyor Signed off						
art Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor
									1