



Mercedes-Benz

offer wksp  
p/p 17530.11  
945

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNR7121C

CHINA TAIPING INSURANCE (S) PTE LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 19610  
Reg No/Reg Date SNR7121C / 28/06/2024  
Date In/Mileage / /  
Chassis No W1N2437022J1197021  
Engine No 78020021470885  
Make/Model MB/EQA 250+  
Colour/Trim 029 922 HighTech Si/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
WC000668	Credit	12/08/2024/ 08:47		356 / Vincent Seah				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
<b>THIS IS NOT AN OFFICIAL TAX INVOICE</b>								
<b>ESTIMATE</b>								
Z REQUEST Customer Request								
M BPNSUN POLICY NO/ACC DATE :7240107335//23.07.2024								✓ 15.00
DRIVE IN/EXCESS :24.07.2024// TP CAR NO.: SNR729X=CHINA								✓ 380.00
DATE IN/DATE SURVEY:								
BY/AUTHORIZED ON :								
M BPNSUN SUNDRIES								
A BPILAB USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT					0.10			✓ 540.00
A BPILAB TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT								RM 960.00 X
A BPILAB REMOVE CARRIAGE ASSY FROM FRAME, IMPACT REPLACE AND ASSEMBLE WHEEL BASE & ADJUST TO VEHICLE.								12 480.00 X
A BPILAB TO REMOVE & REFIT FUEL TANK FILLER HOSE.NETT								60.00
S BPNSUB TRANSFER RIM AND BALANCING TYRE. NETT								✓ 120.00
RHR								
A BPILAB BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS SEAL								✓ 180.00
A BPILAB CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM					0.07			12 1000.00 X
A BPILAB PLACE VEHICLE ON-TO CELLETTE BENCH & CONDUCT CHASSIS ALIGNMENT. NETT								4800 ✓ 6240.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.					0.01			2400 ✓ 3200.00
A BPIRES RESPRAY ON REAR BUMPER, RHR FENDER, RIGHT REAR DR, AND ACCIDENT AFFECTED AREA								

Confirmed & accepted by

Authorized signatory and company stamp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Signature:  
Date:

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNR7121C

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 19610  
Reg No/Reg Date SNR7121C / 28/06/2024  
Date In/Mileage / 10  
Chassis No W1N2437022J1197021  
Engine No 78020021470885  
Make/Model MB/EQA 250+  
Colour/Trim 029 922 HighTech Si/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	12/08/2024/ 08:47		356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
A BPILAB REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTERY ETC FOR NECESSARY REPAIR.NETT				960.00
A BPILAB REMOVE & TRANSFER DOOR MECHANICAL & ELETRICAL INSTALL TO NEW DOOR.NETT				400.00
RHR DR				
M RIGHT REAR DOOR repair	1.00	2401.19	00.00	2401.19
M DAMPING, DRIVER'S DOOR	1.00	37.48	00.00	37.48
M RHF DOOR WEATHERSTRIP	1.00	335.72	00.00	335.72
M RHR DR BOTTOM COVER STRIP	1.00	335.75	00.00	335.75
M RH/REAR DOOR INNER SMALL COVER STRIP	1.00	86.58	00.00	86.58
M FILLISTER HD.SCREW	11.00	6.50	00.00	71.50
M BLIND RIVET WITH PAN HEAD	11.00	2.89	00.00	31.79
M RHR DR WINDOW RUN	1.00	166.74	00.00	166.74
M RIGHT REAR DISK WHEEL	1.00	818.91	00.00	818.91
M RHR FENDER	1.00	3500.48	00.00	3500.48
M RHR FENDER MOULDING	1.00	142.77	00.00	142.77
M LHR FENDER LINEAR	1.00	155.15	00.00	155.15
M RHR FENDER VENT FLAP	1.00	72.31	00.00	72.31
M TRIM, BUMPER	1.00	0.00	00.00	
M LOWER COVER,REAR BUMPER	1.00	969.33	00.00	969.33
M RHR BUMPER LATERAL SUPPORT	1.00	88.90	00.00	88.90
M RHR DR INNER SMALL COVER STRIP	1.00	238.84	00.00	238.84
M SEAM SEAL	1.00	123.74	00.00	123.74
M TWO-COMPONENT ADHESIVE- REAR FENDER	1.00	125.03	00.00	125.03
M TS TWO-COMPONENT ADHESIVE- REAR FENDER	1.00	955.13	00.00	955.13
M REAR BUMPER	1.00	1520.45	00.00	1520.45

Confirmed & accepted by

Nett 26,712.79  
9% GST on 26712.79 2404.15  
Total Payable 29,116.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg









Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNR7121C

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 19610  
Reg No/Reg Date SNR7121C / 28/06/2024  
Date In/Mileage 12/08/2024/ 2004  
Chassis No W1N2437022J1197021  
Engine No 78020021470885  
Make/Model MB/EQA 250+  
Colour/Trim 029 922 HighTech Si/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator								
WC000668	Credit	28/05/2025/ 14:17		356 / Vincent Seah								
Description of Goods / Services					Qty	Unit Price	Disc%	Amount				
Z REQUEST												
Customer Request												
M BPNSUN												
POLICY NO/ACC DATE :7240107335//23.07.2024												
DRIVE IN/EXCESS :24.07.2024// TP CAR NO.: SNR729X=CHINA												
DATE IN/DATE SURVEY:12.08.2024//12.08.2024 rasul-1kk 11:15am												
DIRECT SETTLEMENT: ALFRED TOH-CHINA TAIPING												
M BPNSUN												15.00
SUNDRIES												
A BPILAB											0.10	380.00
USING XENTRY DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT												
A BPILAB												540.00
TO INSPECT & CONDUCT WHEEL ALIGNMENT.NETT												
S BPNSUB												60.00
TRANSFER RIM AND BALANCING TYRE. RHR												
SUPPLY LABOUR FOR INSTALLATION.												
DO NO:352235												
A BPILAB												120.00
BEADS, SEAMS AND FLANGES ON REPLACEMENT BODY PANELS/ COMPONENTS SEAL												
A BPILAB												180.00
CAVITY PRESERVATION ON REPLACED OR REPAIRED BODY PANELS PERFORM												
A BPILAB												4800.00
DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.												
A BPIRES												2400.00
RESPRAY ON REAR BUMPER, RHR FENDER , RIGHT REAR DR, AND ACCIDENT AFFECTED AREA												
A BPILAB												960.00
REMOVE & INSTALL INTERIOR SEATS, CARPET, GARNISH UNHOLSTRY ETC FOR NECESSARY REPAIR.NETT												
A BPILAB												960.00
TO DISCONNECT AND LOCK HIGH-CURRENT SYSTEM												
X RIGHT REAR DISK WHEEL												
					1.00	818.91	00.00	818.91				

Confirmed & accepted by

Finalization

9 days

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg





Mercedes-Benz

Cycle & Carriage  
Industries Pte Limited  
Authorised Dealer  
Company No. 196400367W  
GST Reg No. MR-8500111-X

## ESTIMATE FOR SNR7121C

CHINA TAIPING INSURANCE (S) PTE  
LTD  
ATTN: MOTOR CLAIM DEPARTMENT  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909  
62222366

Vehicle & Document Information  
WIP No 19610  
Reg No/Reg Date SNR7121C / 28/06/2024  
Date In/Mileage 12/08/2024/ 2004  
Chassis No W1N2437022J1197021  
Engine No 78020021470885  
Make/Model MB/EQA 250+  
Colour/Trim 029 922 HighTech Si/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/05/2025/ 14:17		356 / Vincent Seah

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X RHR FENDER	1.00	3500.48	00.00	3500.48
X RHR FENDER MOULDING	1.00	142.77	00.00	142.77
X SEAM SEAL	1.00	123.74	00.00	123.74
X TWO-COMPONENT ADHESIVE- REAR FENDER	1.00	125.03	00.00	125.03
X TS TWO-COMPONENT ADHESIVE- REAR FENDER	1.00	955.13	00.00	955.13
X RHR SIDE WINDOW, FIXED	1.00	613.54	00.00	613.54
X 1-COMPONENT ADHESIVE	1.00	191.93	00.00	191.93
X TRIM STRIP	1.00	335.46	00.00	335.46
X STOP PLUG	3.00	2.83	00.00	8.49
X RIVET	10.00	3.27	00.00	32.70
X BLIND RIVET W CSK. HEAD	10.00	2.14	00.00	21.40
X RHR DR INNER SMALL COVER STRIP	1.00	245.53	00.00	245.53

Finalization

Confirmed & accepted by

Nett 17,530.11  
9% GST on 17530.11 1577.71

Authorized signatory and company stamp

Total Payable 19,107.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.  
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG

Pandan Loop Service Center  
188 Pandan Loop  
Singapore 128378  
Tel: 6777 8388  
Fax: 6779 5383  
www.mercedes-benz.com.sg