Note: This document has not been finalised. LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited From: LKK Auto Consultants Pte Ltd

10 Eunos Road 851 Ubi Ave 1 #01-25#09-04A Singapore Post CentrePaya Ubi Industrial ParkSingapore 408600Singapore 408933

Attn: Sharon Tan Chow Yen Date: 07 Oct 2024

Preliminary Advice

Insured Vehicle No : SJL1155Z

TP Vehicle No : SMJ3012P Accident Date : 11/06/2024

Make : AUDI A3 SPORTBACK Assignment Date : 12/06/2024

Date of Inspection : 13/06/2024 Est. Duration of Repair : 11

Inspection At : 24 BENOI SECTOR

REPAIRER: PREMIUM AUTOMOBILES PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	70,224.00
Revised Amount	:S\$	40,294.80
Check Items (Estimated)	:S\$	0.00
Total	:S\$	40,294.80

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :\$\$ 91,000.00 COE / PARF Rebate :\$\$ 34,837.00 Salvage Value :\$\$

Margin for Repair :S\$ 56,163.00

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly	
		let us have your authorisation.	

) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.