

(08/11/13) Wef

ASS. REC. BY:

REF: CASE-24060071

790f

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: SMJ 3012

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 67K

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 S.B 110 TFSI TRONIC c.c 199

Colour

A/C: Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

Add Fee:

☐

: Site Insp (\$

☐


: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0464/2024/EQ
DATE : 12-Jun-24
WIP : 19112

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/6/2024

YOUR INSURED VEH NO : SJL 1155 Z

ECICS LIMITED

10 EUNOS ROAD 8

#09-04A, SINGAPORE POST CENTRE

SINGAPORE 408600

Attn: Motor Claims Dept

OWNER'S NAME : MR WAN MING FENG (WEN MINGFENG)
ADDRESS : BLK 93B TELOK BLANGAH STREET 31
#14-179
SINGAPORE 102093
TELEPHONE : HP +65 96206081
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070051171-04
VEHICLE NO : **SMJ 3012 P**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 23/3/2020
ENGINE NO : CHZ C38944
CHASSIS NO : WAUZZZ8V6LA049703
MILEAGE : 71,357 KM
DATE IN : 11-Jun-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-24
PLACE OF ACCIDENT : JUNCTION OF LOWER DELTA ROAD AND ALEXANDRA ROAD



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	invoice
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$ 1,800.00	
3	TO CARRY OUT VACUUM AND REGAS FOR R134.	S/N \$ 600.00	
4	TO REMOVE AND TRANSFER LHS WING MIRROR TO FACILITATE DOOR PAINTING.	S/N \$ 450.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD LHS FRONT FENDER SUPPORT. TO REPAIR LHS A-PILLAR, LHS FRONT FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	@900 x 6.5 7 \$ 10,800.00	6300 5850
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS A-PILLAR, LHS SILL PANEL AND LHS FRONT FENDER SUPPORT.	@900 x 6.5 + 200 plus \$ 6,300.00	6050
SUBTOTAL LABOUR CHARGES		: \$ 20,230.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$	3,600.00	?
8	TO CARRY OUT COMPUTERISED WHEEL ALIGNMENT.	S/N \$	280.00	/
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	480.00	/
TOTAL LABOUR CHARGES		:	\$ 24,590.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>tom</i>	1	\$ 2,411.00	
2	FRONT BUMPER FIXING PARTS <i>X</i>	1	\$ 209.00	
3	FRONT BUMPER GUIDE SECTION - LH <i>mis</i>	1	\$ 49.00	
4	FRONT BUMPER GRILLE - CENTER <i>cm</i>	1	\$ 201.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>?</i>	1	\$ 373.00	
6	FRONT BUMPER CLOSING ELEMENT - LH <i>mis</i>	1	\$ 357.00	
7	RADIATOR GRILLE <i>cm</i>	1	\$ 1,784.00	
8	RADIATOR GRILLE CLOSING ELEMENT <i>cm</i>	1	\$ 235.00	
9	CAUTION SIGN STICKER <i>nu</i>	1	\$ 25.00	
10	AIR CONDITIONER STICKER <i>nu</i>	1	\$ 10.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH <i>cm</i>	1	\$ 236.00	
12	FRONT BUMPER REINFORCEMENT BEAM COVER <i>?</i>	1	\$ 153.00	
13	FRONT BUMPER FOAM FILLER PIECE <i>cm</i>	1	\$ 237.00	
14	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>st</i>	1	\$ 1,055.00	
15	OUTSIDE TEMPERATURE SENSOR BRACKET <i>nu</i>	1	\$ 30.00	
16	HEADLIGHT - LH <i>bru</i>	1	\$ 6,647.00	
17	HEADLIGHT POWER MODULE - LH <i>?</i>	1	\$ 904.00	
18	HEADLIGHT CONTROL UNIT <i>?</i>	1	\$ 664.00	
19	HEADLIGHT HEAT SINK - LH <i>?</i>	1	\$ 924.00	
20	LIFT CYLINDER - LH <i>cm</i>	1	\$ 170.00	
SUB TOTAL SPARE PARTS			\$ 16,674.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER HOSE ?	1	\$ 86.00	
22	BONNET bt/	1	\$ 3,418.00	
23	BONNET ATTACHMENT PARTS X	1	\$ 184.00	
24	BONNET HINGE - LH / RH ?	2	\$ 150.00	
25	BONNET SIDE SEAL COVER - LH X	1	\$ 53.00	
26	BONNET STOP BUFFER re/	1	\$ 8.00	
27	BONNET GAS FILLED STRUT X	1	\$ 123.00	
28	BONNET EDGE PROTECTION re/	1	\$ 35.00	
29	BONNET CATCH HOOK X	1	\$ 116.00	
30	BONNET STRIKER - LH / RH X	2	\$ 274.00	
31	BONNET CATCH HOOK X ? X	1	\$ 79.00	
32	BONNET LOCK WITH MICRO-SWITCH - LH / RH	2	\$ 491.00	
33	BONNET RELEASE CABLE COVER X	1	\$ 12.00	
34	BONNET BOWDEN CABLE - CENTER X	1	\$ 71.00	
35	BONNET ENGINE SOUND ABSORBER X	1	\$ 275.00	
36	FRONT PLENUM CHAMBER COVER X	1	\$ 296.00	
37	NOTICE FOR VEHICLES WITH AUXILIARY HEATER X	1	\$ 9.00	
38	FRONT FENDER - LH bue/	1	\$ 1,016.00	
39	FRONT FENDER ATTACHMENT PARTS X	1	\$ 85.00	
40	FRONT FENDER BRACKET - LH REAR bt/	1	\$ 45.00	
SUB TOTAL SPARE PARTS		:	\$ 6,826.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH CENTER <i>bf ✓</i>	1	\$	74.00
42	FRONT FENDER RIVET <i>na ✓</i>	8	\$	34.00
43	FRONT FENDER INSULATION - LH <i>?</i>	1	\$	54.00
44	FRONT FENDER CLOSING ELEMENT - LH	1	\$	42.00
45	FRONT FENDER SEAL - LH <i>?</i>	1	\$	43.00
46	FRONT FENDER BRACE <i>bf ✓</i>	1	\$	122.00
47	FRONT FENDER CLOSING ELEMENT - LH <i>?</i>	1	\$	76.00
48	FRONT WHEEL HOUSING LINER - LH <i>de ✓</i>	1	\$	204.00
49	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>X</i>	1	\$	67.00
50	A-PILLAR CONNECTING PLATE - LH INNER <i>X</i>	1	\$	261.00
51	LOCK CARRIER CLOSING ELEMENT - LH FRONT <i>?</i>	1	\$	106.00
52	LOCK CARRIER <i>cm ✓</i>	1	\$	908.00
53	RADIATOR AIR GUIDE - LH <i>cm ✓</i>	1	\$	59.00
54	RADIATOR AIR GUIDE - RH <i>X</i>	1	\$	86.00
55	RADIATOR AIR GUIDE SEAL - RH OUTER <i>X</i>	1	\$	10.00
56	RADIATOR AIR GUIDE - UPPER CENTRE <i>X</i>	1	\$	21.00
57	A/C CONDENSER WITH FLUID RESERVOIR <i>X</i>	1	\$	846.00
58	A/C CONDENSER SEAL RING <i>X</i>	1	\$	16.00
59	A/C CONDENSER SEAL RING <i>X</i>	1	\$	15.00
60	ADDITIONAL RADIATOR <i>X</i>	1	\$	987.00
SUB TOTAL SPARE PARTS		:	\$	4,031.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR BRACKET - LH / RH UPPER X	2	\$ 94.00	
62	RADIATOR BUSH - LH / RH LOWER X	2	\$ 24.00	
63	RADIATOR X	1	\$ 1,177.00	
64	READY-MIX COOLANT <i>for</i>	6	\$ 332.00	
65	RADIATOR FAN WITH FAN RING X	1	\$ 1,681.00	
66	WASH WATER RESERVOIR <i>de</i>	1	\$ 238.00	
67	FRONT WINDSCREEN WASHER SYSTEM PUMP ?	1	\$ 147.00	
68	FRONT WINDSCREEN WASHER SYSTEM PUMP SEAL ?	1	\$ 4.00	
69	FRONT WINDSCREEN WASHER SYSTEM PUMP ELBOW FITTING ?	1	\$ 16.00	
70	HORN HIGH TONE - LH <i>cm</i>	1	\$ 239.00	
71	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH X	1	\$ 335.00	
72	FRONT LOWER CONTROL ARM - LH ?	1	\$ 422.00	
73	FRONT STABILIZER ?	1	\$ 479.00	
74	FRONT WHEEL BEARING HOUSING ?	1	\$ 669.00	
75	FRONT WHEELHUB WITH BEARING ?	1	\$ 554.00	
76	FRONT GUIDE JOINT ?	1	\$ 145.00	
77	FRONT COUPLING ROD ?	1	\$ 112.00	
78	FRONT DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS - LH ?	1	\$ 1,615.00	
79	FRONT GAS SHOCK ABSORBER ?	1	\$ 301.00	
80	FRONT STEERING GEAR ?	1	\$ 6,113.00	
SUB TOTAL SPARE PARTS		:	\$ 14,697.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

S/N	PARTS DESCRIPTION	DAMAGED PARTS & PRICES			REMARKS
		QTY	S/NETT		
81	FRONT STEERING BOX REPAIR SET ?	1	\$	28.00	
82	FRONT STEERING GEAR GREASE ?	1	\$	54.00	
83	FRONT TRACK ROD ?	1	\$	110.00	
84	FRONT TIE ROD END - LH ?	1	\$	138.00	
85	FRONT ASSEMBLY CARRIER ?	1	\$	1,309.00	
86	1 SET BONDED RUBBER BUSHES ?	1	\$	127.00	
87	FRONT NUMBER PLATE <i>na</i> ✓	S/N	\$	60.00	
88	METAL FILTER POWDER X	S/N	\$	280.00	
89	ACRYLIC SEALANT X	S/N	\$	180.00	
90	STONE CHIP X	S/N	\$	180.00	
91	CAVITY WAX X	S/N	\$	140.00	
92	SUNDRIES ?		\$	800.00	
TOTAL SPARE PARTS		:	\$	45,634.00	
TOTAL LABOUR CHARGES		:	\$	24,590.00	
GRAND TOTAL		:	\$	70,224.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

: Rasul - Hg 50010068
: 13/06/24
: 11 days
: Resurvey & paint

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	790F
Vehicle Details	
Vehicle No.:	SMJ3012P
Vehicle to be Exported:	No
Intended Deregistration Date:	14 Jun 2024
Vehicle Make:	AUDI
Vehicle Model:	A3 SPORTBACK 1.0 TFSI S TRONIC (LED)
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	CHZC38944
Chassis No.:	WAUZZZ8V6LA049703
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$21,738.00
Original Registration Date:	23 Mar 2020
First Registration Date:	23 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$22,434.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2030
PARF Rebate Amount:	\$16,825.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2030
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$31,210.00
COE Rebate Amount:	\$18,012.00
Total Rebate Amount:	\$34,837.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 14 Jun 2024

OK



Audi A3 Sportback 1.0A TFSI S-tronic

\$102,999 Instalment \$1,209/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator



Overview Financial Photo Research

Depreciation

\$15,900 / year

Reg. Date

23-Mar-2020

(5yrs 9mths 8days COE left)

Manufactured

2019

Mileage

32,000 km (7.6k / year)

Transmission

Auto

Engine Cap

999 cc

Road Tax

\$392 / year

Power

85.0 kW (113 bhp)

View specs of the [Audi S3 Sportback \(2009-2013\)](#)

Curb Weight

1,275 kg

COE

\$31,210

OMV

\$21,740

ARF

\$22,436

Dereg Value

\$34,843 as of today