

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0464/2024/EQ
DATE : 12-Jun-24
WIP : 19112

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 13/6/2024

YOUR INSURED VEH NO : SJL 1155 Z

ECICS LIMITED

10 EUNOS ROAD 8

#09-04A, SINGAPORE POST CENTRE

SINGAPORE 408600

Attn: Motor Claims Dept

OWNER'S NAME : MR WAN MING FENG (WEN MINGFENG)
ADDRESS : BLK 93B TELOK BLANGAH STREET 31
#14-179
SINGAPORE 102093
TELEPHONE : HP +65 96206081
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070051171-04
VEHICLE NO : **SMJ 3012 P**
MODEL CODE : AUDI A3 SPORTSBACK 1.0 TF
MODEL YEAR : 23/3/2020
ENGINE NO : CHZ C38944
CHASSIS NO : WAUZZZ8V6LA049703
MILEAGE : 71,357 KM
DATE IN : 11-Jun-24
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 11-Jun-24
PLACE OF ACCIDENT : JUNCTION OF LOWER DELTA ROAD AND ALEXANDRA ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00	
2	TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR, CHECK ELECTRICAL FANS AND CONTROL UNIT.	S/N \$	1,800.00	
3	TO CARRY OUT VACUUM AND REGAS FOR R134.	S/N \$	600.00	
4	TO REMOVE AND TRANSFER LHS WING MIRROR TO FACILITATE DOOR PAINTING.	S/N \$	450.00	
5	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. TO CUT OUT AND WELD LHS FRONT FENDER SUPPORT. TO REPAIR LHS A-PILLAR, LHS FRONT FENDER AND LHS SILL PANEL. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	10,800.00	
6	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER, LHS FRONT DOOR, LHS A-PILLAR, LHS SILL PANEL AND LHS FRONT FENDER SUPPORT.	\$	6,300.00	
SUBTOTAL LABOUR CHARGES		:	\$ 20,230.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 3012 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO REMOVE AND REINSTALL FRONT SUSPENSION. INSPECT FOR DAMAGES AND RENEW ACCORDINGLY.	S/N \$	3,600.00	
8	TO CARRY OUT COMPUTERISED WHEEL ALIGNMENT.	S/N \$	280.00	
9	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	480.00	
TOTAL LABOUR CHARGES		:	\$ 24,590.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,411.00	
2	FRONT BUMPER FIXING PARTS	1	\$ 209.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 49.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 201.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 373.00	
6	FRONT BUMPER CLOSING ELEMENT - LH	1	\$ 357.00	
7	RADIATOR GRILLE	1	\$ 1,784.00	
8	RADIATOR GRILLE CLOSING ELEMENT	1	\$ 235.00	
9	CAUTION SIGN STICKER	1	\$ 25.00	
10	AIR CONDITIONER STICKER	1	\$ 10.00	
11	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 236.00	
12	FRONT BUMPER REINFORCEMENT BEAM COVER	1	\$ 153.00	
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 237.00	
14	FRONT BUMPER SIDE REINFORCEMENT BEAM	1	\$ 1,055.00	
15	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 30.00	
16	HEADLIGHT - LH	1	\$ 6,647.00	
17	HEADLIGHT POWER MODULE - LH	1	\$ 904.00	
18	HEADLIGHT CONTROL UNIT	1	\$ 664.00	
19	HEADLIGHT HEAT SINK - LH	1	\$ 924.00	
20	LIFT CYLINDER - LH	1	\$ 170.00	
SUB TOTAL SPARE PARTS		:	\$ 16,674.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	LIFT CYLINDER HOSE	1	\$ 86.00	
22	BONNET	1	\$ 3,418.00	
23	BONNET ATTACHMENT PARTS	1	\$ 184.00	
24	BONNET HINGE - LH / RH	2	\$ 150.00	
25	BONNET SIDE SEAL COVER - LH	1	\$ 53.00	
26	BONNET STOP BUFFER	1	\$ 8.00	
27	BONNET GAS FILLED STRUT	1	\$ 123.00	
28	BONNET EDGE PROTECTION	1	\$ 35.00	
29	BONNET CATCH HOOK	1	\$ 116.00	
30	BONNET STRIKER - LH / RH	2	\$ 274.00	
31	BONNET CATCH HOOK	1	\$ 79.00	
32	BONNET LOCK WITH MICRO-SWITCH - LH / RH	2	\$ 491.00	
33	BONNET RELEASE CABLE COVER	1	\$ 12.00	
34	BONNET BOWDEN CABLE - CENTER	1	\$ 71.00	
35	BONNET ENGINE SOUND ABSORBER	1	\$ 275.00	
36	FRONT PLENUM CHAMBER COVER	1	\$ 296.00	
37	NOTICE FOR VEHICLES WITH AUXILIARY HEATER	1	\$ 9.00	
38	FRONT FENDER - LH	1	\$ 1,016.00	
39	FRONT FENDER ATTACHMENT PARTS	1	\$ 85.00	
40	FRONT FENDER BRACKET - LH REAR	1	\$ 45.00	
SUB TOTAL SPARE PARTS		:	\$ 6,826.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT FENDER BRACKET - LH CENTER	1	\$ 74.00	
42	FRONT FENDER RIVET	8	\$ 34.00	
43	FRONT FENDER INSULATION - LH	1	\$ 54.00	
44	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 42.00	
45	FRONT FENDER SEAL - LH	1	\$ 43.00	
46	FRONT FENDER BRACE	1	\$ 122.00	
47	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 76.00	
48	FRONT WHEEL HOUSING LINER - LH	1	\$ 204.00	
49	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 67.00	
50	A-PILLAR CONNECTING PLATE - LH INNER	1	\$ 261.00	
51	LOCK CARRIER CLOSING ELEMENT - LH FRONT	1	\$ 106.00	
52	LOCK CARRIER	1	\$ 908.00	
53	RADIATOR AIR GUIDE - LH	1	\$ 59.00	
54	RADIATOR AIR GUIDE - RH	1	\$ 86.00	
55	RADIATOR AIR GUIDE SEAL - RH OUTER	1	\$ 10.00	
56	RADIATOR AIR GUIDE - UPPER CENTRE	1	\$ 21.00	
57	A/C CONDENSER WITH FLUID RESERVOIR	1	\$ 846.00	
58	A/C CONDENSER SEAL RING	1	\$ 16.00	
59	A/C CONDENSER SEAL RING	1	\$ 15.00	
60	ADDITIONAL RADIATOR	1	\$ 987.00	
SUB TOTAL SPARE PARTS		:	\$ 4,031.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	RADIATOR BRACKET - LH / RH UPPER	2	\$ 94.00	
62	RADIATOR BUSH - LH / RH LOWER	2	\$ 24.00	
63	RADIATOR	1	\$ 1,177.00	
64	READY-MIX COOLANT	6	\$ 332.00	
65	RADIATOR FAN WITH FAN RING	1	\$ 1,681.00	
66	WASH WATER RESERVOIR	1	\$ 238.00	
67	FRONT WINDSCREEN WASHER SYSTEM PUMP	1	\$ 147.00	
68	FRONT WINDSCREEN WASHER SYSTEM PUMP SEAL	1	\$ 4.00	
69	FRONT WINDSCREEN WASHER SYSTEM PUMP ELBOW FITTING	1	\$ 16.00	
70	HORN HIGH TONE - LH	1	\$ 239.00	
71	FRONT WINDOW SLOT SEAL CHROME TRIM STRIP - LH	1	\$ 335.00	
72	FRONT LOWER CONTROL ARM - LH	1	\$ 422.00	
73	FRONT STABILIZER	1	\$ 479.00	
74	FRONT WHEEL BEARING HOUSING	1	\$ 669.00	
75	FRONT WHEELHUB WITH BEARING	1	\$ 554.00	
76	FRONT GUIDE JOINT	1	\$ 145.00	
77	FRONT COUPLING ROD	1	\$ 112.00	
78	FRONT DRIVE SHAFT WITH CONSTANT VELOCITY JOINTS - LH	1	\$ 1,615.00	
79	FRONT GAS SHOCK ABSORBER	1	\$ 301.00	
80	FRONT STEERING GEAR	1	\$ 6,113.00	
SUB TOTAL SPARE PARTS		:	\$ 14,697.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 3012 P

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
81	FRONT STEERING BOX REPAIR SET	1	\$ 28.00	
82	FRONT STEERING GEAR GREASE	1	\$ 54.00	
83	FRONT TRACK ROD	1	\$ 110.00	
84	FRONT TIE ROD END - LH	1	\$ 138.00	
85	FRONT ASSEMBLY CARRIER	1	\$ 1,309.00	
86	1 SET BONDED RUBBER BUSHES	1	\$ 127.00	
87	FRONT NUMBER PLATE	S/N	\$ 60.00	
88	METAL FILTER POWDER	S/N	\$ 280.00	
89	ACRYLIC SEALANT	S/N	\$ 180.00	
90	STONE CHIP	S/N	\$ 180.00	
91	CAVITY WAX	S/N	\$ 140.00	
92	SUNDRIES		\$ 800.00	
TOTAL SPARE PARTS		:	\$ 45,634.00	
TOTAL LABOUR CHARGES		:	\$ 24,590.00	
GRAND TOTAL		:	\$ 70,224.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT