

Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

*Not With in
11 Day \$30,750/-
Running After Paint
12 days*

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER	1		BN \$1,300.00	✓
2	REAR BUMPER LOWER	1		BN CM \$380.00	✓
3	REAR BUMPER LOWER MOULDING	1		CM \$300.00	✓
4	REAR LH BUMPER REFLECTOR	1		CM \$40.00	✓
5	REAR RH BUMPER REFLECTOR	1		BN \$40.00	X
6	REAR BUMPER CENTER BRACKET	1		DIY \$120.00	✓
7	REAR BUMPER LOWER INNER BRACKET	1		BN \$140.00	✓
8	REAR BOOT OPEN CONTROL MODULE	1		ND \$280.00	✓
9	REAR LH BUMPER RETAINER	1		BN \$80.00	X
10	REAR RH BUMPER RETAINER	1		BN \$80.00	X
11	REAR LH BUMPER SIDE SUPPORT BRACKET	1		CM \$75.00	✓
12	REAR RH BUMPER SIDE SUPPORT BRACKET	1		CM \$75.00	✓
13	REAR LH BUMPER UPPER BRACKET	1		DIY \$50.00	✓
14	REAR RH BUMPER UPPER BRACKET	1		DIY \$50.00	✓
15	REAR LH EXHAUST TAIL PIPE TIP	1		ND \$340.00	✓
16	REAR RH EXHAUST TAIL PIPE TIP	1		BN \$340.00	X
17	REAR BUMPER REINFORCEMENT	1		BN \$760.00	✓
18	REAR BUMPER TOWING COVER	1		BN \$120.00	X
19	REAR LH BUMPER LOWER SIDE TRIM	1		ND \$95.00	✓
20	TAILLAMP LH	1		CM \$520.00	✓
21	TAILLAMP RH	1		CM \$520.00	✓
22	REAR BOOT	1		BN \$1,820.00	✓
23	REAR BOOT MERCEDES LOGO	1		BN \$50.00	✓
24	REAR BOOT E200 EMBLEM	1		BN \$130.00	✓
25	REAR BOOT 9G-TRONIC EMBLEM	1		BN \$120.00	✓
26	REAR BOOT OUTER CENTER CHROME MOULDING	1		CM \$180.00	✓
27	REAR BOOT OUTER CHROME MOULDING LOWER GARNISH	1		DIY \$220.00	✓
27	REAR BOOT WEATHERSTRIP	1	1055W	DIY \$210.00	502m
28	REAR BOOT LOCK	1		ND \$240.00	✓
29	REAR BOOT INNER TRIM BOARD	1		BN \$280.00	X
30	REAR BOOT LOCK INNER TOP GARNISH	1		BN \$130.00	X
31	REAR LH BOOT HINGE COVER	1		CM BN \$35.00	X
32	REAR RH BOOT HINGE COVER	1		CM BN \$35.00	X
33	REAR BOOT OUTER OPENING SWITCH	1		ND \$160.00	✓
34	REAR LICENCE PLATE LAMP	2	\$30.00	BN \$60.00	X
35	REAR LH BOOT OPENING INNER GARNISH	1		BN \$70.00	X
36	REAR RH BOOT OPENING INNER GARNISH	1		BN \$70.00	X

Head office

8 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

37	REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR	1		Tr \$375.00	2
38	REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR COVER	1		nd \$65.00	2
39	REAR BOOT FLOOR BOARD	1		nd \$450.00	✓
40	REAR LUGGAGE COMPARTMENT INNER TRAY TOP COVER	1		cm \$330.00	2
41	REAR END PANEL	1		Bu \$1,450.00	✓
42	REAR END PANEL TRIM BOARD	1		ng cm \$150.00	✓
43	REAR END FLOOR LOWER COVER	1		nd \$120.00	✓
44	FRONT BUMPER	1		Bu \$1,380.00	✓
45	FRONT BUMPER LICENCE PLATE MOULDING	1		cm \$130.00	✓
46	FRONT LH BUMPER RETAINER	1		nd \$25.00	✓
47	FRONT RH BUMPER RETAINER	1		nd \$25.00	X
48	FRONT LH BUMPER SIDE SUPPORT BRACKET	1		Bu \$100.00	2
49	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		Bu \$100.00	1
50	FRONT BUMPER LOWER MOUNT BRACKET	1		nd \$180.00	✓
51	FRONT BUMPER ENERGY ABSORBER	1		cm \$200.00	✓
52	FRONT BUMPER REINFORCEMENT	1		Bu \$480.00	✓
53	FRONT BUMPER LOWER GRILLE COVER CHROME MOULDING	1		nd \$400.00	X
54	FRONT BUMPER LOWER GRILLE COVER	1		nd \$220.00	X
55	FRONT LH BUMPER FOG LAMP GRILLE COVER	1		nd \$140.00	X
56	FRONT RH BUMPER FOG LAMP GRILLE COVER	1		nd \$140.00	X
57	FRONT RADAR SENSOR	1		nd \$1,150.00	2
58	FRONT PARKING SENSOR	5	\$150.00	\$750.00	2
59	FRONT BUMPER PEDESTRIAN PROTECTION PRESSURE SENSOR	1		shot \$180.00	2
60	RADIATOR GRILLE	1		cm \$250.00	✓
61	RADIATOR GRILLE CHROME FRAME MOULDING	1		cm \$270.00	✓
62	RADIATOR GRILLE OUTER TRIM	1		cm \$260.00	✓
63	RADIATOR GRILLE OUTER TRIM MOULDING LH	1		scr \$80.00	2
64	RADIATOR GRILLE OUTER TRIM MOULDING RH	1		scr \$80.00	2
65	RADIATOR GRILLE EMBLEM	1		cm \$140.00	✓
66	RADIATOR GRILLE EMBLEM BASE	1		cm \$100.00	✓
67	RADIATOR GRILLE INNER AIR DUCT	1		nd \$150.00	2
68	FRONT LH HEADLAMP	1		ng cm \$2,500.00	✓
69	FRONT RH HEADLAMP	1		nd \$2,500.00	✓
70	FRONT LH HEADLAMP MODULE	1		nd \$590.00	2
71	FRONT RH HEADLAMP MODULE	1		nd \$590.00	2
72	FRONT LH AIRBAG SENSOR	1		nd \$150.00	2
73	FRONT RH AIRBAG SENSOR	1		nd \$150.00	2
74	FRONT RADIATOR SUPPORT BAR WITH BRACKET	1		cm \$300.00	✓
75	FRONT LH RADIATOR SUPPORT OUTER BRACKET	1		cm \$120.00	2

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

76	FRONT RH RADIATOR SUPPORT OUTER BRACKET	1		<i>✓</i> \$120.00	<i>✓</i>
77	FRONT LH RADIATOR SUPPORT SIDE FRAME BRACKET	1		<i>✓</i> \$110.00	<i>✓</i>
78	FRONT RH RADIATOR SUPPORT SIDE FRAME BRACKET	1		<i>✓</i> \$110.00	<i>✓</i>
79	FRONT LH FENDER PANEL	1		<i>✓</i> \$780.00	<i>✓</i>
80	FRONT LH SEAT BELT	1		<i>✓</i> \$1,300.00	<i>✓</i>
81	FRONT RH SEAT BELT	1		<i>✓</i> \$1,300.00	<i>✓</i>
82	REAR LH SEAT BELT	1		<i>✓</i> \$550.00	<i>✓</i>
83	REAR RH SEAT BELT	1		<i>✓</i> \$550.00	<i>✓</i>
84	AIRBAG CONTROL MODULE	1		<i>✓</i> \$860.00	<i>✓</i>
85	FRONT RH FENDER PANEL	1		REPAIR	<i>✓</i>
86	FRONT BONNET	1		REPAIR	<i>✓</i>
87	FRONT LH DOOR PANEL	1		REPAIR	<i>✓</i>
88	REAR LH FENDER PANEL	1		REPAIR	<i>✓</i>
89	REAR RH FENDER PANEL	1		REPAIR	<i>✓</i>
90	TAILLAMP PANEL LH	1		REPAIR	<i>✓</i>
91	TAILLAMP PANEL RH	1		REPAIR	<i>✓</i>
				SUB TOTAL	\$31,965.00
				PLUS 10%	\$3,196.50
				PARTS TOTAL	\$35,161.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		<i>✓</i> \$55.00	<i>✓</i>
2	FRONT BUMPER RIVETS	1		<i>✓</i> \$50.00	<i>✓</i>
3	FRONT FENDER LINER CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
4	FRONT BUMPER LOWER COVER CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
5	FRONT LICENCE PLATE NUMBER WITH FRAME	1		<i>✓</i> \$180.00	<i>✓</i>
6	RADIATOR GRILLE CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
7	FRONT PARKING SENSOR MOUNTING BRACKET SET	1		<i>✓</i> \$450.00	<i>✓</i>
8	REAR BUMPER CLIPS	1		<i>✓</i> \$55.00	<i>✓</i>
9	REAR BUMPER LOWER COVER CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
10	REAR LICENCE PLATE NUMBER WITH FRAME	1		<i>✓</i> \$120.00	<i>✓</i>
11	REAR BOOT INNER TRIM BOARD CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
12	REAR END PANEL SEALANT	1		<i>✓</i> \$180.00	<i>✓</i>
13	TAILLAMP GUIDE CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
14	REAR REVERSE SENSOR MOUNTING BRACKET SET	1		<i>✓</i> \$450.00	<i>✓</i>
15	REAR BOOT MOULDING CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
				S/N TOTAL	\$1,890.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.	1100	\$2,000.00
LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL, REAR LH & RH FENDER, TAILLAMP PANEL LH & RH, FRONT BUMPER, FRONT LH & RH FENDER PANEL, FRONT BONNET, FRONT LH DOOR, ETC	1500	\$3,000.00
TO REMOVE AND REFIT FRONT DRIVER, PASSENGER SIDE AND REAR LUGGAGE COMPARTMENTS INNER TRIMMINGS, LININGS, COVER, GARNISH AND OTHER NEC ITEMS TO REPLACE AIRBAG PARTS AND ENABLE BODYWORK REPAIR	250	\$450.00
LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOT INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS.	60	\$150.00
LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.	60	\$100.00
LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.	60	\$100.00
TO TUFF KOTE & UNDERSEAL MATERIALS.	60	\$160.00
TO DIAGNOSIS FAULT CODE AND RESET AIRBAG AND OTHER FAULT CODE	250	\$400.00
TO CHECK WIRING & ELECTRICAL SYSTEM.	40	\$150.00
TO RECALIBRATE, READJUST AND REALIGN HEADLAMP AIM	100	\$200.00
TO RECALIBRATE, RESET AND TEST FRONT CAMERA AND FRONT RADAR SENSOR	180	\$300.00

LABOUR TOTAL \$7,010.00

TOTAL \$44,061.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

