

ASS. REC. BY:

REF:

CD/TH / 24070297/kmas

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: NII / S/Rlm / STD A/Rlm or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

2/12 11:30 AM 30,7501 Calm

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

: Prel. Report

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: : Site Insp (\$

: Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Not Withheld
11 Day \$30,750/-
Running After Paint
12 days

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$	
1	REAR BUMPER	1		BA \$1,300.00	✓
2	REAR BUMPER LOWER	1		BA / CM \$380.00	✓
3	REAR BUMPER LOWER MOULDING	1		CM \$300.00	✓
4	REAR LH BUMPER REFLECTOR	1		CM \$40.00	✓
5	REAR RH BUMPER REFLECTOR	1		R \$40.00	X
6	REAR BUMPER CENTER BRACKET	1		DIY \$120.00	✓
7	REAR BUMPER LOWER INNER BRACKET	1		R \$140.00	✓
8	REAR BOOT OPEN CONTROL MODULE	1		DIY \$280.00	✓
9	REAR LH BUMPER RETAINER	1		R \$80.00	X
10	REAR RH BUMPER RETAINER	1		R \$80.00	X
11	REAR LH BUMPER SIDE SUPPORT BRACKET	1		CM \$75.00	✓
12	REAR RH BUMPER SIDE SUPPORT BRACKET	1		CM \$75.00	✓
13	REAR LH BUMPER UPPER BRACKET	1		DIY \$50.00	✓
14	REAR RH BUMPER UPPER BRACKET	1		DIY \$50.00	✓
15	REAR LH EXHAUST TAIL PIPE TIP	1		DIY \$340.00	✓
16	REAR RH EXHAUST TAIL PIPE TIP	1		R \$340.00	X
17	REAR BUMPER REINFORCEMENT	1		R \$760.00	✓
18	REAR BUMPER TOWING COVER	1		R \$120.00	X
19	REAR LH BUMPER LOWER SIDE TRIM	1		DIY \$95.00	✓
20	TAILLAMP LH	1		CM \$520.00	✓
21	TAILLAMP RH	1		CM \$520.00	✓
22	REAR BOOT	1		R \$1,820.00	✓
23	REAR BOOT MERCEDES LOGO	1		R \$50.00	✓
24	REAR BOOT E200 EMBLEM	1		R \$130.00	✓
25	REAR BOOT 9G-TRONIC EMBLEM	1		R \$120.00	✓
26	REAR BOOT OUTER CENTER CHROME MOULDING	1		CM \$180.00	✓
27	REAR BOOT OUTER CHROME MOULDING LOWER GARNISH	1		DIY \$220.00	✓
27	REAR BOOT WEATHERSTRIP	1	✓ 1055w	DIY \$210.00	502A
28	REAR BOOT LOCK	1		DIY \$240.00	✓
29	REAR BOOT INNER TRIM BOARD	1		R \$280.00	X
30	REAR BOOT LOCK INNER TOP GARNISH	1		R \$130.00	X
31	REAR LH BOOT HINGE COVER	1		CM / R \$35.00	X
32	REAR RH BOOT HINGE COVER	1		CM / R \$35.00	X
33	REAR BOOT OUTER OPENING SWITCH	1		DIY \$160.00	✓
34	REAR LICENCE PLATE LAMP	2	\$30.00	R \$60.00	X
35	REAR LH BOOT OPENING INNER GARNISH	1		R \$70.00	X
36	REAR RH BOOT OPENING INNER GARNISH	1		R \$70.00	X

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

37	REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR	1		Th	\$375.00	✓
38	REAR BOOT CLOSING DOWN LOCK LATCH ACTUATOR COVER	1		nd	\$65.00	✓
39	REAR BOOT FLOOR BOARD	1		nd / Dis	\$450.00	✓
40	REAR LUGGAGE COMPARTMENT INNER TRAY TOP COVER	1		cm	\$330.00	✓
41	REAR END PANEL	1		Bu	\$1,450.00	✓
42	REAR END PANEL TRIM BOARD	1		ng cm	\$150.00	✓
43	REAR END FLOOR LOWER COVER	1		thir	\$120.00	✓
44	FRONT BUMPER	1		Bu	\$1,380.00	✓
45	FRONT BUMPER LICENCE PLATE MOULDING	1		cm	\$130.00	✓
46	FRONT LH BUMPER RETAINER	1		Dis	\$25.00	✓
47	FRONT RH BUMPER RETAINER	1		cm	\$25.00	X
48	FRONT LH BUMPER SIDE SUPPORT BRACKET	1		Bu	\$100.00	✓
49	FRONT RH BUMPER SIDE SUPPORT BRACKET	1		Bu	\$100.00	✓
50	FRONT BUMPER LOWER MOUNT BRACKET	1		Dis	\$180.00	✓
51	FRONT BUMPER ENERGY ABSORBER	1		cm	\$200.00	✓
52	FRONT BUMPER REINFORCEMENT	1		Bu	\$480.00	✓
53	FRONT BUMPER LOWER GRILLE COVER CHROME MOULDING	1		nd / cm	\$400.00	X
54	FRONT BUMPER LOWER GRILLE COVER	1		cm	\$220.00	X
55	FRONT LH BUMPER FOG LAMP GRILLE COVER	1		cm	\$140.00	X
56	FRONT RH BUMPER FOG LAMP GRILLE COVER	1		cm	\$140.00	X
57	FRONT RADAR SENSOR	1		nd	\$1,150.00	✓
58	FRONT PARKING SENSOR	5	Real / thom	\$150.00	\$750.00	✓
59	FRONT BUMPER PEDESTRIAN PROTECTION PRESSURE SENSOR	1		Short	\$180.00	✓
60	RADIATOR GRILLE	1		cm	\$250.00	✓
61	RADIATOR GRILLE CHROME FRAME MOULDING	1		cm	\$270.00	✓
62	RADIATOR GRILLE OUTER TRIM	1		cm	\$260.00	✓
63	RADIATOR GRILLE OUTER TRIM MOULDING LH	1		Scr	\$80.00	✓
64	RADIATOR GRILLE OUTER TRIM MOULDING RH	1		Scr	\$80.00	✓
65	RADIATOR GRILLE EMBLEM	1		cm	\$140.00	✓
66	RADIATOR GRILLE EMBLEM BASE	1		cm	\$100.00	✓
67	RADIATOR GRILLE INNER AIR DUCT	1		nd	\$150.00	✓
68	FRONT LH HEADLAMP	1		ng / cm	\$2,500.00	✓
69	FRONT RH HEADLAMP	1		cm	\$2,500.00	✓
70	FRONT LH HEADLAMP MODULE	1		nd	\$590.00	✓
71	FRONT RH HEADLAMP MODULE	1		nd	\$590.00	✓
72	FRONT LH AIRBAG SENSOR	1		cm	\$150.00	✓
73	FRONT RH AIRBAG SENSOR	1		cm	\$150.00	✓
74	FRONT RADIATOR SUPPORT BAR WITH BRACKET	1		cm	\$300.00	✓
75	FRONT LH RADIATOR SUPPORT OUTER BRACKET	1		cm	\$120.00	✓

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9819 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 23-7-2024
 Vehicle No: SNQ3185A
 Model: Mercedes Benz E200
 Chassis: WDD2130422A053846
 Reg.Year: 19.10.2016

Third Party Insurer: III
 Third Party Veh No: GBK3219K
 Date of Accident: 22/7/2024
 Estimator: Loong
 Surveyor:

76	FRONT RH RADIATOR SUPPORT OUTER BRACKET	1		<i>✓</i> \$120.00	<i>X</i>
77	FRONT LH RADIATOR SUPPORT SIDE FRAME BRACKET	1		<i>✓</i> \$110.00	<i>X</i>
78	FRONT RH RADIATOR SUPPORT SIDE FRAME BRACKET	1		<i>✓</i> \$110.00	<i>X</i>
79	FRONT LH FENDER PANEL	1		<i>✓</i> \$780.00	<i>X</i>
80	FRONT LH SEAT BELT	1		<i>✓</i> \$1,300.00	<i>✓</i>
81	FRONT RH SEAT BELT	1		<i>✓</i> \$1,300.00	<i>✓</i>
82	REAR LH SEAT BELT	1		<i>✓</i> \$550.00	<i>✓</i>
83	REAR RH SEAT BELT	1		<i>✓</i> \$550.00	<i>✓</i>
84	AIRBAG CONTROL MODULE	1		<i>✓</i> \$860.00	<i>✓</i>
85	FRONT RH FENDER PANEL	1		REPAIR	
86	FRONT BONNET	1		REPAIR	
87	FRONT LH DOOR PANEL	1		REPAIR	
88	REAR LH FENDER PANEL	1		REPAIR	
89	REAR RH FENDER PANEL	1		REPAIR	
90	TAILLAMP PANEL LH	1		REPAIR	
91	TAILLAMP PANEL RH	1		REPAIR	
				SUB TOTAL	\$31,965.00
				PLUS 10%	\$3,196.50
				PARTS TOTAL	\$35,161.50

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$	
1	FRONT BUMPER CLIPS	1		<i>✓</i> \$55.00	<i>✓</i>
2	FRONT BUMPER RIVETS	1		<i>✓</i> \$50.00	<i>✓</i>
3	FRONT FENDER LINER CLIPS	1		<i>✓</i> \$50.00	<i>X</i>
4	FRONT BUMPER LOWER COVER CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
5	FRONT LICENCE PLATE NUMBER WITH FRAME	1		<i>CM</i> \$180.00	<i>45,</i>
6	RADIATOR GRILLE CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
7	FRONT PARKING SENSOR MOUNTING BRACKET SET	1		<i>✓</i> \$450.00	<i>2</i>
8	REAR BUMPER CLIPS	1		<i>✓</i> \$55.00	<i>✓</i>
9	REAR BUMPER LOWER COVER CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
10	REAR LICENCE PLATE NUMBER WITH FRAME	1		<i>✓</i> \$120.00	<i>X</i>
11	REAR BOOT INNER TRIM BOARD CLIPS	1		<i>✓</i> \$50.00	<i>X</i>
12	REAR END PANEL SEALANT	1		<i>✓</i> \$180.00	<i>30,</i>
13	TAILLAMP GUIDE CLIPS	1		<i>✓</i> \$50.00	<i>X</i>
14	REAR REVERSE SENSOR MOUNTING BRACKET SET	1		<i>✓</i> \$450.00	<i>2</i>
15	REAR BOOT MOULDING CLIPS	1		<i>✓</i> \$50.00	<i>✓</i>
				S/N TOTAL	\$1,890.00

Date: 23-7-2024
Vehicle No: SNQ3185A
Model: Mercedes Benz E200
Chassis: WDD2130422A053846
Reg.Year: 19.10.2016

Third Party Insurer: III
Third Party Veh No: GBK3219K
Date of Accident: 22/7/2024
Estimator: Loong
Surveyor:

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST FRONT & REAR ACCIDENT AREAS & ETC.

1100/ \$2,000.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL, REAR LH & RH FENDER, TAILLAMP PANEL LH & RH, FRONT BUMPER, FRONT LH & RH FENDER PANEL, FRONT BONNET, FRONT LH DOOR, ETC

1600/ \$3,000.00

TO REMOVE AND REFIT FRONT DRIVER, PASSENGER SIDE AND REAR LUGGAGE COMPARTMENTS INNER TRIMMINGS, LININGS, COVER, GARNISH AND OTHER NEC ITEMS TO REPLACE AIRBAG PARTS AND ENABLE BODYWORK REPAIR

250/ \$450.00

LABOUR CHARGES TO REMOVE & REINSTALLED REAR BOOT INNER MECHANISM & ETC BACK TO ORIGINAL OPERATIONS.

60/ \$150.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.

60/ \$100.00

LABOUR CHARGES TO REMOVE & REPLACE FRONT BUMPER PARKING SENSOR & ETC.

60/ \$100.00

TO TUFF KOTE & UNDERSEAL MATERIALS.

60/ \$160.00

TO DIAGNOSIS FAULT CODE AND RESET AIRBAG AND OTHER FAULT CODE

250/ \$400.00

TO CHECK WIRING & ELECTRICAL SYSTEM.

40/ \$150.00

TO RECALIBRATE, READJUST AND REALIGN HEADLAMP AIM

100/ \$200.00

TO RECALIBRATE, RESET AND TEST FRONT CAMERA AND FRONT RADAR SENSOR

180/ \$300.00

LABOUR TOTAL \$7,010.00

TOTAL \$44,061.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 569047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



Date: 5-8-2024
 Vehicle No: SNQ3185A
 Model: Mercedes Benz E200
 Chassis: WDD2130422A053846
 Reg.Year: 19.10.2016

Third Party Insurer: III
 Third Party Veh No: GBK3219K
 Date of Accident: 22/7/2024
 Estimator: Loong
 Surveyor:

SUPPLEMENTARY ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR REVERSE SENSOR	5	\$180.00	\$900.00
2	REAR LH EXHAUST TAIL PIPE OUTER COVER	1		\$150.00
3	B PILLAR INNER LOWER TRIM LH	1		\$240.00
4	FRONT RH SEAT BELT HEIGHT ADJUSTER	1		\$220.00
SUB TOTAL				\$1,510.00
PLUS 10%				\$151.00
PARTS TOTAL				\$1,661.00

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
 Tel: (+65) 6484 9910 | Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Bik 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
 Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	752J
Vehicle Details	
Vehicle No.:	SNQ3185A
Vehicle to be Exported:	No
Intended Deregistration Date:	23 Jul 2024
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	E200 AMG LINE (R19 LED)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	27492030739638
Chassis No.:	WDD2130422A053846
Maximum Power Output:	135.0 kW (181 bhp)
Open Market Value:	\$54,213.00
Original Registration Date:	19 Oct 2016
First Registration Date:	19 Oct 2016
Transfer Count:	2
Actual ARF Paid:	\$69,584.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Oct 2026
PARF Rebate Amount:	\$41,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Oct 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$57,002.00
COE Rebate Amount:	\$12,737.00
Total Rebate Amount:	\$54,487.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Jul 2024

OK