



Automotive Pte Ltd

Main Office:
Motor Building
No. 22, Jalan Kuar
Singapore 153419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 10G
Bukit Merah Lane 3
#01-04/06/08/94
Singapore 151722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co Reg: 1999040333
GST Reg: M2-008664-2

SUPPLEMENTARY

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:

No	Description	Qty	U. Price	Amounts S\$
COST ITEMS:				
1	TURBO INTERCOOLER E6 <i>Lt</i>	1	PC \$ 8,500.00	\$ 8,500.00 ✓
2	RADIATOR <i>bt</i>	1	PC \$ 5,000.00	\$ 5,000.00 ✓
3	RADIATOR BRKT <i>bt</i>	2	PC \$ 280.00	\$ 560.00 ✓
4	CABIN HEAT INSULATOR <i>de</i>	1	PC \$ 300.00	\$ 300.00 ✓
5	RADIATOR FAN COWLING <i>cn</i>	1	PC \$ 700.00	\$ 700.00 ✓
6	RADIATOR FAN BLADE <i>cn</i>	1	PC \$ 650.00	\$ 650.00 ✓
7	A/C CONDENSER <i>bt</i>	2	PC \$ 600.00	\$ 1,200.00 ✓
8	RADIATOR FAN CLUTCH <i>bt</i>	1	PC \$ 1,350.00	\$ 1,350.00 ✓
9	A/C CONDENSER COWLING <i>cn</i>	1	PC \$ 350.00	\$ 350.00 ✓
10	CABIN REAR PANEL <i>bt</i>	1	PC \$ 1,800.00	\$ 1,800.00 ✓
11	STEERING SPIRAL SENSOR <i>short</i>	1	PC \$ 786.78	\$ 786.78 ✓

COST TOTAL S\$
15% COST PLUS S\$

\$ 21,196.78
\$ 3,179.52
\$ 24,376.30 ✓

LABOUR CHARGE:

1	TO REPLACE TURBO INTERCOOLER, RADIATOR FAN CLUTCH, COWLING, FAN BLADE AND CHECK FUNCTIONING	\$ 250.00 <i>200</i>
2	LABOUR TO REPLACE STEERING SPIRAL CABLE ASSY(REFER INVOICE) <i>895</i>	\$ 105.00 ✓
3	TO PERFORM INITIALIZE STEERING SPIRAL SENSOR(REFER INVOICE)	\$ 450.00 ✓
4	TO PERFORM UREA SYSTEM WARNING LIGHT CHECK AND RESET (REFER INVOICE)	\$ 140.00 ✓

TOTAL LABOUR COST S\$

\$ 945.00

AMOUNT S\$ \$ 25,321.30
GST @ 9% \$ 2,278.92
AMOUNT DUE S\$ \$ 27,600.22

Customer's Signature

MOVA AUTOMOTIVE PTE LTD