

ESTIMATE

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-008864-2

No	Description	Qty	U. Price	Amounts S\$
COST ITEMS:				
1	FRONT W/SCREEN <i>bro</i>	1	PC \$ 3,500.00	\$ 3,500.00 <i>2200.60</i>
2	W/S WEATHERSTRIP <i>neu</i>	1	PC \$ 480.00	\$ 480.00 <i>301.50</i>
3	MIRROR STAY LH <i>Xnn</i>	1	PC \$ 830.00	\$ 830.00 <i>X</i>
4	SIDE VIEW MIRROR LH <i>Xnn</i>	1	PC \$ 180.00	\$ 180.00 <i>X</i>
5	ROUND MIRROR <i>Xnn</i>	1	PC \$ 180.00	\$ 180.00 <i>X</i>
6	MIRROR STAY LH, LOWER COVER <i>Xnn</i>	1	PC \$ 45.00	\$ 45.00 <i>X</i>
7	WIPER ARM LH/RH <i>X see LH lpc</i>	<i>1/2</i>	PC \$ 250.00	\$ 500.00 <i>250</i>
8	WIPER ARM CAP LH <i>mis</i>	1	PC \$ 28.00	\$ 28.00 <i>/</i>
9	WIPER PANEL TRIM <i>cm</i>	1	PC \$ 550.00	\$ 550.00 <i>/</i>
10	WIPER PANEL HANDLE <i>sun</i>	1	PC \$ 320.00	\$ 320.00 <i>283.20</i>
11	WIPER PANEL HANDLE COVER LH/RH <i>see plus</i>	2	PC \$ 38.00	\$ 76.00 <i>/</i>
12	WIPER PANEL <i>cm</i>	1	PC \$ 850.00	\$ 850.00 <i>/</i>
13	FRONT PANEL <i>bt</i>	1	PC \$ 3,050.00	\$ 3,050.00 <i>2491.82</i>
14	FRONT PANEL HINGE LH/RH <i>?bt</i>	2	PC \$ 130.00	\$ 260.00 <i>240.20</i>
15	FRONT PANEL UPPER TRIM <i>cm</i>	1	PC \$ 750.00	\$ 750.00 <i>/</i>
16	FRONT PANEL CLIPS <i>neu</i>	20	PC \$ 4.00	\$ 80.00 <i>/</i>
17	FRONT PANEL LATCH <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>
18	HINO EMBLEM <i>neu</i>	1	PC \$ 180.00	\$ 180.00 <i>/</i>
19	500 EMBLEM <i>neu</i>	1	PC \$ 150.00	\$ 150.00 <i>88.12</i>
20	FRONT GRILLE <i>cm</i>	1	PC \$ 1,400.00	\$ 1,400.00 <i>62.06</i>
21	HINO LOGO <i>neu</i>	1	PC \$ 180.00	\$ 180.00 <i>/</i>
22	CORNER PANEL LH/RH <i>cm</i>	<i>1/2</i>	PC \$ 850.00	\$ 1,700.00 <i>850</i>
23	CORNER PANEL BRKT LH/RH <i>X see lpc X see</i>	<i>1/2</i>	PC \$ 95.00	\$ 190.00 <i>X</i>
24	DASH PANEL <i>?bt</i>	1	PC \$ 4,500.00	\$ 4,500.00 <i>2915</i>
25	BRAKE PEDAL VALVE <i>Xbro</i>	1	PC \$ 1,950.00	\$ 1,950.00 <i>/</i>
26	BRAKE PEDAL VALVE BRKT <i>cm</i>	1	PC \$ 650.00	\$ 650.00 <i>/</i>
27	BRAKE PEDAL VALVE BRKT SEAL <i>neu</i>	1	PC \$ 95.00	\$ 95.00 <i>/</i>
28	CLUTCH, FLUID RESERVOIR <i>cut</i>	1	PC \$ 190.00	\$ 190.00 <i>/</i>
29	CLUTCH PUMP <i>cm</i>	1	PC \$ 450.00	\$ 450.00 <i>/</i>
30	CLUTCH RESERVOIR, DISCHARGE PIPE <i>bro</i>	1	PC \$ 95.00	\$ 95.00 <i>/</i>
31	WASHER FLUID RESERVOIR <i>de</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>
32	WASHER MOTOR <i>Xnn</i>	1	PC \$ 130.00	\$ 130.00 <i>X</i>
33	WIPER MOTOR <i>Xnn</i>	1	PC \$ 450.00	\$ 450.00 <i>X</i>
34	WIPER LINKAGE ASSY <i>bt</i>	1	PC \$ 220.00	\$ 220.00 <i>/</i>
35	WIPER LINKAGE JOINT <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>

ESTIMATE

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
36	A/C PIPE HIGH PRESSURE (DASH PANEL) <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>90</i>
37	A/C PIPE LOW PRESSURE (DASH PANEL) <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>90</i>
38	A/C HIGH PRESSURE HOSE <i>bt</i>	1	PC \$ 250.00	\$ 250.00 <i>✓</i>
39	A/C LOW PRESSURE HOSE <i>bt</i>	1	PC \$ 280.00	\$ 280.00 <i>✓</i>
40	WIRING HARNESS COVER <i>de</i>	1	PC \$ 90.00	\$ 90.00 <i>✓</i>
41	WIRING HARNESS BASE <i>cut</i>	1	PC \$ 130.00	\$ 130.00 <i>✓</i>
42	DASH PANEL FRONT BEAM <i>bt</i>	1	PC \$ 180.00	\$ 180.00 <i>✓</i>
43	FRONT PANEL LATCH <i>X su</i>	1	PC \$ 150.00	\$ 150.00 <i>X</i>
44	CABIN BUSHING LH/RH <i>? ca</i>	2	PC \$ 280.00	\$ 560.00 <i>✓</i>
45	CABIN MTG BRKT LH/RH <i>? ca</i>	2	PC \$ 800.00	\$ 1,600.00 <i>✓</i>
46	CABIN MTG TORSION BUSH LH/RH <i>? ca X su</i>	2	PC \$ 40.00	\$ 80.00 <i>X</i>
47	CABIN MTG BRKT BOLT <i>mis</i>	8	PC \$ 45.00	\$ 360.00 <i>✓</i>
48	CABIN MTG BRKT NUT <i>mis</i>	8	PC \$ 45.00	\$ 360.00 <i>✓</i>
49	CABIN MTG BRKT WASHER <i>mis</i>	8	PC \$ 18.00	\$ 144.00 <i>✓</i>
50	CABIN JACK (CHECK)	1	PC	\$ -
51	CABIN STAND (CHECK)	1	PC	\$ -
52	FRONT BUMPER REINFORCEMENT <i>coa</i>	1	PC \$ 1,200.00	\$ 1,200.00 <i>1083.33</i>
53	FRONT BUMPER TRIM UPPER <i>coa</i>	1	PC \$ 450.00	\$ 450.00 <i>390.21</i>
54	FRONT BUMPER TRIM UPPER <i>X Lower - mis</i>	1	PC \$ 450.00	\$ 450.00 <i>390.21</i>
55	FRONT BUMPER SIDE COVER LH/RH <i>X 1pc</i>	2	PC \$ 1,050.00	\$ 2,100.00 <i>1050</i>
56	FRONT BUMPER CLIPS <i>ae</i>	10	PC \$ 5.00	\$ 50.00 <i>✓</i>
57	RADAR COVER <i>mis</i>	1	PC \$ 90.00	\$ 90.00 <i>✓</i>
58	RADAR COVER TRIM <i>mis</i>	1	PC \$ 180.00	\$ 180.00 <i>✓</i>
59	HEADLAMP LH/RH <i>X LH-ca</i>	12	PC \$ 1,580.00	\$ 3,160.00 <i>1580</i>
60	HEADLAMP BEZEL LH/RH <i>LH-ca / RH-X su</i>	12	PC \$ 1,350.00	\$ 2,700.00 <i>1350</i>
61	HEADLAMP STAY LH/RH <i>LH-7 / RH-X su</i>	2	PC \$ 720.00	\$ 1,440.00 <i>X</i>
62	FRONT BUMPER END CAP LH <i>X su</i>	1	PC \$ 95.00	\$ 95.00 <i>X</i>
63	A-PILLAR RH (REPAIR)	1	PC	\$ -
64	A-PILLAR LH <i>bt</i>	1	PC \$ 1,850.00	\$ 1,850.00 <i>1391.03</i>
65	FRONT DOOR LH <i>bt</i>	1	PC \$ 4,300.00	\$ 4,300.00 <i>4018.80</i>
66	FRONT DOOR RH (REPAIR)	1	PC	\$ -
67	EURO 6 EMBLEM <i>ae</i>	2	PC \$ 55.00	\$ 110.00 <i>✓</i>
68	B-PILLAR LH/RH (REPAIR)	2	PC	\$ -
69	LH DOOR HINGE LOWER/UPPER <i>Lower - 7bt</i>	12	PC \$ 140.00	\$ 280.00 <i>140</i>
70	DASHBOARD (CHECK)	1	PC	\$ -
71	DASHBOARD REINFORCEMENT <i>? bt</i>	1	PC \$ 950.00	\$ 950.00 <i>✓</i>
72	DASHBOARD REINF SIDE BRKT LH/RH <i>? X su</i>	2	PC \$ 150.00	\$ 300.00 <i>X</i>

bizSAFE

16/07/24

ESTIMATE

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:

18135

No	Description	Qty	U. Price	Amounts S\$
73	DASHBOARD CLIPS <i>ne</i>	10	PC \$ 4.50	\$ 45.00 ✓
74	DASHBOARD LH FUSE BOX TRIM <i>cm</i>	1	PC \$ 350.00	\$ 350.00 ✓
75	A/C BLOWER <i>? cm</i>	1	PC \$ 2,800.00	\$ 2,800.00 ✓
76	A/C HEATER <i>? cm</i>	1	PC \$ 3,300.00	\$ 3,300.00 ✓
77	FLOOR PANEL (REPAIR)	1	PC	\$ -
78	LH SIDE STEP PANEL <i>? cm</i>	1	PC \$ 680.00	\$ 680.00 ✓
79	LH SIDE STEP TRIM <i>de</i>	1	PC \$ 450.00	\$ 450.00 ✓
80	LH SIDE STEP TRIM FRONT BRKT <i>bt</i>	1	PC \$ 180.00	\$ 180.00 ✓
81	RH AIR INTAKE SNORKEL <i>? cm</i>	1	PC \$ 650.00	\$ 650.00 ✓
82	ROOF PANEL TRIM <i>de</i>	1	PC \$ 1,350.00	\$ 1,350.00 ✓
83	B-PILLAR INNER TRIM LH/RH <i>de</i>	2	PC \$ 850.00	\$ 1,700.00 ✓
84	REAR PANEL <i>bt photo</i>	1	PC \$ 2,850.00	\$ 2,850.00 ✓
85	REAR PANEL INNER TRIM <i>de</i>	1	PC \$ 1,350.00	\$ 1,350.00 ✓
86	CABIN LOCK <i>? X sv</i>	1	PC \$ 650.00	\$ 650.00 X
87	CABIN REAR MTG LH/RH <i>? X sv</i>	2	PC \$ 195.00	\$ 390.00 X
88	CABIN REAR SEMI FLOAT BRIDGE <i>bt</i>	1	PC \$ 550.00	\$ 550.00 ✓
89	CABIN REAR BRIDGE BRKT <i>bt</i>	1	PC \$ 1,250.00	\$ 1,250.00 ✓
90	CABIN LOCK HANDLE <i>photo</i>	1	PC \$ 500.00	\$ 500.00 ✓
91	CABIN LOCK HANDLE SAFETY LATCH <i>? X sv</i>	1	PC \$ 450.00	\$ 450.00 X
92	CABIN REAR GLASS WEATHERSTRIP <i>ne</i>	1	PC \$ 130.00	\$ 130.00 ✓

COST TOTAL S\$

15% COST PLUS S\$

52179.08

15% +

60005.94

\$ 68,473.00

\$ 10,270.95

\$ 78,743.95

SPECIAL NET ITEMS:

1	IU BRKT <i>ne</i>	1	PC \$ 40.00	\$ 40.00 <i>26</i>
2	RADIATOR COOLANT <i>? 1596</i>	1	PC \$ 80.00	\$ 80.00 <i>60</i>
3	A/C GAS <i>ne</i>	1	PC \$ 40.00	\$ 40.00 ✓
4	COMPOSITE SEALANT <i>ne</i>	1	PC \$ 40.00	\$ 40.00 ✓
5	RIVET <i>ne</i>	1	PC \$ 50.00	\$ 50.00 <i>30</i>
6	A/C HEATER COOLANT <i>ne</i>	1	PC \$ 80.00	\$ 80.00 <i>60</i>
7	BOX FRONT COMPOSITE BOARD UPPER <i>cm</i>	1	PC \$ 650.00	\$ 650.00 <i>500</i>
8	BOX FRONT COMPOSITE BOARD LOWER <i>cm</i>	1	PC \$ 650.00	\$ 650.00 <i>500</i>
9	BOX FRONT COMPOSITE BOARD INNER SPONGE <i>ne</i>	1	PC \$ 120.00	\$ 120.00 <i>80</i>
10	PILLAR SIDE ALUMINIUM SHEET LH/RH	2	PC \$ 180.00	\$ 360.00 <i>260</i>

bizSAFE

ESTIMATE

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-008864-2


No	Description	Qty	U. Price	Amounts S\$
COST ITEMS:				
1	FRONT W/SCREEN <i>bro</i>	1	PC \$ 3,500.00	\$ 3,500.00 <i>2200.60</i>
2	W/S WEATHERSTRIP <i>neu</i>	1	PC \$ 480.00	\$ 480.00 <i>301.50</i>
3	MIRROR STAY LH <i>Xnn</i>	1	PC \$ 830.00	\$ 830.00 <i>X</i>
4	SIDE VIEW MIRROR LH <i>Xnn</i>	1	PC \$ 180.00	\$ 180.00 <i>X</i>
5	ROUND MIRROR <i>Xnn</i>	1	PC \$ 180.00	\$ 180.00 <i>X</i>
6	MIRROR STAY LH, LOWER COVER <i>Xnn</i>	1	PC \$ 45.00	\$ 45.00 <i>X</i>
7	WIPER ARM LH/RH <i>X see / LH 1pc</i>	1 <i>2</i>	PC \$ 250.00	\$ 500.00 <i>250</i>
8	WIPER ARM CAP LH <i>mis</i>	1	PC \$ 28.00	\$ 28.00 <i>/</i>
9	WIPER PANEL TRIM <i>cm</i>	1	PC \$ 550.00	\$ 550.00 <i>/</i>
10	WIPER PANEL HANDLE <i>sun</i>	1	PC \$ 320.00	\$ 320.00 <i>283.20</i>
11	WIPER PANEL HANDLE COVER LH/RH <i>see / mis</i>	2	PC \$ 38.00	\$ 76.00 <i>/</i>
12	WIPER PANEL <i>cm</i>	1	PC \$ 850.00	\$ 850.00 <i>/</i>
13	FRONT PANEL <i>bt</i>	1	PC \$ 3,050.00	\$ 3,050.00 <i>2491.82</i>
14	FRONT PANEL HINGE LH/RH <i>?bt</i>	2	PC \$ 130.00	\$ 260.00 <i>240.20</i>
15	FRONT PANEL UPPER TRIM <i>cm</i>	1	PC \$ 750.00	\$ 750.00 <i>/</i>
16	FRONT PANEL CLIPS <i>neu</i>	20	PC \$ 4.00	\$ 80.00 <i>/</i>
17	FRONT PANEL LATCH <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>
18	HINO EMBLEM <i>neu</i>	1	PC \$ 180.00	\$ 180.00 <i>/</i>
19	500 EMBLEM <i>neu</i>	1	PC \$ 150.00	\$ 150.00 <i>88.12</i>
20	FRONT GRILLE <i>cm</i>	1	PC \$ 1,400.00	\$ 1,400.00 <i>62.06</i>
21	HINO LOGO <i>neu</i>	1	PC \$ 180.00	\$ 180.00 <i>/</i>
22	CORNER PANEL LH/RH <i>cm</i>	1 <i>2</i>	PC \$ 850.00	\$ 1,700.00 <i>850</i>
23	CORNER PANEL BRKT LH/RH <i>X see / pc X see</i>	1 <i>2</i>	PC \$ 95.00	\$ 190.00 <i>X</i>
24	DASH PANEL <i>?bt</i>	1	PC \$ 4,500.00	\$ 4,500.00 <i>2915</i>
25	BRAKE PEDAL VALVE <i>Xbro</i>	1	PC \$ 1,950.00	\$ 1,950.00 <i>/</i>
26	BRAKE PEDAL VALVE BRKT <i>cm</i>	1	PC \$ 650.00	\$ 650.00 <i>/</i>
27	BRAKE PEDAL VALVE BRKT SEAL <i>neu</i>	1	PC \$ 95.00	\$ 95.00 <i>/</i>
28	CLUTCH, FLUID RESERVOIR <i>cut</i>	1	PC \$ 190.00	\$ 190.00 <i>/</i>
29	CLUTCH PUMP <i>cm</i>	1	PC \$ 450.00	\$ 450.00 <i>/</i>
30	CLUTCH RESERVOIR, DISCHARGE PIPE <i>bro</i>	1	PC \$ 95.00	\$ 95.00 <i>/</i>
31	WASHER FLUID RESERVOIR <i>de</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>
32	WASHER MOTOR <i>Xnn</i>	1	PC \$ 130.00	\$ 130.00 <i>X</i>
33	WIPER MOTOR <i>Xnn</i>	1	PC \$ 450.00	\$ 450.00 <i>X</i>
34	WIPER LINKAGE ASSY <i>bt</i>	1	PC \$ 220.00	\$ 220.00 <i>/</i>
35	WIPER LINKAGE JOINT <i>bt</i>	1	PC \$ 150.00	\$ 150.00 <i>/</i>

ESTIMATE

24/7/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Page: 1
Vehicle No: YQ7434A
Vehicle Model: HINO 500
Est No: CBMQ24070090
Claims ref:
Accident Date: 05/07/24
In Charge: BRIAN
Remarks:



Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
	TOTAL LABOUR COST S\$			\$ 6,770.00

AMOUNT S\$ \$ 87,623.95
GST @ 9% \$ 7,886.16
AMOUNT DUE S\$ \$ 95,510.11

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

60005.94
1596.00
56901.00
24376.30
895.00
92563.24
20%
74050.59
\$74,050.59 / 16 days
16 days
L/S
25/07/24
EXCESS: 700
Resurvey after repair
nil leakage photo