

ASS. REC. BY:

REF:

09/ AG 224070399/Kap3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

08 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SCN 8187B

Yr Regn:

05, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Vezel

c.c

1498

Colour

M. Pika Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

108180

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

RUI

1203826

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

6

mm

L/Bal.

7

mm

L/Bal.

6

mm

D.O.A.

23/7/24

D.O.I.

25/7/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 GIA & En not ready

7/8 11 Sep @ 4600h Colur CPed #10795.80, 70%

Date/Time, File Pass to?

☐

Prell. Report

1) 08/8/2024

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.A. (\$

4600

Repair Estimate

Not Authorized
 11 Sep @ 4600h
 Running After Poring
 5 days

Thiam Heng Huat Pte Ltd

176 Sin Ming Drive #05-14 Sin Ming Autocare Singapore 575721

Mobile: (65) 8263 6295 Email: thiamhenghuat@gmail.com

Make/Model: HONDA VEZEL

Engine/Chassis No.:


Date of accident:

Damaged area: Rear

Date: 31/07/2024

Claim Type: TP

VRN: SLN 8187B



List items					
S/N	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Tailgate 1100-60	1	\$ 1,950.00	\$ 1,950.00	✓
2	Tailgate outer garnish	1	\$ 385.00	\$ 385.00	X
3	Tailgate logo	1	\$ 62.00	\$ 62.00	X
4	Tailgate "Vezel" emblem	1	\$ 57.00	\$ 57.00	✓
5	Tailgate lamp 0305 NISGM OLS	2	\$ 590.00	\$ 1,180.00	X
6	Tailgate buzzer 85.20	1	\$ 269.00	\$ 269.00	✓
7	Tailgate inner handle	1	\$ 84.00	\$ 84.00	X
8	Tailgate inner lock 182-50	1	\$ 285.00	\$ 285.00	✓
9	Tailgate lock sensor 6040	1	\$ 320.00	\$ 320.00	✓
10	Tailgate striker	1	\$ 85.00	\$ 85.00	X
11	Tailgate trimboard 285-60	1	\$ 745.00	\$ 745.00	✓
12	Tailgate weatherstrip 115-30	1	\$ 185.00	\$ 185.00	506m
13	Tailgate windscreen moulding	1	\$ 194.00	\$ 194.00	✓
14	Taillamp 0474-60 NIS GM OLS	2	\$ 689.00	\$ 1,378.00	✓
15	Rear bumper 762-60	1	\$ 1,150.00	\$ 1,150.00	✓
16	Rear bumper retainer	2	\$ 76.00	\$ 152.00	X
17	Rear bumper bracket	2	\$ 68.00	\$ 136.00	X
18	Rear bumper side cover	2	\$ 287.00	\$ 574.00	X
19	Rear bumper side reflector	2	\$ 177.00	\$ 354.00	X
20	Rear bumper cover retainer	2	\$ 52.00	\$ 104.00	X
21	Rear bumper centre lower diffuser	1	\$ 894.00	\$ 894.00	200m
22	Rear bumper lower side cowl	2	\$ 198.00	\$ 396.00	X
23	End panel outer 517-20	1	\$ 685.00	\$ 685.00	✓
24	End panel inner	1	\$ 496.00	\$ 496.00	X
25	Rear fender inner trim	2	\$ 476.00	\$ 952.00	X
26	Rear licence plate lamp	2	\$ 68.00	\$ 136.00	X
27	Tailgate hinge	2	\$ 135.00	\$ 270.00	X
28	Tailgate damper	2	\$ 177.00	\$ 354.00	X
29	End panel top garnish 14630	1	\$ 284.00	\$ 284.00	✓
Subtotal				\$ 14,116.00	
List discount				20.00%	
Total				\$ 11,292.80	

Special nett items

No.	Parts description	QTY	UNIT PRICE	AMOUNT	
1	Rear bumper lower diffuser clips	0	\$ 5.50	\$ 44.00	✓

Repair Estimate

2	Rear bumper lower side cowlings clips	nn 12	\$ 5.50	\$ 66.00	X
3	Tailgate outer garnish clips	nn 6	\$ 5.50	\$ 33.00	X
4	Tailgate lamp clips	nn 6	\$ 5.50	\$ 33.00	X
5	Tailgate trimboard clips	nn 10	\$ 5.50	\$ 55.00	✓
6	Taillamp clips	nn 6	\$ 5.50	\$ 33.00	X
7	End panel top garnish clips	nn 6	\$ 5.50	\$ 33.00	X
8	End panel sealant	nn 1	\$ 100.00	\$ 100.00	301n
9	Rear licence plate & frame	nn 1	\$ 55.00	\$ 55.00	X
10	Reverse sensor	nn 1	\$ 280.00	\$ 280.00	2005n -
11	Tailgate windscreen inner seal	nn 1	\$ 100.00	\$ 100.00	301n -
12	Tailgate windscreen sealant	nn 1	\$ 100.00	\$ 100.00	401n
13	Rear bumper clips	nn 10	\$ 5.50	\$ 55.00	✓
14	Rear bumper side cover clips	nn 12	\$ 5.50	\$ 66.00	X
15	Sundries	nn 1	\$ 50.00	\$ 50.00	X
			Total	\$ 1,103.00	

Labour				
No.	Description	Work unit	Amount	
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	7	\$	1,400.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$	50.00
3	To remove, refit tailgate components to replace tailgate, check and re-adjust close gap, alignment and water seepage.	0.5	\$	100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$	1,200.00
5	To remove and refit rear windscreen to facilitate repair work.	0.75	\$	150.00
6	To rust proof all affected portions after repair.	0.5	\$	100.00
Total labour			\$	3,000.00

Estimate Grand Total	\$	15,395.80
-----------------------------	-----------	------------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: