

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internationa	ıle Des Experts En	Automobile
MS	AUTO & GENERAL	INSURANCE (S) PL	Ref:	CS/AGI24070400/Kqp3m4
	(BUDGET DIRECT 190 CLEMENCEAU	INSURANCE)	Date:	16/08/2024
		PPING CENTRE SINGAPORE 239924	Code:	AGI
1.		Policy Particulars :- 1	THIRD PARTY CLA	IM
	Insured Veh.	SLM 6699J	Veh. Inspected	SHD 5185B
	Policy No.	P11033210R00	Coverage	0
	Claim No.	C10030709/JK	Excess	\$0.00
	Assign From	MICHAEL	Assign Date	25/07/2024
2. Vehicle Details				
	Make & Model	TOYOTA PRIUS 5DR HATCHBACK (AUTO)	C.C	1798
	Engine No.	2ZR2B71780	Year of Reg.	01/11/2018
	Chassis No.	JTDKB3FU003076525	Colour	METALLIC PEARL WHITE / RED
	Odometer	434858 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: STANDARD ALLOY RIM		
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	195/65R15	SAILUN	9
	L/H Front Tyre	195/65R15	SAILUN	9
	R/H Rear Tyre	195/65R15	WANLI	8
	L/H Rear Tyre	195/65R15	WANLI	8
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
ΑN	AGES SEE DETAIL	S.		
5.	General Information			
	Accident Date	23/07/2024	Inspection Date	25/07/2024
	Survey held at TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.		Estimate Day	ys of Repair	

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days