

Not Withheld
C1 Rmp @ 1700p

AAD2407-093

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5185B

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

25 JUL 2024

SHD5185B

JTDKB3FU003076525

200303878K

TOYOTA

PRIUS

23/7/2024

SLM6699J/ Auto General

1/11/2018

	PART
1	COVER, REAR BUMPER
1	COVER, REAR BUMPER, LOWER
1	GUARD, REAR BUMPER, CENTER
1	REINFORCEMENT SUB-ASSY, REAR BUMPER
1	RETAINER, REAR BUMPER RH
1	FILLER, REAR BUMPER EXTENSION, RH
1	COVER, FLOOR UNDER, LH
1	COVER, FLOOR UNDER, NO.2 (RH)
1	COVER, REAR FLOOR
1	GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
1	PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
1	PLATE, BACK DOOR NAME, NO.1
1	ORNAMENT SUB-ASSY, BACK DOOR
1	COVER, BACK DOOR TRIM
1	PANEL SUB-ASSY, BODY LOWER BACK
1	COVER, REAR COMBINATION LAMP, RH
1	LENS AND BODY, REAR LAMP, RH (LOWER)
1	LENS & BODY, REAR COMBINATION LAMP, RH (UPPER)
1	PANEL SUB-ASSY, QUARTER, RH
1	LINER, REAR WHEEL HOUSE, RH

	LIST	
\$	Buckin	558.39 ✓
\$	Redlin	19.43 ✓
\$	CM	726.92 ✓
\$	R	419.90 X
\$	Sn	148.58 X
\$	Sn	155.72 X
\$	Sn	304.92 X
\$	Sn	220.50 X
\$	Sn	290.43 X
\$	Sn	1,171.38 X
\$	Me	68.88 —
\$	Me	68.88 —
\$	Me	90.30 —
\$	Sn	31.50 X
\$	Sn	824.46 X
\$	Sn	81.48 X
\$	Sn	634.73 X
\$	Sn	570.15 X
\$	R	1,099.46 X
\$	Sn	176.09 X
TOTAL	\$	7,662.07
25%	\$	1,915.52
	\$	5,746.55

Special Nett

- 1SET PARKING AID
1 REAR BUMPER CLIP

\$ Red 700.00 220Sn
\$ Me 65.00 60Sn

AAD2407-093

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5185B

- 1 FENDER LINER CLIP
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 1 END PANEL INNER TRIM CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	nn	65.00	X
\$	nn	100.00	30% X
\$	nn	100.00	30% X
\$	nn	60.00	X
\$	nn	150.00	X
\$	nn	200.00	X
\$	nn	130.00	X
TOTAL	\$	870.00	

TOTAL PARTS \$ 8,543.40

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	nn	250.00	X
Putty And Spray Painting Of The Affected Portion.	\$		2,800.00	40% X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	X
To Check Electrical Lighting Concerned.	\$		170.00	15% X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	20% X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To transfer of rear fender panel fittings, attachment and perform water seepage test.	\$	nn	170.00	X
TOTAL	\$		10,160.00	

Over All Total \$ 24,449.95

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Non-legal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

acknowledged by
Signature:

(PART-BY-PART) Repair Days

07 Days
2 days