

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

SQ TRANSPORT SERVICES
406 TAMPINES STREET 41 #10-15 SUN PLAZA
GREEN
SINGAPORE 520406

Contact : 86880232 97208266

TP INC
Veron.

TAX INVOICE

Repair Code : CLM18316

Date in : 22/07/2024

Vehicle Num. : PC7649C

Model : TOYOTA HIACE HIGH ROOF COMMUTER TURBO AUTO

Chassis/Eng# : JTFST22P000038180/1KD2828252

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Ris</i>	1	1180.00	+ 1,180.00
FRONT BUMPER <i>Dehd</i>	1	769.00	- 769.00
FRONT BUMPER FOGLAMP GARNISH LH <i>Dehd</i>	1	106.00	+ 106.00
FRONT BUMPER SIDE RETAINER L/R <i>lit out d</i>	2	151.80	151.80 303.60
FRONT LH CORNER PANEL <i>Dehd</i>	1	284.00	✓ 284.00
FRONT LH DOOR <i>Ris</i>	1	2245.00	+ 2,245.00
FRONT LH DOOR SIDE MIRROR <i>ut</i>	1	980.00	<i>750</i> 980.00
FRONT LH HEADLAMP <i>ut</i>	1	805.00	✓ 805.00
FRONT LH STEP GARNISH <i>the w</i>	1	220.10	+ 220.10
Subtotal before discount			6,892.70
Percentage discount 25%			1,723.18
Sub-total 1			5,169.53
FRONT BUMPER CLIPS - SET <i>New</i>	1	80.00	<i>30</i> 80.00
FRONT LH HEADLAMP CLIPS - SET <i>New</i>	1	25.00	+ 25.00
Subtotal before discount			105.00
Percentage discount 0%			0.00
Sub-total 2			105.00
Parts-total			5,274.53

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

SQ TRANSPORT SERVICES
 406 TAMPINES STREET 41 #10-15 SUN PLAZA
 GREEN
 SINGAPORE 520406

Contact : 86880232 97208266

TAX INVOICE

Repair Code : CLM18316

Date in : 22/07/2024

Vehicle Num. : PC7649C

Model : TOYOTA HIACE HIGH ROOF COMMUTER TURBO AUTO

Chassis/Eng# : JTFST22P000038180/1KD2828252

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

30 80.00

700 1,200.00

300 700.00

30 120.00

2,100.00

7,374.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date

*** This is a computer-generated document which requires no signature.***

page 2

Admin
 H/S 25/09/24

04 Days.

Total: 3159.85

L/S: 2.5K ✓