

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/MSG24070405/KNP3E2**Date:** 02/09/2024REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003274641		
<b>Claimant Vehicle No :</b>	SMW5773U	<b>Insured Vehicle No :</b>	GBM1331X		
Date of Loss:	13/07/2024	Nature of Claim:	TP	Claim No:	368112

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMW5773U</b>		
Make & Model:	MERCEDES-BENZ GLA200, 1.3 SUV PROGRESSIVE (A)	Engine No:	28291480389869
Reg. Date:	27/11/2020 (Man. Year: 2020)	Chassis No:	W1N2477872J134779
Colour:	Metallic Grey	Odometer:	47487 km
Engine Capacity:	1332 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	Pirelli 4 mm	Rear Left Side:	Pirelli 7 mm
Front Right Side:	Pirelli 4 mm	Rear Right Side:	Pirelli 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,332.70	3,176.70	156.00	4.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,910.00	500.00	1,410.00	73.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>5,242.70</b>	<b>3,676.70</b>	<b>1,566.00</b>	<b>29.87</b>
<b>+ GST 9.00/9.00% (\$\$)</b>	<b>471.84</b>	<b>330.90</b>	<b>140.94</b>	<b>29.87</b>
<b>Nett Amount (\$\$)</b>	<b>5,714.54</b>	<b>4,007.60</b>	<b>1,706.94</b>	<b>29.87</b>

INSPECTION

Date of Assignment:	26/07/2024		
Date Inspected:	25/07/2024	Inspected At:	Tong Luck Auto Pte Ltd (HQ) 160 Sin Ming Drive, #07-01 Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	2.0 days		

**Adjuster:** KENNETH KONG**Manager:** HUEY YON*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Aug 2024)
Parts:	M1-SUV	MERCEDES-BENZ GLA200 1.3 SUV PROGRESSIVE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMW5773U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR - LH	Bent	2,565.00 FN	*2,565.00 FN
2	20		*REAR DOOR TRIMBOARD RIVET - LH	Necessary	216.00 FS	*60.00 FS
3	1		*REAR DOOR WEATHERSTRIP - LH	Necessary	386.00 FN	*386.00 FN
4	1		*REAR DOOR PROTECTOR - LH	Cut	256.00 FN	*256.00 FN
5	1		*REAR DOOR ARCH GARNISH - LH	Cut	256.00 FN	*256.00 FN
						F=Franchise part. S=SpcNett. N=NettItemDisc.
					Sub Total (\$\$)	3,679.00 3,523.00
					- Nett Item Discount on N Items 10.00/10.00% (\$\$)	346.30 346.30
					Total Parts (\$\$)	3,332.70 3,176.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE & REFIT LH REAR DAMAGED DOOR INTERIOR MECHANISM & GLASS TO NEW DOOR	New	150.00	60.00
2	TO CHECK AND RECTIFY WIRING SYSTEM	New	80.00	20.00
3	TO PANEL BEAT & STRAIGHTEN LH REAR DOOR HINGES, LH REAR FENDER, INCLUDING REPLACEMENT OF PARTS & ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	800.00	200.00
4	TO PUTTY & SPRAY PAINT ON AFFECTED AREAS	New	800.00	220.00
5	TO APPLY RUST-PROOFING ON REPLACED AND REPAIRED PANELS	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>1,910.00</b>	<b>500.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >