

ASS. REC. BY:

REF:

MSG/ CS/MSG24070405/Knp3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s

of

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$153k

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 02 days

Res.: Yes or No

Lum Sum: 1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SNW 57734Yr Regn: 11, 20

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M. GLA 200

c.c

1332Colour: M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading: 47487

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WIN247-7872-J134779

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 235/55R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mmR/Bal. 7 mmL/Bal. 4 mmL/Bal. 7 mmD.O.A. 13/7/24D.O.I. 25/7/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Rear body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

29/8 @ 3676.70 Calm (Red. \$1566, 29%)

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation

S + RS. \$

Fees

Others

Add Fee: ☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

TOTAL

Report Format :

Lump Sum / I.B.I. (\$



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1

1 GATEWAY DRIVE #15-08

WESTGATE TOWER

SINGAPORE 608531

TEL :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBM1331X

CLAIM TYPE : THIRD PARTY

TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD

ACCIDENT DATE : 13/07/2024

TP VEH REG NO : GBM1331X

ESTIMATE

NO : QUOT202407-000057(00)

DATE : 24/07/2024

POLICY NO : SP2003907937

VEH REG NO : SMW5773U

MAKE/MODEL : MERCEDES BENZ GLA200
SUV PROGRESSIVE

CHASSIS NO : W1N2477872J134779

ENGINE NO : 28291480389869

REG. DATE : 2020

FAX : *Not Authorised*

2 days

3676-70

Estimate Repair Cost to Vehicle No : SMW5773U

Description	Quantity	Unit Price	Amount
		S\$	S\$
NET PRICE			
1 Rear door - LH	1	2,565.00	2,565.00
2 Rear door trimboard rivet - LH	20	12.00	240.00
3 Rear door weatherstrip - LH	1	386.00	386.00
4 Rear door protector - LH	1	256.00	256.00
5 Rear door arch garnish - LH	1	256.00	256.00
			3,703.00
		Less 10%	370.30
			3,332.70
LABOUR			
6 To remove & refit LH rear damaged door interior mechanism & glass to new door	1	150.00	150.00
7 To check and rectify wiring system	1	80.00	80.00
8 To panel beat & straighten LH rear door hinges, LH rear fender, including replacement of parts & align where necessary, to refit and adjust the same	1	800.00	800.00
9 To putty & spray paint on affected areas	1	800.00	800.00
10 To apply rust-proofing on replaced and repaired panels	1	80.00	80.00
			1,910.00
		TOTAL	S\$ 5,242.70
		ADD GST @ 9.00%	471.84
		GRAND TOTAL	S\$ 5,714.54

SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED FOURTEEN AND CENTS FIFTY-FOUR ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE