



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : MERCEDES-BENZ FLEET MANAGEMENT SINGAPORE P1
1 GATEWAY DRIVE #15-08
WESTGATE TOWER
SINGAPORE 608531

TEL :
ATTN : ACCOUNTS DEPT

YOUR REF NO : GBM1331X
CLAIM TYPE : THIRD PARTY
TP INS. CO. : MSIG INSURANCE (SINGAPORE) PTE LTD
ACCIDENT DATE : 13/07/2024
TP VEH REG NO : GBM1331X

Not Authorised
Accy B4 pain

2 day

Q 3676-70

ESTIMATE

NO : QUOT202407-000057(00)
DATE : 24/07/2024
POLICY NO : SP2003907937
VEH REG NO : SMW5773U
MAKE/MODEL : MERCEDES BENZ GLA200
SUV PROGRESSIVE
CHASSIS NO : W1N2477872J134779
ENGINE NO : 28291480389869
REG. DATE : 2020

Estimate Repair Cost to Vehicle No : SMW5773U

Description	Quantity	Unit Price S\$	Amount S\$
NET PRICE			
1 Rear door - LH	1	2,565.00	2,565.00
2 Rear door trimboard rivet - LH	20	12.00	240.00
3 Rear door weatherstrip - LH	1	386.00	386.00
4 Rear door protector - LH	1	256.00	256.00
5 Rear door arch garnish - LH	1	256.00	256.00
			3,703.00
		Less 10%	370.30
			3,332.70
LABOUR			
6 To remove & refit LH rear damaged door interior mechanism & glass to new door	1	150.00	150.00
7 To check and rectify wiring system	1	80.00	80.00
8 To panel beat & straighten LH rear door hinges, LH rear fender, including replacement of parts & align where necessary, to refit and adjust the same	1	800.00	800.00
9 To putty & spray paint on affected areas	1	80.00	80.00
10 To apply rust-proofing on replaced and repaired panels			1,910.00
			1,910.00
		TOTAL	S\$ 5,242.70
		ADD GST @ 9.00%	471.84
		GRAND TOTAL	S\$ 5,714.54

SINGAPORE DOLLAR FIVE THOUSAND SEVEN HUNDRED FOURTEEN AND CENTS FIFTY-FOUR ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE