

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0262/24
DATE : 23-JUL-2024

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD
3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
S(079909)
TEL : 63896111
FAX : 62247175

OWNER'S NAME : TAN KOON SAN
ADDRESS : BLK 301C ANCHORVALE DRIVE
#11-45
S(543301)
TELEPHONE NO :

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 7240115637
VEHICLE NO : SNR8941X
MODEL CODE : FDWARF9E13HDAY746Y
MODEL/YEAR : NISSAN NOTE 1.2L E-POWER PREMIUM (IV) 2023
ENGINE NO : HR12041752M
CHASSIS NO : JN1FAAE13Z0950157
MILEAGE : 427 KM
DATE IN : 23/07/2024
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 23/07/2024

not Attributed
nu
more
PIP S
4 days.
take photo. Bedu 24
26/7/24

- 9645 0084

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) for resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SNR8941X

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL AND TRUNKFLR RENEW RR BUMPER AND TAIL GATE 430	2580.00	645
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME 350	1400.00	700
3	ZZ/003	TO APPLY CERAMIC COATING ON THE AFFECTED AREA	240.00	✓
4	ZZ/006	REMOVE AND INSTALL BOTH RR COMB LAMP AND CHECK LIGHT SYSTEM	80.00	✓
5	ZZ/007	PERFORM RUST PROOFING ON THE AFFECTED AREA	120.00	✓
6	ZZ/008	REMOVE AND INSTALL REVERSE CAMERA	120.00	✓
7	ZZ/009	REMOVE AND INSTALL REVERSE SENSOR AND CHECK RENEW INNER BRACKET REVERSE SENSOR	110.00	✗
8	ZZ/011	SUPPLY RR LICENSE PLATE		
9	ZZ/012	COMPUTER CHECK DIAGNOSIS	120.00	?
10	ZZ/013	REMOVE AND INSTALL REAR WINDSCREEN GLASS	280.00	✓
11	ZZ/10	REMOVE AND INSTALL BOTH RR FENDER INNER TRIM TO FACILITATE RR END PANEL REPAIR	240.00	✗
TOTAL LABOUR CHARGES			5290.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SNR8941X

DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST S/NETT REMAR
1	ORNAMENT-BACK DOOR NOTE	90892-6XJ0A	1er 88.80	✓
2	LABEL-BACK DOOR E POWER	90893-6XJ0A	1er 36.40	✓
3	EMBLEM-BACK DOOR NISSAN	90890-6XJ0A	155.80	?
4	3EAR LICENCE PLATE	RLP		60.00 ?
5	STRIKER-TAIL GATE	90570-6RA0A	m 38.70	X
6	HATCHBACK DOOR LOCK	90503-0754R	8u 192.60	X
7	CENTER FINISHER OUTER HATCHBACK DOOR	90810-6XJ0A	17 416.00	X
8	WEATHER STRIP HATCHBACK DOOR	90830-6XJ0B	17 106.30	X
9	HATCHBACK DOOR	K010M-6XJMA	22 1352.80	✓
10	CLIP RR BUMPER @ SGD\$1.50 EACH	01553-10501	17 15.00	X
11	STAY-RR BUMPER @ SGD\$108.00 EACH	H5212-1HMMA	216.00	?
12	RH SIDE BRACKET RR BUMPER	85220-6XJ0A	17 19.80	X
13	LH SIDE BRACKET RR BUMPER	85221-6XJ0A	17 19.80	X
14	TOW HOOK COVER RR BUMPER	85071-6XV0H	17 31.40	X
15	REAR BUMPER	85022-6XJ5A	2 579.90	X
16	SUNDRIES	NPN		50.00 ?
17	REAR W/SCREEN SEALANT	SEALANT - 4		1er 80.00 ✓
SUB TOTAL			3269.30	0.00 190.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			653.86	0.00 0.00
GRAND TOTAL			2615.44	0.00 190.00
OVERALL TOTAL			2805.44	

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SNR8941X

TOTAL LABOUR CHARGES 5290.00
TOTAL SPARE PARTS CHARGES 2805.44

GRAND TOTAL 8095.44 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.