Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: **ECICS Limited** From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25

10 Eunos Road 8

#09-04A Singapore Post Centre Paya Ubi Industrial Park Singapore 408600 Singapore 408933

Attn: Date: 01 Aug 2024

Preliminary Advice

Insured Vehicle No : SNR2929Y

TP Vehicle No : SLT5933C Accident Date : 25/07/2024 Make : AUDI A4 **Assignment Date** : 26/07/2024

Date of Inspection : 26/07/2024 Est. Duration of Repair : 5

Inspection At : TWINCAR AUTOMOTIVE PTE LTD (KAKI BUKIT)

BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB

SINGAPORE 417921

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,687.50
Revised Amount	:S\$	6,049.60
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,049.60

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us
		have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

Other comments: Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.