

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSHORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TRECICS.
Hui Rong
TAX INVOICE

Repair Code : CLM16370
Date in : 25/07/2024
Vehicle Num. : SLT5933C
Model : AUDI A4 1.4 TFSI S TRONIC
Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>don</i>	1	1790.00	✓ 1,790.00
REAR BUMPER SIDE RETAINER L/R <i>Ken</i>	2	198.00	+ 396.00
REAR LH CONTROL ARM (1) <i>Bent</i>	1	405.00	✓ 405.00
REAR LH CONTROL ARM (2) <i>Ken</i>	1	405.00	+ 405.00
REAR LH FENDER <i>Rep's</i>	1	1800.00	+ 1,800.00
REAR LH KNUCKLE ARM <i>Rep's</i>	1	869.00	✓ 869.00
REAR LH KNUCKLE ARM BEARING <i>Rep's</i>	1	765.00	✓ 765.00
REAR LH LOWER ARM <i>Bent</i>	1	515.00	✓ 515.00
REAR LH SHOCK ABSORBER <i>Ken</i>	1	405.00	+ 405.00
REAR LH UPPER ARM <i>Bent Ken</i>	1	425.00	+ 425.00
Subtotal before discount			7,775.00
Percentage discount 10%			777.50
Sub-total 1			6,997.50
REAR BUMPER CLIPS - SET <i>M</i>	1	80.00	<i>30</i> 80.00
REAR LH SPORT RIM <i>At</i>	1	1080.00	<i>80</i> 1,080.00
REAR LH TYRE (225/45ZR18) <i>At</i>	1	600.00	<i>250</i> 600.00

*** This is a computer-generated document which requires no signature.***
page 1

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSHORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TAX INVOICE

Repair Code : CLM16370

Date in : 25/07/2024

Vehicle Num. : SLT5933C

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Subtotal before discount	1,760.00
Percentage discount 0%	0.00
Sub-total 2	1,760.00
Parts-total	8,757.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knucke arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.


To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,930.00
Parts & Labour Total	10,687.50

*** This is a computer-generated document which requires no signature.***

page 2



Adrian Cj
1/5 26/07/24
08 Pays.
Total: 6099.60
1/5: 4.8K ✓