

CS/ICS24070413/Anp3 (SLT 5933C)

ASSIGNMENT

From: _____ Date: _____
 Estin: ☒ ~~Estin~~
 OD: ☒ ~~TP RES / CD RES / EVA / INV / MV~~
 To in ~~Vehicle~~ No: _____
 at ~~Work~~ ~~Shop~~ /s _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vek: _____

(Policy Condition)

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLT5933C Yr Regn: 2017 / Nov
 Type: ☒ M. Car / ☐ M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Andi A4 C.D. 1395
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 143701 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZ2F44JA025228
 Gen. Cond: ☒ Good / Fair / Poor / Burnt
 Steering: ☒ In order / Jammed / Leaked / Burnt or
 Brake: ☒ In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R18
 R: 225/45R18

BS / DUN / EXNOVA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Privilo

Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/07/24
 Survey held at Zwinger

Des. of Damages: Frt / Rear / O/S / ☒ N/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECKS</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>Adrian confirmed lump sum \$4800 and 5 days (red, \$5887.5, 55%)</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

Photos

1)

Date/Time, File Return to?

2)

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TAX INVOICE

Repair Code : CLM16370

Date in : 25/07/2024

Vehicle Num. : SLT5933C

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>born</i>	1	1790.00	✓ 1,790.00
REAR BUMPER SIDE RETAINER L/R <i>Ken</i>	2	198.00	+ 396.00
REAR LH CONTROL ARM (1) <i>Buk</i>	1	405.00	✓ 405.00
REAR LH CONTROL ARM (2) <i>Ken</i>	1	405.00	+ 405.00
REAR LH FENDER <i>Rep's</i>	1	1800.00	+ 1,800.00
REAR LH KNUCKLE ARM <i>Ryd</i>	1	869.00	✓ 869.00
REAR LH KNUCKLE ARM BEARING <i>Ryd</i>	1	765.00	✓ 765.00
REAR LH LOWER ARM <i>Best</i>	1	515.00	✓ 515.00
REAR LH SHOCK ABSORBER <i>Neu</i>	1	405.00	+ 405.00
REAR LH UPPER ARM <i>Best Neu</i>	1	425.00	+ 425.00
Subtotal before discount			7,775.00
Percentage discount 10%			777.50
Sub-total 1			6,997.50
REAR BUMPER CLIPS - SET <i>M</i>	1	80.00	<i>30</i> 80.00
REAR LH SPORT RIM <i>ut</i>	1	1080.00	<i>80</i> 1,080.00
REAR LH TYRE (225/45ZR18) <i>ut</i>	1	600.00	<i>250</i> 600.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSHORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TAX INVOICE

Repair Code : CLM16370

Date in : 25/07/2024

Vehicle Num. : SLT5933C

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Subtotal before discount	1,760.00
Percentage discount 0%	0.00
Sub-total 2	1,760.00
Parts-total	8,757.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,930.00
Parts & Labour Total	10,687.50

50
✓ 80.00
200 350.00
80 100.00
400 700.00
300 600.00
30 100.00

*** This is a computer-generated document which requires no signature.***

page 2

Adrian Cj
1/s 26/07/24
08 Days.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: