

ASSIGNMENT

From: _____ Date: _____
 Estir: _____
 OD / TP / RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at Work / Shop / ms _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLT5933C Yr Regn: 2017, Nov
 Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Audi A4 C.D. 1395
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 143701 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WAUZZZF44JA025228
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/45R18
 R: 225/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Pirelli

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/07/24

Survey held at Twinlax
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP ECICS</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + R8. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Inve (\$ _____)

Report Format: _____

Report Form: _____

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSHORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TAX INVOICE

Repair Code : CLM16370

Date in : 25/07/2024

Vehicle Num. : SLT5933C

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>born</i>	1	1790.00	✓ 1,790.00
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	198.00	+ 396.00
REAR LH CONTROL ARM (1) <i>But</i>	1	405.00	✓ 405.00
REAR LH CONTROL ARM (2) <i>new</i>	1	405.00	+ 405.00
REAR LH FENDER <i>Rep's</i>	1	1800.00	+ 1,800.00
REAR LH KNUCKLE ARM <i>Rep's</i>	1	869.00	✓ 869.00
REAR LH KNUCKLE ARM BEARING <i>Rep's</i>	1	765.00	✓ 765.00
REAR LH LOWER ARM <i>Best</i>	1	515.00	✓ 515.00
REAR LH SHOCK ABSORBER <i>new</i>	1	405.00	+ 405.00
REAR LH UPPER ARM <i>Best new</i>	1	425.00	+ 425.00
Subtotal before discount			7,775.00
Percentage discount 10%			777.50
Sub-total 1			6,997.50
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i> 80.00
REAR LH SPORT RIM <i>cut</i>	1	1080.00	<i>80</i> 1,080.00
REAR LH TYRE (225/45ZR18) <i>cut</i>	1	600.00	<i>250</i> 600.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ZHOU CHAOQUN
402B NORTHSORE DRIVE #06-56
SINGAPORE 822402

Contact : 80352393

TAX INVOICE

Repair Code : CLM16370

Date in : 25/07/2024

Vehicle Num. : SLT5933C

Model : AUDI A4 1.4 TFSI S TRONIC

Chassis/Eng# : WAUZZZF44JA025228/CVN045583

Subtotal before discount	1,760.00
Percentage discount 0%	0.00
Sub-total 2	1,760.00
Parts-total	8,757.50

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change rear suspension parts, axle carriage, absorber, lower arm, top arm, trailing arm, knuckle arm, wheel bearing, bearing hub and etc.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	1,930.00
Parts & Labour Total	10,687.50

50
✓ 80.00
200 350.00
80 100.00
400 700.00
300 600.00
30 100.00

*** This is a computer-generated document which requires no signature.***

page 2

Adrian Lj
1/3 26/07/24
OBS Pays.

