

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. : SAC2401844

INV Date : 13-12-2024

Reference CD/LPC24070414/Rua3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SKG 8846G
Insured Veh. SMU 4113S
Claim No. 23/24/24/VP05/029573
Policy No. Z23VP05034590
Accident Date 20/07/2024
Inspection Date 05/08/2024

Description	Amount
Third Party Express Settlement	450.00
Sub-Total	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24070414/Rua3q2
300 BEACH ROAD	Date:	13/12/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SMU 4113S	Veh. Inspected	SKG 8846G
Policy No.	Z23VP05034590	Coverage	0
Claim No.	23/24/24/VP05/029573	Excess	\$0.00
Assign From	ENG HUEY NI	Assign Date	26/07/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ C180 AVANTGARDE (R17 LED)	C.C	1595
Engine No.	27491030766398	Year of Reg.	23/03/2017
Chassis No.	WDD2050402R257484	Colour	GREY
Odometer	64642 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/50 R17	CONTINENTAL	6
L/H Front Tyre	225/50 R17	CONTINENTAL	6
R/H Rear Tyre	225/50 R17	CONTINENTAL	6
L/H Rear Tyre	225/50 R17	CONTINENTAL	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/07/2024	Inspection Date	05/08/2024
Survey held at	CYCLE & CARRIAGE INDUSTRIES PL 188 PANDAN LOOP (MERCEDES-BENZ)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKG 8846G

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SUNDRIES (SN)	NECESSARY	\$20.00	\$20.00
1	REAR BUMPER (SN)	DEFORMED	\$2,078.29	\$2,078.29
1	REAR BUMPER LOWER (SN)	SCRATCHED	\$321.68	\$321.68
1	REAR BUMPER LOWER CHROME MOULDING (SN)	SCRATCHED	\$370.49	\$370.49
1	REAR BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	\$135.36	\$0.00
1	REAR DISTANCE SENSOR (SN)	NOT NECESSARY	\$201.17	\$0.00
1	PTS SPACER RING (SN)	NECESSARY	\$8.89	\$8.89
1	RIGHT REAR BUMPER BOTTOM BRACKET (SN)	CRACKED	\$49.85	\$49.85
1	REAR BUMPER UNDER COVERING (SN)	NOT NECESSARY	\$122.73	\$0.00
1	REAR BUMPER BOTTOM SWITCH BRACKET (SN)	NOT NECESSARY	\$47.69	\$0.00
1	REAR CROSS MEMBER (SN)	BENT	\$921.58	\$921.58
			\$4,277.73	\$3,770.78

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	PANEL BEATING TO REPAIR AFFECTED AREAS ,REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH		\$1,200.00	\$960.00
	RESPRAY REAR BUMPER		\$1,200.00	\$800.00
	USING XENTRY SYSTEM TO CHECK CONTROL UNITS ,RESET SYSTEM TO STANDARD SETTING		\$380.00	\$380.00
	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE		\$120.00	\$120.00
			\$2,900.00	\$2,260.00

GRAND TOTAL			\$7,177.73	\$6,030.78
--------------------	--	--	-------------------	-------------------

	RECOMMENDED COST OF REPAIRS			\$6,030.78
--	------------------------------------	--	--	-------------------

Report Ref No: CD/LPC24070414/Rua3q2

MARKET VALUE: \$69,000.00(EST) LESS LTA REBATE: \$36,875.00(EST) = NETT VALUE :\$32,125.00(EST)

MRB

MOHAMMED RASUL BIN MOHD YUNUS



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 8 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G



PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SKG 8846G

