

CARSMITH PRIVATE LIMITED

Bartley Biz Centre 13 Kaki Bukit Road 4 #01-20 Singapore 417807

Tel: 9091 0000/ Email: info@carsmith.biz

Not Authorized
in
may
30/7/24
4/5 #2200/
telephone 176 172-
3 days

VEHICLE NO: GBD8921U

MAKE & MODEL: TOYOTA DYNA

DOA: 24.07.2024

CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
TAILGATE	1	\$ 1,365.00	20/24t ✓
TAILGATE FLOOR PANEL	1	\$ 987.00	2X
SIDE GATE LH	1	\$ 1,850.00	2X
SIDE GATE LOCK LH	1	\$ 280.00	2X
SIDE GATE FLOOR PANEL LH	1	\$ 3,258.00	11X
REAR TAIL LAMP LH	1	\$ 640.00	11X
REAR TAIL LAMP PANEL LH	1	\$ 270.00	11X
NUMBER PLATE PANEL	1	\$ 490.00	11X
END STEP PANEL	1	\$ 450.00	34t ✓
END PANEL	1	\$ 980.00	2X
END PANEL SIDE BRACKET LH & RH	2	\$ 560.00	11X
END PANEL SIDE BRACKET STOPPER LH & RH	2	\$ 122.00	11X
		\$ 11,252.00	
	LESS 25%	\$ 2,813.00	
	SUB TOTAL	\$ 8,439.00	

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
REAR NUMBER PLATE	1	\$ 90.00	Sub X
70KM/H STICKER	1	\$ 35.00	new 105/12
13 PAX STICKER	1	\$ 35.00	new 105/12
TOYOTA STICKER	1	\$ 55.00	NE X
DYNA STICKER	1	\$ 35.00	NE X
Tailgate inner Aluminium plate	1 SET	\$ 480.00	Sub 400 5/12
REAR FLOOR CHECKED PLATE RIVETS	1 SET	\$ 180.00	new 30 5/12
JOINT SEALANT	1	\$ 120.00	11X
	SUB TOTAL	\$ 1,030.00	

LABOUR	QTY	PRICE (\$)	REMARKS
CHECK REAR WIRING AND LIGHTING SYSTEM	1	\$ 100.00	20
REMOVE AND RENEW REAR REVERSE SENSOR	1	\$ 120.00	11X
REMOVE AND REFIT REAR LINING, TRIM AND GARNISH	1	\$ 150.00	11X
PANEL BEATING ON AFFECTED AREAS AND RENEW DAMAGE PARTS	1	\$ 1,200.00	400

SPRAY PAINTING ON AFFECTED AREAS	1	\$ 1,000.00	522
APPLY ANTI RUST ON AFFECTED AREAS	1	\$ 100.00	30

SUB TOTAL \$ 2,670.00

GRAND TOTAL \$ 12,139.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-1815
252
1361.28
450
950
2761.28
212
2209