

REF:

CS LIP 24070420 / Avh3

ASSIGNMENT

From: _____ Date: _____

Estimate: _____

OD / ~~TP~~ / TP RES / OD RES / EVA / INV / MV

To in _____ Vehicle No: _____

at _____

of _____

Insured: **SLH 5129X**

Policy No: _____

Claims No: **AVS24/2305**

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Rep.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: **PD3378E** Yr Regn: **2023 Oct.**Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: **Volvo B11R** C.D. **10837**Colour: **Gold** A/C: Insured / Std / NI / NASp. Reading: **65547** T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: **YV3T2482XNA 209799**Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim, orTyre Size: F: **295/80 R22-5**R: **295/80 R22-5**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. **08** mm R/Bal. **08** mmL/Bal. **08** mm L/Bal. **08** mmD.O.A. **24/7/24** D.O.I. **06/08/24**Survey held at **YSL**Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP Liberty
10/9/25	Adrian confirmed LS \$9800 (red 22,340, 69%)
	COE Expiry
	Estimate given during 1st Survey
	MV: Yes ()
	1st Survey No (✓)
	PV: 79K
	Nett.
	503C

Date/Time, File Pass to?



Preli. Report

1)

Date/Time, File Return to?



Final Report

2)

Days Of Repair: **6**

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

3 + RS. \$1

Photos

Others

Addl Fee: ☐

Site Insp (\$)



Interview (\$)



Tech. Inve (\$)



Report Format:

Report Format: A, B, C, D, E, F, G, H, I, J, K, L, M, N, O, P, Q, R, S, T, U, V, W, X, Y, Z

M.V. \$220K - \$240K

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	503C
Vehicle Details	
Vehicle No.:	PD3378E
Vehicle to be Exported:	No
Intended Deregistration Date:	07 Aug 2024
Vehicle Make:	VOLVO
Vehicle Model:	B11R
Primary Colour:	Multicolor
Manufacturing Year:	2022
Engine No.:	D112039701
Chassis No.:	YV3T2U82XNA209799
Maximum Power Output:	-
Open Market Value:	\$163,000.00
Original Registration Date:	18 Oct 2023
First Registration Date:	18 Oct 2023
Transfer Count:	0
Actual ARF Paid:	\$8,150.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	17 Oct 2033
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$85,900.00
COE Rebate Amount:	\$78,972.00
Total Rebate Amount:	\$78,972.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 07 Aug 2024

OK

depr. ≈ \$27K

YSK AUTO

1 KAKI BUKIT AVENUE 6
#01-71 AUTOBAY SINGAPORE 47883

DOA 24/7/20

TO	: LIBERTY	TE	6/8/2024
VEHICLE NO	: PD3378E (2023)		
VEHICLE MODEL	: VOLVO B11R		Veron.
CHASSIS NO	: YV3T2U82XNA209799		

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	REAR NUMBER PLATE <i>New</i>	1	\$ 50.00	\$ 50.00
2	REAR BUMPER <i>Smashed</i>	1	\$ 4,000.00	\$ 4,000.00
3	REAR BUMPER SIDE <i>LH Distorted, RH Repair</i>	2	\$ 2,800.00	\$ 5,600.00
4	REAR BUMPER SIDE SUPPORT STRUCTURE <i>LH Distorted</i>	2	\$ 1,500.00	\$ 3,000.00
5	REAR BUMPER REFLECTOR (RED) <i>Cracked</i>	1	\$ 100.00	\$ 100.00
6	REAR BUMPER REFLECTOR (ORANGE) <i>new</i>	1	\$ 80.00	\$ 80.00
7	TAILLAMP <i>Cracked</i>	1	\$ 2,800.00	\$ 2,800.00
8	TAILLAMP PANEL <i>Repair</i>	1	\$ 1,800.00	\$ 1,800.00
9	ENGINE COMPARTMENT COVER <i>Repair</i>	1	\$ 6,800.00	\$ 6,800.00
10	ENGINE COMPARTMENT COVER STICKERS (SET) <i>new</i>	1	\$ 380.00	\$ 380.00
11	60 KM/H STICKER <i>3 New</i>	1	\$ 15.00	\$ 15.00
12	90KM/H STICKER <i>3 New</i>	1	\$ 15.00	\$ 15.00
13	VOLVO WORDING <i>3 New</i>	1	\$ 200.00	\$ 200.00
14	B11R WORDING <i>3 New</i>	1	\$ 250.00	\$ 250.00
15	HOSE <i>at</i>	1	\$ 200.00	\$ 200.00
16	SIDE COMPARTMENT COVER <i>Buckled</i>	1	\$ 1,300.00	\$ 1,300.00
17	REVERSE SENSOR (SET) <i>Damaged</i>	1	\$ 400.00	\$ 400.00
18	REAR EXHAUST TAIL PIPE <i>Missing</i>	1	\$ 300.00	\$ 300.00
TOTAL :				\$ 27,290.00

x
3500
2000
1000
✓
✓
2000
x
x
150
✓
✓
✓
120
1000
280
180

10890

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	2,500.00	800	
2	SPRAY PAINTING TO AFFECTED AREA	2,000.00	1000	
3	WIRING CHECK	100.00	30	
4	TO APPLY TUFF COAT	250.00	50	

TOTAL:

4,850.00

1880

ESTIMATE REPORT

TOTAL PARTS COST: \$ 27,290.00
TOTAL LABOUR COST: \$ 4,850.00
TOTAL REPAIR COST: \$ 32,140.00

Total 12770
H/s 10.2K
06 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer