



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070421/Uvp3
16 RAFFLES QUAY	Date:	16/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 3960J	Veh. Inspected	SJQ 940D
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24006432MFCT	Excess	\$0.00
Assign From	CAROLINE	Assign Date	26/07/2024

2. Vehicle Details

Make & Model	BMW 520I (A)	C.C	1998
Engine No.	11706309B48B20A	Year of Reg.	14/04/2021
Chassis No.	WBA72AG010WX09731	Colour	WHITE
Odometer	37142 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/40R19	BRIDGESTONE	7
L/H Front Tyre	245/40R19	BRIDGESTONE	7
R/H Rear Tyre	275/35R19	BRIDGESTONE	7
L/H Rear Tyre	275/35R19	BRIDGESTONE	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES

5. General Information

Accident Date	23/07/2024	Inspection Date	29/07/2024
Survey held at	SPECIALISTS MOTOR PTE LTD BLK 3018A UBI ROAD 1 #01-24-26 SINGAPORE 408711		

5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days