

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJQ940D/24071111

23rd July 2024

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
16 Raffles Quay
#42-01 Hong Leong Building
Singapore 048581

Not Authorized
29/7/24
P/P \$4587.52
3 days
take photo before pay.

Date Of Accident : 23rd July 2024

Location :

Third Party Claim Vehicle No : SHA 3960 J

Repair Cost For Vehicle No : SJQ 940 D BMW

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia DO/PC 1510.80	1	1,554.15	\$ 1,554.15
2	Front bumper clips	1set	50.00	\$ 50.00
3	Front bumper side retainer L&RH 111	2	35.60	\$ 71.20 X
4	Front bumper sensor (centre) SK	2	265.55	\$ 531.10 X
5	Front bumper towing cover CUY	1	98.50	\$ 98.50
6	Front bumper lower grille 11	1	151.12	\$ 151.12 X
7	Front bumper reinforcement 2	1	797.25	\$ 797.25 +
8	Front bumper sponge 111	1	130.75	\$ 130.75 X
9	Front grille with chrome L&RH CNE	2	503.90	\$ 1,007.80
10	Front grille base CNE	2	440.70	\$ 881.40
11	Front grille camera Daye/CNE 773.80	1	920.60	\$ 920.60
12	Front number plate (s/nett) CNE	1	50.00	\$ 50.00
				\$ 6,243.87

52

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJQ940D/24071111

23rd July 2024

Balance b/f \$ 6,243.87

Labour Charges :-

Amounts

Cut out, renew, knocking & welding front bumper reinforcement, remove & install all damage parts & re-align body	\$ 880.00	300
Remove & refix rear bumper sensor	\$ 100.00	40
Spray painting on damage parts	\$ 580.00	300
Diagnostic & reset	17 \$ 380.00	X
Check all lighting after repairs	\$ 40.00	20
Remove & refit front camera	\$ 400.00	200

Labour Charge \$ 2,380.00

Total Amount \$ 8,623.87

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-3881.6
506
3687.52
40
860
4587.52