

ASSIGNMENT

Front: _____ Date: _____
 Estin: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at W/O _____
 of _____
 Insured: _____
 Policy: File
 Claims: File
 Sum Insured _____ Excess: _____
 (Client's Record)
 Make of Val _____
 (Policy Condition)

Remark: The vehicle had commenced its repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repair: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Veh No: SmX5910K Yr Regn: 2021 Jan.
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Noah Hybrid 1797
 Colour: White A/C: Insured / Std / NI / NA
 Sp. Reading: 195571 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: ZWR800404590
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: Nil S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Rydan

Front _____ Rear _____
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 26/07/24
 Survey held at Xin Hua
 Des. of Damages: Frt / Rear / O/S / VS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

TP 1st Cap

COE Expiry

Estimate given during: Yes (✓)
 1st Survey: No ()

MV: 150K

PV: 51K

Nett: 98.9K

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Inve (\$

Report Format:

Report Format: _____

XIN HUA WORKSHOP PTE. LTD.

23 Kaki Bukit Avenue 4, #04-01 (South Wing) Singapore 415933

Reg : 201838521G

Vehicle Number : SMX 5910 K
Vehicle Model : TOYOTA VOXY
Accident Date : 24.07.2024
Original Reg Date : 20.01.2021

Date : 25.07.2024
Chassis : ZWR800404590
TP Ins. FIRST CAP

ESTIMATE

1	1 pc	SIDE SLIDING DOOR LH <i>Dented</i>		2,183.00	
2	1 pc	SLIDING DOOR WEATHERSTRIP RH(DOOR) <i>th</i>		189.60	+
3	1 pc	SLIDING DOOR STOPPER <i>den</i>	35.00	70.00	+
4	1 pc	SLIDING DOOR INNERLOCK <i>den</i>		298.60	+
5	1 pc	SLIDING DOOR CATCH <i>den</i>		38.60	+
6	1 pc	SLIDING DOOR INNERTRIM LH <i>den</i>		598.20	+
7	1 pc	SIDE DOOR STEP GARNISH <i>den</i>		325.70	+
8	1 pc	SIDESKIRT LH <i>den ?</i>		725.90	den ?
9	1 pc	REAR FENDER LH <i>Peris</i>		1,645.80	+
10	1 pc	REAR FENDER INNERTRIM LH <i>den</i>		825.60	+
11	1 pc	REAR FENDER INNER COWLING LH(FRONT) <i>den</i>		186.20	+
12	1 pc	REAR FENDER INNER COWLING LH (REAR) <i>?</i>		178.60	?
13	1 pc	REAR BUMPER <i>?</i>		705.20	?
14	1 pc	REAR BUMPER RETAINER LH <i>den</i>		86.30	+
15	1 pc	REAR CORNER BUMPER LH <i>den</i>		285.90	+
16	1 pc	REAR RIM LH <i>den</i>		1,025.60	500/sr
17	1 pc	REAR WHEEL HUB BEARING LH <i>?</i>		385.20	?
18	1 pc	REAR ABSORBER LH <i>den</i>		345.80	+
			subtotal	10,099.80	
			Less 25%	2,019.96	
			total	8,079.84	

Special Nett

1	1 set	Rear door inner trim clips <i>den</i>		30.00	+
2	1 set	Rear Bumper clips <i>den</i>		30.00	+
3	1 set	Sideskirt clips <i>den</i>		30.00	+
4	1 set	Rear fender inner cowling clips <i>?</i>		30.00	?
5	1 pc	Rear Tyre <i>den</i>		380.00	+
6	1 Set	Rear fender glass sealant <i>den</i>		80.00	+
			subtotal	580.00	

Labour charge

Panel Beating		1,800.00	500
Spray painting		1,800.00	800
Anti rust		120.00	40
Perform computerised wheel alignment		120.00	80
Remove and install rear undercarriage		300.00	50
Remove and install rear fender glass		120.00	x
Remove and install side door mechanism		200.00	60
		\$ 4,460.00	

total

13,119.84

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin Lg
f/s 26/07/24.
05hys.

Blkord

CITY TYREAUTO PTE LTD
219 KAKI BUKIT AVE 1
SHUN LI INDUSTRIAL PARK
SINGAPORE 416044
TEL: 67466686
H/P: 85153676

Work Order: R007624
License: SMX5910K
Date: 25.7.24 14:57

Factory Japan 2020.0.1 : Toyota : Noah / Voxy : R80 Series : ZRR80G

Front : Left

Actual	Before	Specified Range
-0°56'	-0°56'	-0°50' 0°40'
3°25'	3°25'	2°40' 4°10'
0°12'	0°12'	-0°03' 0°08'
1°26'	1°26'	9°30' 11°00'
0°30'	0°30'	8°40' 11°40'

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°50'	-0°50'	-0°50' 0°40'
3°25'	3°25'	2°40' 4°10'
0°07'	0°07'	-0°03' 0°08'
1°20'	1°20'	9°30' 11°00'
0°30'	0°30'	8°40' 11°40'

Front

Cross Camber
Cross Caster
Cross SAI
Total Toe
Cross Turn Diff.

Actual	Before	Specified Range
-0°06'	-0°06'	-0°45' 0°45'
0°00'	0°00'	-0°45' 0°45'
0°06'	0°06'	
0°19'	0°19'	-0°05' 0°16'

Rear : Left

Actual	Before	Specified Range
1°35'	1°35'	-1°55' -0°25'
1°04'	1°04'	-0°01' 0°18'

Camber
Toe

Rear : Right

Actual	Before	Specified Range
-0°59'	-0°59'	-1°55' -0°25'
0°12'	0°12'	-0°01' 0°18'

Rear

Cross Camber
Total Toe
Thrust Angle
Axle Offset

Actual	Before	Specified Range
2°34'	2°34'	-0°45' 0°45'
1°16'	1°16'	-0°03' 0°35'
0°26'	0°26'	
0mm	0mm	