



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 1
DOCUMENT NO.: 1326
DOCUMENT DATE: 23/07/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 16806
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA3 1.5L SDN DELUXE BLACK L
CHASSIS NO.: JM6BN22A8H0167678
ENGINE NO.: P520459338
REG NO.: SLR5251Y
REGN DATE: 17/08/2017

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	CHINA TAIPING TP CLAIM				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER. AND ALL ACCIDENT AFFECTED AREA.			792	1,584.00	S
SUB	TO RESPRAY REAR BUMPER.			756	1,512.00	S
SUB	TO TRANSFER REVERSE SENSOR.			180	330.00	S
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.			120	250.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.			152	300.00	S
SUB	SUNDRIES.			20	50.00	S
BFYD-50-221	REAR BUMPER BM/BN W/SENSOR	1.00	1,143.51	NO STOCK	1,143.51	S
BBM4-50-355	RIVET	4.00	3.71	NO STOCK	14.84	S
BHN1-50-0Z1A	GROMMET, SCREW	4.00	2.36	NO STOCK	9.44	S
BFYB-51-077	BRACKET 'B' LHR BUMPER BM/BN	1.00	51.17	STOCK	51.17	S
BFYB-51-067	BRACKET 'A' RHR BUMPER BM/BN	1.00	51.17	STOCK	51.17	S
B45A-56-146A	FASTENER	4.00	2.36	STOCK	9.44	S
BFYB-50-EL1	COVER(L), TOWING HOOK BM	1.00	48.13	STOCK	48.13	S
BFYB-50-EK1	COVER, TOWING HOOK BM/BN	1.00	48.13	STOCK	48.13	S
D350-51-5LOE	REFLECTOR LHR, REFLEX-	1.00	55.13	NO STOCK	55.13	S
D350-51-5MOE	REFLECTOR RHR REFLEX-	1.00	55.13	NO STOCK	55.13	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will vary depending on the time unit that was taken for the checking and diagnosis of your vehicle.

LIK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

TRANS EUROKARS Corporate Head Office: Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

Zoom-Zoom Showrooms & Service Centres:

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:
27A Tanjong Penjuru Singapore 609042
Service Tel: 6331 0606
Service Fax: 6331 0620

Not Approved
The 3rd party.
3.17/24
3 days
PIP \$3270.43



QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 2
DOCUMENT NO.: 1326
DOCUMENT DATE: 23/07/2024
POS ID: MU
PRINTED BY: Lee Yao Sheng
SERVICE ADV:
CSP/OP CODE: Lee Yao Sheng
DEPT: I
WIP NO.: 16806
REF. NO.:
DATE IN:
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA3 1.5L SDN DELUXE BLACK L
CHASSIS NO.: JM6BN22A8H0167678
ENGINE NO.: P520459338
REG NO.: SLR5251Y
REGN DATE: 17/08/2017

DESCRIPTION:

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
KD47-67-UC5A2	RETAINER KF	4.00	15.77	*NO STOCK	63.08	S ✓
BHN1-50-2J1A	RETAINER LHR BUMPER BM/BN	1.00	40.55	STOCK	40.55	S ✓
BHN1-50-2H1A	RETAINER RHR BUMPER BM/BN	1.00	40.55	*NO STOCK	40.55	S ✓
B45A-50-260	REINFORMENT REAR BM	1.00	576.77	*NO STOCK	576.77	S ✓
B64F-67-290	CORD,SHORT	1.00	184.34	*NO STOCK	184.34	S ✓
GMK6-67-UC1	2SENSOR,ULTRASONIC KF	2.00	184.59	*NO STOCK	369.18	S ✓
KD47-67-UC1	2'SENSOR,ULTRASONIC GJ	2.00	184.59	*NO STOCK	369.18	S ✓
GS1D-50-EM1A	TAPE,PROTECTOR	3.00	7.42	*NO STOCK	22.26	S ✓
BHN1-50-340B	SHIELD(R),SPLASH-R.B BM	1.00	89.35	*NO STOCK	89.35	S ✓
BHN1-50-350B	SHIELD(L),SPLASH-R.B BM	1.00	89.35	STOCK	89.35	S ✓
BHN1-51-153	GASKET(R),RR.COMB.BM/BN	1.00	26.47	STOCK	26.47	S ✓
BHN1-51-163	GASKET(L),RR.COMB. BM/BN	1.00	26.47	STOCK	26.47	S ✓

	GST Code	Rate	Service/Goods	GST
Parts	0	-		-
Surcharge	S	9.00%	7,409.64	666.87
Labour				
Menus				

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross	7,409.64	666.87	8,076.51
Less: Deposit**	0.00	0.00	0.00
Amount Due	7,409.64	666.87	8,076.51

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date:

Customer signature

Authorised signature



TRANS EUROKARS
Eurokars Group

Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147

Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

ZOOM-ZOOM

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre:

27A Tanjong Penjuru Singapore 609042

Service Tel: 6331 0606

Service Fax: 6331 0620