

QUOTATION

CODE: CUSTOMER: C0006

CONTACT NO.: 6389 6111

CHINA TAIPING (SINGAPORE) PTE LT

MAZDA3 1.5L SDN DELUXE BLACK L

ADDRESS:

MODEL:

REG NO.:

REGN DATE:

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

JM6BN22A8H0167678

P520459338

17/08/2017

SLR5251Y

POS ID:MU

PAGE NO .:

DOCUMENT NO .:

DOCUMENT DATE:

PRINTED BY:

SERVICE ADV:

CSP/OP CODE:

DEPT:

WIP NO .:

REF. NO.: DATE IN:

EXT. WTY:

MILEAGE:

0

16806

1

1387

17/08/2024

Wong Chun Wei

Wong Chun Wei

DESCRIPTION:

CHASSIS NO.:

ENGINE NO.:

Item	Description	Stk/Status Qty. Unit Price SGD	Gross GST amount Code SGD	
NOTES	CHINA TAIPING TP CLAIM	300	0.00	0
SUB	MZ 3 UBI		792.00	S
	TO REMOVE & REPLACE REAR BUMPER.		772.00	3
	AND ALL ACCIDENT AFFECTED AREA.			
	- PO22513			
SUB	MZ 3 UBI		756.00	S
	to respray rear bumper.		730.00	5
	- PO22513			
SUB	MZ 3 UBI		180.00	S
	to transfer reverse sensor.		100.00	9
	- PO22513			
SUB	MZ 3 UBI		120.00	S
	TO CHECK ELECTRICAL SYSTEM			
	FOR PROPER FUNCTIONING.			
CLID	- PO22513			
SUB	MZ 3 UBI		150.00	S
	TO REPROGRAMME AFTER THE			
	ACCIDENT REPAIR WORKS.			
	- PO22513			



TRANS**ELROKARS** Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

^{*}This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



QUOTATION

CODE:

C0006

CUSTOMER:

CHINA TAIPING (SINGAPORE) PTE LT

ADDRESS:

CONTACT NO.: 6389 6111

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

DOCUMENT NO .: **DOCUMENT DATE:**

2 1387

17/08/2024

MU

PRINTED BY:

PAGE NO .:

SERVICE ADV:

CSP/OP CODE:

Wong Chun Wei

Wong Chun Wei

DEPT:

WIP NO .:

POS ID:

16806

MAZDA3 1.5L SDN DELUXE BLACK L JM6BN22A8H0167678

ENGINE NO .: **REG NO.:**

CHASSIS NO.:

MODEL:

P520459338

REGN DATE:

SLR5251Y 17/08/2017

REF. NO .: DATE IN: EXT. WTY:

MILEAGE:

0

DESCRIPTION:

Item	Description	Qty. U	J <mark>nit Price</mark> SGD	Stk/Status	Gross amount SGD	
SUB	MZ 3 UBI SUNDRIES. - PO22513				20.00	S
B45A-56-146A GS1D-50-EM1	REAR BUMPER BM/BN W/SENSOR RIVET A GROMMET,SCREW FASTENER A TAPE,PROTECTOR GASKET(R),RR.COMB.BM/BN	1.00 4.00 4.00 4.00 3.00 1.00	1,143.51 3.71 2.36 2.36 7.42 26.47 26.47	*ISSUED *ISSUED *ISSUED *ISSUED *ISSUED *ISSUED *ISSUED	1,143.51 14.84 9.44 9.44 22.26 26.47 26.47	S S S

	*	GST Code	Rate	Service/Goods	GST
Parts	1,252.43	0	_		
Surcharge	0.00	S	9.00%	3,270.43	294.34
Labour	2,018.00				
Menus	0.00				
*This is only an e	estimate from ou	r visual inspectio	n and sho	uld there be more dama	ges found during

the process of works you will then be informed for your approval before proceeding with the repairs.

^{*}Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

	Before GST	GST	Total
Gross *	3,270.43	294.34	3,564,77
Less: Deposit**	0.00	0.00	0.00
Amount Due	3,270.43	294.34	3,564.77

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE No.

Date:

Customer signature

Authorised signature

ZOWN-ZOWN

(5) TRANSEUROKARS Corporate Head Office: Trans Eurokars Pte Ltd,11 Kung Chong Road Singapore 159147 Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres: 5 Ubi Close Singapore 408605

23 Leng Kee Road Singapore 159095 Sales Tel: 6603 6118 Service Tel: 6603 6128 Sales Fax: 6476 7073 Service Fax: 6476 7417

Eurokars Aftersales Centre: 27A Tanjong Penjuru Singapore 609042 Service Tel: 6331 0606 Service Fax: 6331 0620

Sales Tel: 6395 8888 Service Tel: 6395 8899 Sales Fax: 68461700 Service Fax: 6744 9402