

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

利民达摩多



Jementah Motor Works

Blk 14 Defu Lane 10 #01-406

Singapore 539195

H/P : 9299 6636 Fax : 6285 7054

No f Autocal
moving
d/s \$1800/
4 days.
alphas Hecy..

Date : 26-Jul-24

Estimated repair cost of SMX 8049 C Toyota Corolla Altis

Qty	Description	Amt S(\$)
	<u>List Items</u>	
1	Rear boot lid <i>Re</i>	\$ 985.70 <i>X</i>
2	Rear boot hinges <i>11</i>	\$ 171.40 <i>X</i>
2	Rear boot lamps <i>11</i>	\$ 577.40 <i>X</i>
1	Rear boot lock <i>11</i>	\$ 100.80 <i>X</i>
1	Rear boot logo <i>11</i>	\$ 89.70 <i>X</i>
1	Rear boot rubber <i>11</i>	\$ 145.70 <i>X</i>
2	Rear taillamps <i>11</i>	\$ 760.20 <i>X</i>
1	Rear end panel <i>Re</i>	\$ 777.40 <i>X</i>
1	Rear end panel inner garnish <i>11</i>	\$ 200.30 <i>X</i>
1	Rear keyless sensor <i>11</i>	\$ 185.20 <i>X</i>
1	Rear bumper <i>Re</i>	\$ 754.20 <i>X</i>
2	Rear bumper top brackets <i>11</i>	\$ 181.80 <i>X</i>
2	Rear bumper side brackets <i>11</i>	\$ 97.00 <i>X</i>
2	Rear bumper reflectors <i>11</i>	\$ 120.20 <i>X</i>
1	Rear bumper reinforcement <i>DD/Ref</i>	\$ 542.80 <i>X</i>
2	Rear bumper side retainers <i>11</i>	\$ 130.00 <i>X</i>
2	Rear bumper PDC sensors <i>Se</i>	\$ 390.00 <i>X</i>
		\$ 6,209.80
	Less 25%	\$ 1,552.45
		\$ 4,657.35

Special Nett Items

1	Rear bumper clip (1 set) <i>Re</i>	\$ 50.00
		\$ 50.00

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$ 80.00 <i>20</i>
2	To remove and refit inner garnishes.	\$ 11 120.00 <i>X</i>
3	To remove and refit rear reverse sensor.	\$ 120.00 <i>30</i>
4	To transfer boot lid mechanism and wiring assembly.	\$ 11 80.00 <i>X</i>
5	To apply undercoating.	\$ 11 100.00 <i>X</i>
6	Panel beating.	\$ 1,400.00 <i>550</i>
7	To re-spray painting on the affected areas.	\$ 1,300.00 <i>720</i>
		\$ 3,200.00

Grand Total :

\$ 7,907.35

P-1259-4
252
944.55
30
1320
2294.55
1835