

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

TPINC
Veron

Make/ Model : <u>MERCEDES S320</u>	Date: <u>29.07.2024</u>
Chassis No : <u>WDD2221622A427764</u>	Vehicle No: <u>SKE9980E</u>
Date/Time of Accide <u>16.07.2024</u>	Year of Reg: <u>26.09.2018</u>

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$	FINAL PRICE \$
1	REAR DOOR RH <i>Rps</i>	1	\$ 2,895.60	\$ 2,895.60
2	REAR DOOR INNER TRIM RH	1	\$ 1,682.30	\$ 1,682.30
3	REAR DOOR INNER LOCK RH <i>Renew</i>	1	\$ 398.60	\$ 398.60
4	REAR DOOR HINGES RH	2	\$ 178.60	\$ 357.20
5	REAR DOOR WEATHERSTRIP RH	1	\$ 325.80	\$ 325.80
6	REAR DOOR CHROME <i>ut</i>	1	\$ 398.20	\$ 398.20
7	REAR SIDE SKIRT <i>Rps</i>	1	\$ 1,455.70	\$ 1,455.70
8	REAR FENDER <i>Rps</i>	1	\$ 3,215.80	\$ 3,215.80
9	REAR RIM RH <i>ut</i>	1	\$ 2,525.60	\$ 2,525.60
10	REAR LOWER ARM RH	1	\$ 925.80	\$ 925.80
11	REAR TRAILING ARM RH	1	\$ 845.80	\$ 845.80
12	REAR ABSORBER RH <i>NOF</i>	1	\$ 895.60	\$ 895.60
13	REAR KNUCKLE ARM RH <i>NOF</i>	1	\$ 987.20	\$ 987.20
14	REAR WHEEL HUB BEARING RH	1	\$ 856.30	\$ 856.30
15	STABILIZER LINKAGE	1	\$ 348.90	\$ 348.90
Total List Price Cost				\$ 18,114.40
				\$ 16,302.96

35820
35838 1100(SW)

PARTS DISCOUNT 10%

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$	FINAL PRICE \$
1	REAR FENDER INNER COWLING CLIPS	1 SET	\$ 30.00	\$ 30.00
2	REAR FENDER INNER TRIM CLIPS	1 SET	\$ 30.00	\$ 30.00
3	REAR TYRE	1	\$ 350.00	\$ 350.00
4	REAR DOOR INNER TRIM CLIPS	1 SET	\$ 30.00	\$ 30.00
Total Special Nett Items				\$ 440.00

Labour Works/ Panel Beating Related Works

Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 2,000.00

Spray Painting

Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 2,000.00

Others Cost (Accident Repair Related Expenses)

Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00

TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$	150.00	*
TO APPLY SEALANT TO THE AFFECTED AREAS	\$	150.00	*
TO PERFORM COMPUTERISED WHEEL ALIGNMENT	\$	160.00	*
TO CONDUCT WATER LEAKAGE TEST	\$	150.00	*
TO REMOVE/ REPLACE REAR UNDERCARRIAGE	\$	200.00	*
TO REMOVE/ REFIT / REPLACE REAR DOOR MECHANISM	\$	160.00	*
Total Others Cost	\$	1,170.00	
	GRAND TOTAL	\$	21,912.96

SW.

total: 1958.38

4/s: 1.5K

0.37w/s.

1.5K

Person Incharge: JOHN
 Direct Contact: 98287487
 Email: ktmotorwerk@hotmail.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: