



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FBU 1496L

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	AIR BOX COVER	CUT	\$100.00	\$100.00
1	CVT COVER	CUT	\$100.00	\$100.00
1	REAR BOX WITH BONE PLATE (60L)	BENT	\$580.00	\$450.00
1	PILLION FOOTREST LH	CUT	\$180.00	\$180.00
1	MAIN STAND	BENT	\$150.00	\$150.00
1	SIDE STAND	BENT	\$90.00	\$90.00
1	HANDLE BAR END BALANCER LH	BENT	\$100.00	\$70.00
1	REAR VIEW MIRROR LH	BROKEN	\$100.00	\$100.00
1	BRAKE LEVEL LH	CUT	\$50.00	\$50.00
1	HANDLE BAR	BENT	\$170.00	\$170.00
1	SET FORK + TRIPLE CLAMP	BENT	\$780.00	\$780.00
1	FRONT DISC ROTOR	NOT NECESSARY	\$170.00	\$0.00
1	FRONT BRAKE PAD	NOT NECESSARY	\$80.00	\$0.00
1	SET WIND SHIELD	NOT NECESSARY	\$180.00	\$0.00
1	LAMP STAY	NOT NECESSARY	\$200.00	\$0.00
1	SET BODY COVER	CUT	\$800.00	\$700.00
1	SET INNER BLACK COVER	CUT	\$600.00	\$500.00
1	SET REAR BOX BRACKET	BENT	\$250.00	\$250.00
1	REAR MUD GUARD	CUT	\$210.00	\$210.00
1	STEERING CONE BEARING	NECESSARY	\$220.00	\$120.00
	LESS 0.00 / 10.00% DISCOUNT		\$0.00	(\$402.00)
			\$5,110.00	\$3,618.00

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	\$25.00	\$0.00
			\$25.00	\$0.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO REMOVE, REPLACE, REPAIR AND STRAIGHTEN THE ABOVE DAMAGED PARTS. TO RE-ADJUST TO THE ORIGINAL POSITION		\$480.00	\$250.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK, REPAIR AND STRAIGHTEN BODY FRAME TO THE ORIGINAL POSITION	NOT NECESSARY	\$650.00	\$0.00
			\$1,130.00	\$250.00
GRAND TOTAL			\$6,265.00	\$3,868.00
	RECOMMENDED COST OF REPAIRS			\$3,800.00
Report Ref No: CS/LIP24070435/Eqh3m4				

MARKET VALUE: \$12,500.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,316.00=NETT VALUE: \$4,184.00

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.