

KT GARAGE PTE LTD UEN: 201906115R
 Auto Bay@ Kaki Bukit Entrance A
 BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

Date :

Not Authorised

LKK Auto Consultants hence notify the Repairer of the following:

- To rectify before/after spray painting
- To display damaged parts before rectify
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be rectified and is subject to final approval from Insurance Company

Total Pages:

Our Customer: Zhe Kai Construction Pte Ltd

Vehicle No: **GBJ1687K**

Model: **Toyota Dyna**

Manufacture Year:

Date of Accident: **25/7/2024**

Total Estimate Repair Days:

TO: Whom it may concern

31/7/24
1/5 \$3900
3 days
24hrs A.M.

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front Bumper	1	\$720.00	\$720.00	715 ✓
2	Front Bumper Inner Bracket	1			NS X
3	Front Grille	1	\$710.00	\$710.00	11 X
4	Front Grille Emblem	1	\$105.00	\$105.00	11 X
5	Headlamp - RH	1	\$1,158.00	\$1,158.00	Che ✓
6	RH Headlamp Lower Trim	1			NS X
7	RH Corner Panel	1	\$495.00	\$495.00	Cut/che ✓
8	RH Corner Panel Clip	1	\$5.50	\$5.50	11 X
9	Front Body Panel Assy	1	\$1,451.50	\$1,451.50	11 X
10	RH Front Door	1	\$2,681.60	\$2,681.60	27/28 ✓
11	RH Front Door Checker	1	\$249.30	\$249.30	11 X
12	RH Front Door outer Weatherstrip Moulding	1	\$154.70	\$154.70	11 X
13	RH Front Door Weather strip	1	\$278.00	\$278.00	11 X
14	RH Front Door Weather Strip	1			11 X
15	RH Front Door Step Garnish	1	\$415.00	\$415.00	11 X
16	Wheel Arch Rubber Seal	1	\$64.00	\$64.00	11 X
17	Front Windscreen Rubber	1	\$505.00	\$505.00	11 X
18	RH Windscreen Pillar	1	\$615.00	\$615.00	11 X
	Sub Total			\$9,607.60	
	Less 25%			\$2,401.90	
	Sub Total 1			\$7,205.70	
B	Special Nett				
1	Company Sticker	1	\$80.00	\$80.00	Net 30 S/N
	Sub Total 2			\$80.00	
C	Labour				
1	To panel beat, knock and straighten damaged panel and re-align the same			\$1,680.00	500
2	To rust proof the affected areas			\$120.00	30
3	To check all necessary lighting & wiring			\$80.00	20
4	To remove front dashboard			\$400.00	11 X
5	To remove and refit front windscreen			\$180.00	11 X
6	To perform water seepage test			\$100.00	11 X
7	To spray paint the affected areas			\$1,250.00	520
	Total Labour			\$3,810.00	
	Total Repair Cost			\$11,095.70	



KT GARAGE PTE LTD UEN: 201906115R
Auto Bay@ Kaki Bukit Entrance A
BLK 1 Kaki Bukit Ave 6 #01-04 Singapore 417883

* The above quoted are exclusive of GST.

Yours faithfully,

Kai
f KT Garage Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

P- 5048-60
252
P- 3786-45
S.N- 30
L- 1070
4886-45
212
3909.16