

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CD/III24070437/KPA3Q2**Date:** 18/11/2024REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D23MFL0002571
Claimant Vehicle No :	SNF5600M	Insured Vehicle No :	SLK9713S
Date of Loss:	17/07/2024	Nature of Claim:	TP
		Claim No:	N/A

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNF5600M	Engine No:	B05910
Make & Model:	PORSCHE PANAMERA, 3.6 (A)	Chassis No:	WP0ZZZ97ZBL004175
Reg. Date:	16/05/2011 (Man. Year: 2011)	Odometer:	196958 km
Colour:	Metallic Brown		
Engine Capacity:	3605 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35Z R21	Rear Tyre Size:	295/30Z R21
Front Left Side:	Michelin 8 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 8 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,015.64	9,259.91	10,755.73	53.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,160.00	2,400.00	3,760.00	61.04
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,175.64	11,659.91	14,515.73	55.46
Approved Total (Overridden) (S\$)		9,500.00		
(S\$)	26,175.64	9,500.00	16,675.64	63.71
+ GST 9.00/9.00% (S\$)	2,355.81	855.00	1,500.81	63.71
Nett Amount (S\$)	28,531.45	10,355.00	18,176.45	63.71
+ Car Rental (10.0 x S\$150.00/day) (S\$)		1,500.00		
Nett Liability (S\$)		11,855.00		

INSPECTION

Date of Assignment:	30/07/2024	
Date Inspected:	30/07/2024	Inspected At: T & B Motor Repairs Services Pte Ltd Blk 160 Sin Ming Drive #08-03, Sin Ming Auto City Singapore 575722
Estimated Period of Repair:	6.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Oct 2024)
Parts:	144	PORSCHE PANAMERA 3.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNF5600M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Cracked	4,800.00 FL	*4,120.00 FL
2	1		*REAR BUMPER RETAINER	Serviceable	245.00 FL	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Bent	1,995.00 FL	*1,995.00 FL
4	1		*REAR END PANEL	Bent	2,680.70 FL	*2,216.00 FL
5	1		*PARKING SENSOR (4PCS)	Missing (2Pcs Only)	1,120.00 FL	*560.00 FL
6	2		*REAR LEFT EXHAUST (LOCAL REPAIR)	Dented	7,360.00 FN	*350.00 F
7	1		*REAR LEFT EXHAUST TIP	N/S Dented	2,300.00 FL	*640.00 FL
8	2		*REAR BUMPER PAT	Serviceable	1,370.00 FL	*- FL
9	1		*EXHAUST HEAD SHEILD LEFT	Bent	368.90 FL	*368.90 FL
F=Franchise part. L=ListItemDisc. N=NettItemDisc.						
Sub Total (\$)					22,239.60	10,249.90
- List Item Discount on L Items 10.00/10.00% (\$)					1,487.96	989.99
- Nett Item Discount on N Items 10.00/0.00% (\$)					736.00	0.00
Total Parts (\$)					20,015.64	9,259.91

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE BUMPER, REAR PANEL PULL AND KNOCKING	New	2,600.00	1,200.00
2	TO SPRAY REAR BUMPER AND LOWER SKIRT	New	1,400.00	900.00
3	COMPUTER DIAGNOSE & RESET SENSOR PARKING FAULT	New	350.00	0.00
4	LABOUR TO REMOVE INSIDE GARNISH IN ORDER TO REPAIR REAR END PANEL	New	580.00	150.00
5	LABOUR TO REMOVE EXHAUST AND BELOW COVER AND BRACKET AND FIX	New	450.00	120.00
6	TO REPAIR REAR EXHAUST	New	600.00	0.00
7	TO SPARY REAR END PANEL, ANTI RUST	New	180.00	30.00
Gross Labour Cost (\$\$)			6,160.00	2,400.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >