



HS AUTOMOTIVES PTE LTD

Bik 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

JP Chua
Veron.

Vehicle No: **SMD1994A**

Make/Model: **MERCEDES BENZ E250**

CHASSIS NO:

Date: **20-Aug-24**

Estimate cost of repair to the above mentioned

NO. LIST ITEMS

QTY UNIT \$ AMOUNT (\$\$)

1	FRONT BUMPER <i>old</i>	✓	1	\$	\$ 1650.85
2	FRONT BUMPER BASIC MOUNTING LH <i>new</i>	+	1	\$	\$ 173.00
3	FRONT BUMPER DISTANCE SENSOR LH <i>new</i>	+	1	\$	\$ 275.00
4	FRONT BUMPER PARKING SNEsor SPACER RING <i>new</i>	+	6	\$ 18.00	\$ 108.00
5	FRONT HEADLAMP LH <i>new</i>	+	1	\$ 3550	\$ 5424.32
6	FRONT HEADLAMP PANEL LH <i>new</i>	+	1	\$	\$ 515.00
7	FRONT FENDER LH <i>Repair</i>	+	1	\$	\$ 1232.00
8	FRONT FENDER LINER FRONT LH <i>new</i>	+	1	\$	\$ 735.00
9	FRONT RIM LH <i>new</i>	✓	1	\$	\$ 1193.00
10	FRONT SUB-FRAME CROSS MEMBER <i>new</i>	+	1	\$	\$ 1795.00
11	FRONT STEERING KNUCKLE LH <i>new</i>	✓	1	\$	\$ 1155.00
12	FRONT WHEEL BEARING HUB LH <i>new</i>	✓	1	\$	\$ 521.00
13	FRONT CONTROL UPPER ARM LH <i>new</i>	+	1	\$	\$ 236.00
14	FRONT CONTROL LOWER ARM LH <i>new</i>	+	1	\$	\$ 975.00
15	FRONT TRAILING LINK LH <i>new</i>	+	1	\$	\$ 253.00
16	FRONT TIE ROD LH <i>new</i>	+	1	\$	\$ 310.00
17	FRONT SHOCK ABSORDER LH <i>new</i>	+	1	\$	\$ 1370.00
18	LH FRONT SIDE MIRROR. <i>new</i>	✓			1210.00 2130.00
SUB TOTAL FOR LIST ITEMS					\$
9279.85					
8351.86					



HS AUTOMOTIVES PTE LTD

Blk 2 KAKI BUKIT AVE 2 @ KAKI BUKIT AUTOHUB #02-25 SINGAPORE 417921.

TEL: 6538 1368 FAX: 6538 1367 EMAIL: HSAUTOMOTIVESPL@GMAIL.COM

ROC: 201907812C

Vehicle No: **SMD1994A**

Make/Model: **MERCEDES BENZ E250**

CHASSIS NO:

Date: **20-Aug-24**

Estimate cost of repair to the above mentioned

NO. LIST ITEMS

QTY UNIT \$ AMOUNT (\$\$)

SPECIAL NETT ITEM

1	FRONT BUMPER RIVERT & CLIPS <i>nr</i>	1 SET	\$ x 100.00
2	FRONT FENDER INNER COWLING CLIPS LH <i>nr 280</i>	1 SET	\$ x 100.00
3	FRONT TYRE LH <i>Punctured</i>	1 PC <i>280</i>	\$ 400.00
SUB TOTAL FOR SPECIAL NETT ITEMS			\$ 600.00

LABOUR & MISC CHARGES

1	TO DISMANTLE, REPLACE AND PANEL BEATING ON AFFECTED PARTS AT FRONT PORTION.		\$ <i>4w</i> 1,000.00
2	TO SPRAY PAINT ON AFFECTED AREA AT FRONT PORTION.		\$ 400 800.00
3	TO REMOVE/REPLACE/REINSTALL PDC SENSORS.		\$ 50 100.00
4	TO REMOVE/REPLACE/REINSTALL FRONT UNDER CARRIAGE COMPONENTS.		\$ 100 400.00
5	TO PERFORM COMPUTERIZED WHEEL ALIGNMENT.		\$ 80 150.00
6	TO APPLY ANTI-RUST ON AFFECTED AREAS.	<i>1250</i>	\$ 40 100.00
7	TO CHECK WIRING FOR FRONT PORTION.		\$ 30 100.00
8	TO PERFORM SYSTEM DIAGNOSTIC & RESET ECU SYSTEM.		\$ 150 400.00
SUB TOTAL FOR LABOUR & MISC CHARGES			\$ 3,050.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

GRAND TOTAL

\$ **24,001.17**

Acknowledged by Repairer

REMARKS:

Signature:

Date:

NO OF DAYS:

AGREED FIGURE/LUMP SUM:

SURVEYOR NAME

EMAIL ADD:

06 Days

Adrian Ling

CONTACT:

96893735