



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS UNITED OVERSEAS INSURANCE LTD
146 ROBINSON ROAD
#02-01 UOI BUILDING SINGAPORE 068909

Ref: CS/UOI24070440/Dnp3e2

Date: 06/11/2024

Code: UOI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJK 8220C	Veh. Inspected	SHC 8481G
Policy No.	-	Coverage	0
Claim No.	M13D00042408	Excess	\$0.00
Assign From	JOEY TAY	Assign Date	29/07/2024

2. Vehicle Details

Make & Model	TOYOTA PRIUS	C.C	1797
Engine No.	2ZR2X01862	Year of Reg.	28/09/2023
Chassis No.	JTDAE3AU403001451	Colour	BLUE
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/60R17	YOKOHAMA	6
L/H Front Tyre	195/60R17	YOKOHAMA	6
R/H Rear Tyre	195/60R17	YOKOHAMA	6
L/H Rear Tyre	195/60R17	YOKOHAMA	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2024	Inspection Date	29/07/2024
Survey held at	59 LOYANG DRIVE LEVEL 4 ROOM 7 SINGAPORE 508969 - REPAIRER: BIFROST AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days