

ESTIMATE

26/7/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

Vehicle No: SKX1210Y
Vehicle Model: PEOGEOT 3008
Est No: CBMQ24070275
Claims ref:
Accident Date: 19/07/24
In Charge: JUNIOR
Remarks:

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 100B,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	FRONT BUMPER <i>sc</i>	1	PC \$ 2,300.00	\$ 2,300.00 ✓
2	FRONT BUMPER UPPER GARNISH <i>sc</i>	1	PC \$ 980.00	\$ 980.00 ✓
3	FRONT BUMPER UPPER GARNISH BRKT <i>? Xsc</i>	1	PC \$ 490.00	\$ 490.00
4	FRONT UPPER GRILLE BASE <i>? Xsc</i>	1	PC \$ 830.00	\$ 830.00
5	FRONT UPPER GRILLE BRACKET <i>? Xsc</i>	1	PC \$ 840.00	\$ 840.00
6	FRONT UPPER GARNISH EMBLEM "3008" <i>Dec</i>	1	PC \$ 220.00	\$ 220.00 ✓
7	FRT UPPER GRILLE EMBLEM "PEUGEOT" <i>? Xsc</i>	1	PC \$ 220.00	\$ 220.00
8	FRONT SPONGE <i>? Xsc</i>	1	PC \$ 430.00	\$ 430.00
9	FRONT LOWER GRILLE <i>? Xsc</i>	1	PC \$ 680.00	\$ 680.00
10	FRONT LOWER MOUDLING <i>sc</i>	1	PC \$ 990.00	\$ 990.00 ✓
11	FRONT LOWER SPOILER <i>Xsc</i>	1	PC \$ 630.00	\$ 630.00
12	HEADLAMP LH & RH <i>LH-? Xsc</i>	2	PC \$ 2,480.00	\$ 4,960.00
13	HEADLAMP LOWER PANEL LH & RH <i>LH-? Xsc</i>	2	PC \$ 730.00	\$ 1,460.00
14	FRONT PANEL SUPPORT BRACKET <i>Xsc</i>	1	PC \$ 690.00	\$ 690.00
15	FRONT BUMPER CLIPS <i>sc</i>	10	PC \$ 8.00	\$ 80.00 ✓
16	FRONT BUMPER RIVETS <i>? Xsc</i>	20	PC \$ 8.00	\$ 160.00

LIST TOTAL S\$ \$ 15,960.00
10% DISCOUNT S\$ \$ (1,596.00)
\$ 14,364.00

SPECIAL NET ITEMS:

1	FRONT NUMBER PLATE <i>bt</i>	1	PC \$ 50.00	\$ 50.00
---	------------------------------	---	-------------	----------

SPECIAL NET TOTAL S\$ \$ 50.00

LABOUR CHARGE:

1	TO CUT, WELD, PANEL BEAT, STRAIGHTEN, REPLACE DAMAGED PARTS
---	---

ESTIMATE

26/7/2024

INDIA INT'L INSURANCE PTE LTD
64 CECIL STREET
#04-06 IOB BUILDING
SINGAPORE 049711.

MOVA
Automotive Pte Ltd

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314

Vehicle No: SKX1210Y
Vehicle Model: PEOGEOT 3008
Est No: CBMQ24070275
Claims ref:
Accident Date: 19/07/24
In Charge: JUNIOR
Remarks:

Co. Reg. 198904033G
GST Reg. M2-0088864-2

No	Description	Qty	U. Price	Amounts S\$
	& REALIGN AFFECTED AREAS			\$ 1,000.00 400
2	TO PUTTY SPRAY PAINT ON FRONT BUMPER TOP GARNISH, FRONT BONNET, FRONT BUMPER, HEADLAMP LOWER PANEL LH & RH FRONT BUMPER LOWER GARNISH			\$ 1,200.00 450
3	TO CHECK WIRING & ELECTRICAL SYSTEM FOR PROPER FUNCTION			\$ 100.00 30%
4	TO CONDUCT ADAS SYSTEM PROGRAMMING			\$ 380.00 200
	TOTAL LABOUR COST S\$			\$ 2,680.00

Customer's Signature

MOVA AUTOMOTIVE PTE LTD

AMOUNT S\$ \$ 17,094.00
GST @ 9% \$ 1,538.46
AMOUNT DUE S\$ \$ 18,632.46

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4/5 - 84,200/4 days

4 days

P/P

03/09/24

Rey 64 part