

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

MS FIRST CAPITAL INSURANCE LTD
16 RAFFLES QUAY
#42-01 HONG LEONG BUILDING

SINGAPORE 048581

INV No. : SAC2400975
INV Date : 14-10-2024

Reference CD/FCI24070442/Rma3
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SKU 5579Z
Insured Veh. SHA 8041D
Claim No. D24006538MFCT/CCPL
Policy No. D-24101860MFCT
Accident Date 25/07/2024
Inspection Date 01/08/2024

Description	Amount
Third Party Express Settlement	300.00
Sub-Total	300.00
GST (9%)	27.00
Grand Total	327.00

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CD/FCI24070442/Rma3
16 RAFFLES QUAY	Date:	14/10/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	SHA 8041D	Veh. Inspected	SKU 5579Z
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006538MFCT/CCPL	Excess	\$0.00
Assign From	JOANNE YONG	Assign Date	29/07/2024

2. Vehicle Details

Make & Model	NISSAN SYLPHY 1.6 CVT ABS D/AIRBAG 2WD 4DR	C.C	1598
Engine No.	HR16971324B	Year of Reg.	31/07/2015
Chassis No.	MNTBBAB17Z0024281	Colour	GREY
Odometer	130227 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/60 R16	FALKEN	6
L/H Front Tyre	195/60 R16	FALKEN	6
R/H Rear Tyre	195/60 R16	FALKEN	6
L/H Rear Tyre	195/60 R16	FALKEN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	25/07/2024	Inspection Date	01/08/2024
Survey held at	913 BUKIT TIMAH ROAD SINGAPORE 589623		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKU 5579Z

Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	STAY RR BMPR RH (N)	SERVICEABLE	\$50.20	\$0.00
1	STAY RR BMPR LH (N)	SERVICEABLE	\$47.40	\$0.00
2	GROMMET BUMPER @\$3.00 (N)	NECESSARY	\$6.00	\$6.00
1	ENERGY ABSORBER (N)	SERVICEABLE	\$39.00	\$0.00
1	BUMPER REAR (N)	CRACKED	\$858.60	\$858.60
4	CLIPS BUMPER @\$1.50 (N)	NECESSARY	\$6.00	\$6.00
	LESS 20.00%		(\$201.44)	(\$174.12)
			\$805.76	\$696.48
Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SENSOR REVERSE (SN)	SERVICEABLE	\$250.00	\$0.00
1	SUNDRIES (SN)	NECESSARY	\$20.00	\$20.00
			\$270.00	\$20.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	REPAIR END PANEL AND RENEW REAR BUMPER		\$1,290.00	\$430.00
	S/PAINT REAR BUMPER AND END PANEL		\$1,140.00	\$350.00
	R/I REAR REVERSE SENSOR TO ASSIST REPAIR		\$55.00	\$55.00
			\$2,485.00	\$835.00
GRAND TOTAL			\$3,560.76	\$1,551.48
RECOMMENDED COST OF REPAIRS				\$1,551.48
Report Ref No: CD/FCI24070442/Rma3				

MRB

MOHAMMED RASUL BIN MOHD YUNUS

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



PHOTOGRAPHS FOR VEHICLE NO. : SKU 5579Z



PHOTOGRAPHS FOR VEHICLE NO. : SKU 5579Z



PHOTOGRAPHS FOR VEHICLE NO. : SKU 5579Z





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 5 of 5)

PHOTOGRAPHS FOR VEHICLE NO. : SKU 5579Z



PHOTOGRAPHS FOR VEHICLE NO. : SKU 5579Z

