

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/072024/C0311
Date : 23-07-2024
Accident Date : 20-07-2024

Vehicle Details

Make & Model : Toyota LEXUS RX270 AUTO STD
Chassis No : JTJZA11A602403032
Registration No : SKB1018C

S/N	Description	Qty	Amount (\$)
1	DASHBOARD	1.00	de ✓ \$2,400.00
2	DASHBOARD AIRBAG	1.00	act ✓ \$2,700.00
3	STEERING AIRBAG	1.00	act ✓ \$2,100.00
4	DRIVER KNEE AIRBAG	1.00	act ✓ \$2,500.00
5	DRIVE SEATBELT	1.00	act ✓ \$850.00
6	FRONT PASSENGER KNEE AIRBAG	1.00	act ✓ \$1,500.00
7	FRONT PASSENGER SEATBELT	1.00	act ✓ \$850.00
8	REAR SEATBELTS LH	1.00	act ✓ \$950.00
9	REAR SEATBELTS RH	1.00	act ✓ \$950.00
10	AIRBAG ECU	1.00	act ✓ \$800.00
11	HEADLAMP LH	1.00	cur ✓ \$1,900.00
12	FRONT BUMPER	1.00	de ✓ \$650.00
13	FRONT BUMPER RETAINER LH	1.00	de ✓ \$60.00
14	FRONT BUMPER RETAINER RH	1.00	ann ✓ \$60.00
15	FRONT BUMPER DIFFUSER LH	1.00	aut ✓ \$110.00
16	FRONT BUMPER DIFFUSER RH	1.00	aut ✓ \$110.00
17	FRONT BUMPER UNDERCOVER	1.00	th ✓ \$120.00
18	FRONT GRILLE WITH CHROME	1.00	cur ✓ \$620.00
19	FRONT GRILLE LOGO BASE	1.00	dis ✓ \$50.00
20	FRONT GRILLE CHROME LOGO	1.00	cur ✓ \$60.00
21	FRONT FENDER LH	1.00	bt ✓ \$750.00
22	FRONT FENDER RH	1.00	bt ✓ \$750.00
23	FRONT FENDER INNERSHIELD LH	1.00	de ✓ \$280.00
24	FRONT FENDER INNERSHIELD RH	1.00	mi ✓ \$280.00
25	FRONT FENDER INNERSHIELD CLIPS LH @\$2.00/PC	10.00	ut ✓ \$20.00
26	FRONT FENDER INNERSHIELD CLIPS RH @\$2.00/PC	10.00	cur ✓ \$20.00
27	SIDE SKIRT LH	1.00	dis ✓ \$480.00
28	SIDE SKIRT RH	1.00	mi ✓ \$480.00
29	SIDE MIRROR LH	1.00	dis ✓ \$1,200.00
30	SIDE MIRROR RH	1.00	dis ✓ \$1,200.00
31	SIDE MIRROR GLASS LH	1.00	ora ✓ \$400.00

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

32	SIDE MIRROR GLASS RH	1.00	dis	\$400.00
33	SIDE MIRROR SIGNAL LAMP LH	1.00	cut	\$110.00
34	SIDE MIRROR SIGNAL LAMP RH	1.00	ant	\$110.00
35	SIDE MIRROR COVER LH	1.00	cut	\$80.00
36	SIDE MIRROR COVER RH	1.00	cut	\$80.00
37	FRONT DOOR LH	1.00	bt	\$1,300.00
38	FRONT DOOR RH	1.00	bt	\$1,300.00
39	FRONT DOOR BOTTOM PROTECTOR WITH CHROME AND LOGO LH	1.00	de	\$220.00
40	FRONT DOOR BOTTOM PROTECTOR WITH CHROME AND LOGO RH	1.00	mis	\$220.00
41	FRONT DOOR HINGE TOP AND BOTTOM LH	1.00	bt	\$50.00
42	FRONT DOOR STOPPER LH	1.00	new?	\$160.00
43	FRONT DOOR HANDLE LH (BIG)	1.00	buo	\$270.00
44	FRONT DOOR HANDLE LH (SMALL)	1.00	dis	\$30.00
45	FRONT DOOR WINDOW TOP GARNISH LH	1.00	dis?	\$80.00
46	FRONT DOOR WINDOW BOTTOM GARNISH LH	1.00	dis?	\$110.00
47	FRONT DOOR INNER TRIM BOARD LH	1.00	de?	\$800.00
48	FRONT DOOR POWER WINDOW SWITCH LH	1.00	un x	\$120.00
49	FRONT DOOR POWER WINDOW MOTOR LH	1.00	un x	\$240.00
50	FRONT DOOR POWER WINDOW GEAR LH	1.00	bt?	\$230.00
51	REAR DOOR LH	1.00	bt	\$1,100.00
52	REAR DOOR BOTTOM PROTECTOR WITH CHROME GARNISH LH	1.00	mis	\$220.00
53	REAR DOOR HANDLE LH (BIG)	1.00	cut	\$300.00
54	REAR DOOR HINGE TOP AND BOTTOM LH	1.00	bt?	\$70.00
55	REAR DOOR STOPPER LH	1.00	un?	\$210.00
56	REAR DOOR INNER TRIM BOARD LH	1.00	de?	\$750.00
57	REAR DOOR WINDOW TOP GARNISH LH	1.00	dis?	\$80.00
58	REAR DOOR WINDOW BOTTOM GARNISH LH	1.00	dis?	\$120.00
59	REAR DOOR POWER WINDOW SWITCH LH	1.00	x	\$120.00
60	REAR DOOR POWER WINDOW MOTOR LH	1.00	dis?	\$220.00
61	REAR DOOR POWER WINDOW GEAR LH	1.00	bt?	\$210.00
62	FRONT ABSORBER LH	1.00	bt	\$550.00
63	FRONT ABSORBER RH	1.00	bt	\$550.00
64	FRONT ABSORBER MOUNTING LH	1.00	ne?	\$80.00
65	FRONT ABSORBER MOUNTING RH	1.00	bt	\$80.00
66	FRONT ABSORBER DUST COVER LH	1.00	un?	\$40.00
67	FRONT ABSORBER DUST COVER RH	1.00	dis?	\$40.00
68	FRONT ABSORBER STOPPER LH	1.00	un?	\$20.00
69	FRONT ABSORBER STOPPER RH	1.00	un?	\$20.00
70	FRONT ABSORBER BEARING LH	1.00	bt?	\$80.00
71	FRONT ABSORBER BEARING RH	1.00	bt	\$80.00
72	FRONT LOWER ARM LH	1.00	bt?	\$300.00
73	FRONT LOWER ARM RH	1.00	bt	\$300.00
74	FRONT LOWER ARM BALL JOINT LH	1.00	bt	\$120.00
75	FRONT LOWER ARM BALL JOINT RH	1.00	bt?	\$120.00

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

76	FRONT KNUCKLE LH
77	FRONT KNUCKLE RH
78	FRONT KNUCKLE BEARING LH
79	FRONT KNUCKLE BEARING RH
80	DRIVESHAFT LH
81	DRIVESHAFT RH
82	STEERING RACK
83	FRONT ANTI ROLL BAR
84	FRONT LINKAGE LH
85	FRONT LINKAGE RH
86	FRONT CROSSMEMBER
87	ENGINE OIL SUMP
88	ENGINE UNDERCOVER CENTER
89	ENGINE MOUNTING LH
90	ENGINE MOUNTING RH
91	GEARBOX MOUNTING
92	AUTO OIL SUMP
93	EXHAUST PIPE (DOWN PIPE)
94	EXHAUST MUFFLER
95	REAR ABSORBER LH
96	REAR ABSORBER RH
97	REAR LOWER ARM LH
98	REAR LOWER ARM RH
99	REAR SIDE ARM LH
100	REAR SIDE ARM RH
101	REAR CONTROL ARM LH
102	REAR CONTROL ARM RH
103	REAR KNUCKLE LH
104	REAR KNUCKLE RH
105	REAR KNUCKLE BEARING LH
106	REAR KNUCKLE BEARING RH
107	REAR CROSSMEMBER
108	RIMS @\$600.00/PC

1.00	bt	\$450.00
1.00	bt	\$450.00
1.00	bt	\$210.00
1.00	bt	\$210.00
1.00	bt	\$600.00
1.00	bt	\$600.00
1.00	bt	\$1,200.00
1.00	bt	\$280.00
1.00	bt	\$110.00
1.00	bt	\$110.00
1.00	bt	\$1,800.00
1.00	dl	\$220.00
1.00	dl	\$160.00
1.00	dl	\$140.00
1.00	dl	\$320.00
1.00	dl	\$330.00
1.00	un	\$140.00
1.00	dl	\$450.00
1.00	dl	\$1,200.00
1.00	bt	\$150.00
1.00	bt	\$150.00
1.00	bt	\$310.00
1.00	bt	\$310.00
1.00	bt	\$210.00
1.00	bt	\$210.00
1.00	bt	\$240.00
1.00	bt	\$240.00
1.00	bt	\$620.00
1.00	bt	\$620.00
1.00	bt	\$670.00
1.00	bt	\$670.00
1.00	bt	\$1,400.00
4.00	dl	\$2,400.00

\$54,070.00

Margin: 10% \$5,407.00

4.00	80%	\$59,477.00
1.00	at	\$1,120.00
1.00	un	\$40.00
1.00	un	\$80.00
1.00	un	\$150.00
1.00	un	\$150.00
1.00	250	\$380.00

109	TYRES @\$280.00/PC
110	FRONT NUMBER CARPLATE WITH HOLDER
111	COOLANT
112	TO CHECK WHEEL ALIGNMENT
113	TO REMOVE/ TOP UP AIRCON GAS
114	TO RESET AIRBAG SYSTEMS

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

- 115 TO REMOVE/ REPLACE DASHBOARD
- 116 TO REMOVE/ REPLACE UNDERCARRIAGE
- 117 TO REPAIR DAMAGE
- 118 TO SPRAY PAINTING

Photo	1.00	220.	\$380.00
	1.00	300✓	\$480.00
	1.00	1200	\$1,400.00
	1.00	1400	\$1,600.00

→ Remove / Re Engine - \$2001

Subtotal w/o GST:

\$65,257.00

Tanfhi 97495749 / 62563561
Not Authorise 29/7/24 2415p-
Ex \$4500
tanfhi@khand.com.
12 days
L/S Reony after repair
As

Issued by Melvin

This is a computer-generated document. No signature is required.