



Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : ECICS LIMITED
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

Claim Details

Case Ref. No. : OD/072024/C0311
Date : 23-07-2024
Accident Date : 20-07-2024

Vehicle Details

Make & Model : Toyota LEXUS RX270 AUTO STD
Chassis No : JTJZA11A602403032
Registration No : SKB1018C

S/N	Description	Qty	Amount (\$S)
1	DASHBOARD	1.00	de ✓ \$2,400.00
2	DASHBOARD AIRBAG	1.00	act ✓ \$2,700.00
3	STEERING AIRBAG	1.00	act ✓ \$2,100.00
4	DRIVER KNEE AIRBAG	1.00	act ✓ \$2,500.00
5	DRIVE SEATBELT	1.00	act ✓ \$850.00
6	FRONT PASSENGER KNEE AIRBAG	1.00	act ✓ \$1,500.00
7	FRONT PASSENGER SEATBELT	1.00	act ✓ \$850.00
8	REAR SEATBELTS LH	1.00	act ✓ \$950.00
9	REAR SEATBELTS RH	1.00	act ✓ \$950.00
10	AIRBAG ECU	1.00	act ✓ \$800.00
11	HEADLAMP LH	1.00	env ✓ \$1,900.00
12	FRONT BUMPER	1.00	de ✓ \$650.00
13	FRONT BUMPER RETAINER LH	1.00	de ✓ \$60.00
14	FRONT BUMPER RETAINER RH	1.00	R ✓ \$60.00x
15	FRONT BUMPER DIFFUSER LH	1.00	act ✓ \$110.00
16	FRONT BUMPER DIFFUSER RH	1.00	act ✓ \$110.00
17	FRONT BUMPER UNDERCOVER	1.00	th ✓ \$120.00
18	FRONT GRILLE WITH CHROME	1.00	env ✓ \$620.00
19	FRONT GRILLE LOGO BASE	1.00	dis ✓ \$50.00
20	FRONT GRILLE CHROME LOGO	1.00	env ✓ \$60.00
21	FRONT FENDER LH	1.00	bt ✓ \$750.00
22	FRONT FENDER RH	1.00	bt ✓ \$750.00
23	FRONT FENDER INNERSHIELD LH	1.00	de ✓ \$280.00
24	FRONT FENDER INNERSHIELD RH	1.00	mi ✓ \$280.00
25	FRONT FENDER INNERSHIELD CLIPS LH @\$2.00/PC	10.00	mi ✓ \$20.00
26	FRONT FENDER INNERSHIELD CLIPS RH @\$2.00/PC	10.00	mi ✓ \$20.00
27	SIDE SKIRT LH	1.00	dis ✓ \$480.00
28	SIDE SKIRT RH	1.00	mi ✓ \$480.00
29	SIDE MIRROR LH	1.00	dis ✓ \$1,200.00
30	SIDE MIRROR RH	1.00	dis ✓ \$1,200.00
31	SIDE MIRROR GLASS LH	1.00	ora ✓ \$400.00

32	SIDE MIRROR GLASS RH	1.00	del	\$400.00
33	SIDE MIRROR SIGNAL LAMP LH	1.00	cut	\$110.00
34	SIDE MIRROR SIGNAL LAMP RH	1.00	ant	\$110.00
35	SIDE MIRROR COVER LH	1.00	cut	\$80.00
36	SIDE MIRROR COVER RH	1.00	cut	\$80.00
37	FRONT DOOR LH	1.00	bt	\$1,300.00
38	FRONT DOOR RH	1.00	bt	\$1,300.00
39	FRONT DOOR BOTTOM PROTECTOR WITH CHROME AND LOGO LH	1.00	de	\$220.00
40	FRONT DOOR BOTTOM PROTECTOR WITH CHROME AND LOGO RH	1.00	mis	\$220.00
41	FRONT DOOR HINGE TOP AND BOTTOM LH	1.00	38	\$50.00
42	FRONT DOOR STOPPER LH	1.00	new?	\$160.00
43	FRONT DOOR HANDLE LH (BIG)	1.00	bno	\$270.00
44	FRONT DOOR HANDLE LH (SMALL)	1.00	dis	\$30.00
45	FRONT DOOR WINDOW TOP GARNISH LH	1.00	dis?	\$80.00
46	FRONT DOOR WINDOW BOTTOM GARNISH LH	1.00	dis?	\$110.00
47	FRONT DOOR INNER TRIM BOARD LH	1.00	de?	\$800.00
48	FRONT DOOR POWER WINDOW SWITCH LH	1.00	x	\$120.00 x
49	FRONT DOOR POWER WINDOW MOTOR LH	1.00	x	\$240.00 x
50	FRONT DOOR POWER WINDOW GEAR LH	1.00	bt?	\$230.00
51	REAR DOOR LH	1.00	bt	\$1,100.00
52	REAR DOOR BOTTOM PROTECTOR WITH CHROME GARNISH LH	1.00	mis	\$220.00
53	REAR DOOR HANDLE LH (BIG)	1.00	cut	\$300.00
54	REAR DOOR HINGE TOP AND BOTTOM LH	1.00	bt?	\$70.00
55	REAR DOOR STOPPER LH	1.00	mis?	\$210.00
56	REAR DOOR INNER TRIM BOARD LH	1.00	de?	\$750.00
57	REAR DOOR WINDOW TOP GARNISH LH	1.00	dis?	\$80.00
58	REAR DOOR WINDOW BOTTOM GARNISH LH	1.00	dis?	\$120.00
59	REAR DOOR POWER WINDOW SWITCH LH	1.00	x	\$120.00
60	REAR DOOR POWER WINDOW MOTOR LH	1.00	dis?	\$220.00
61	REAR DOOR POWER WINDOW GEAR LH	1.00	bt?	\$210.00
62	FRONT ABSORBER LH	1.00	bt	\$550.00
63	FRONT ABSORBER RH	1.00	bt	\$550.00
64	FRONT ABSORBER MOUNTING LH	1.00	new?	\$80.00
65	FRONT ABSORBER MOUNTING RH	1.00	bt	\$80.00
66	FRONT ABSORBER DUST COVER LH	1.00	mis?	\$40.00
67	FRONT ABSORBER DUST COVER RH	1.00	dis?	\$40.00
68	FRONT ABSORBER STOPPER LH	1.00	mis?	\$20.00
69	FRONT ABSORBER STOPPER RH	1.00	mis?	\$20.00
70	FRONT ABSORBER BEARING LH	1.00	bt?	\$80.00
71	FRONT ABSORBER BEARING RH	1.00	bt	\$80.00
72	FRONT LOWER ARM LH	1.00	bt?	\$300.00
73	FRONT LOWER ARM RH	1.00	bt	\$300.00
74	FRONT LOWER ARM BALL JOINT LH	1.00	bt	\$120.00
75	FRONT LOWER ARM BALL JOINT RH	1.00	bt?	\$120.00

VIN'S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

76	FRONT KNUCKLE LH	1.00	bt	\$450.00
77	FRONT KNUCKLE RH	1.00	bt	\$450.00
78	FRONT KNUCKLE BEARING LH	1.00	bt	\$210.00
79	FRONT KNUCKLE BEARING RH	1.00	bt	\$210.00
80	DRIVESHAFT LH	1.00	bt	\$600.00
81	DRIVESHAFT RH	1.00	bt	\$600.00
82	STEERING RACK	1.00	bt	\$1,200.00
83	FRONT ANTI ROLL BAR	1.00	bt	\$280.00
84	FRONT LINKAGE LH	1.00	bt	\$110.00
85	FRONT LINKAGE RH	1.00	bt	\$110.00
86	FRONT CROSSMEMBER	1.00	bt	\$1,800.00
87	ENGINE OIL SUMP	1.00	dt	\$220.00
88	ENGINE UNDERCOVER CENTER	1.00	dt	\$160.00
89	ENGINE MOUNTING LH	1.00	dt	\$140.00
90	ENGINE MOUNTING RH	1.00	dt	\$320.00
91	GEARBOX MOUNTING	1.00	dt	\$330.00
92	AUTO OIL SUMP	1.00	X	\$140.00 X
93	EXHAUST PIPE (DOWN PIPE)	1.00	dt	\$450.00
94	EXHAUST MUFFLER	1.00	dt	\$1,200.00
95	REAR ABSORBER LH	1.00	bt	\$150.00
96	REAR ABSORBER RH	1.00	bt	\$150.00
97	REAR LOWER ARM LH	1.00	bt	\$310.00
98	REAR LOWER ARM RH	1.00	bt	\$310.00
99	REAR SIDE ARM LH	1.00	bt	\$210.00
100	REAR SIDE ARM RH	1.00	bt	\$210.00
101	REAR CONTROL ARM LH	1.00	bt	\$240.00
102	REAR CONTROL ARM RH	1.00	bt	\$240.00
103	REAR KNUCKLE LH	1.00	bt	\$620.00
104	REAR KNUCKLE RH	1.00	bt	\$620.00
105	REAR KNUCKLE BEARING LH	1.00	bt	\$670.00
106	REAR KNUCKLE BEARING RH	1.00	bt	\$670.00
107	REAR CROSSMEMBER	1.00	dt	\$1,400.00
108	RIMS @\$600.00/PC	4.00	dt	\$2,400.00
				\$54,070.00
				Margin: 10%
				\$5,407.00
109	TYRES @\$280.00/PC	4.00	80%	\$1,120.00
110	FRONT NUMBER CARPLATE WITH HOLDER	1.00	dt	\$40.00
111	COOLANT	1.00	dt	\$50.00
112	TO CHECK WHEEL ALIGNMENT	1.00	dt	\$150.00
113	TO REMOVE/ TOP UP AIRCON GAS	1.00	dt	\$150.00
114	TO RESET AIRBAG SYSTEMS	1.00	250	\$380.00

VIN S

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Authority
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

- 115 TO REMOVE/ REPLACE DASHBOARD
- 116 TO REMOVE/ REPLACE UNDERCARRIAGE
- 117 TO REPAIR DAMAGE
- 118 TO SPRAY PAINTING

	1.00	220	\$380.00
Photo	1.00	300✓	\$480.00
	1.00	1200	\$1,400.00
	1.00	1400	\$1,600.00

→ Remove / Re Engine - \$200

Subtotal w/o GST:

\$65,257.00

Tanfkin 97495749 / 62563561
Not Authorise 29/7/24 R4157-
Ex \$4500
tanfkin@khando.com
12 days
L/S Pending after repair
As

$$P = \$53,510 + 10\% = 58,861$$

$$S/N = \$792$$

$$L = \$3,800$$

$$T = \$63,453$$

$$-20\% L/S = \$50,762.40$$

Issued by Melvin

This is a computer-generated document. No signature is required.