

TWIN WHEELS AUTO TRADING ENTERPRISE

38 Woodlands Industrial Park E1 #03-14

Singapore 757700

TEL: 6457 0410 / 6765 2616

EMAIL: twinauto@singnet.com.sg

Date :

ATTN: MOTOR CLAIM DEPARTMENT

INSURED: MT SINGAPORE CAR RENTAL PTE LTD

H/P: 6765 2616

Dear Sirs / Madam,

Accident Claim for Vehicle No. SMG 7274 P, Involving Vehicle No. GBF 6463 C.

Accident on 27/07/2024 at 14:15pm along Ritz Mansions, 346 Balestier Road (S) 329776.

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BOOT LID / 00	1PC	\$ 1,099.80 ✓
2	REAR BOOT LID LOCK ? / ST/pressed	1PC	\$ 236.20 ✓
3	REAR BOOT LID EMBLEM x n	1PC	\$ 60.60
4	REAR BOOT LID HANDLE 3/4 (chrome) / CRA	1PC	\$ 380.00 ✓
5	REAR BOOT LID LAMP x n	2PCS	\$ 1,100.80
6	REAR BOOT LID W/S MOULDING / CRA	1PC	\$ 120 / 260.00
7	REAR BUMPER / BR	1PC	\$ 758.50 ✓
8	REAR LAMP x n	2PCS	\$ 1,080.40
9	REAR BOOT LID HANDLE x n	1PC	\$ 380.00
	TOTAL LIST PRICE		\$ 5,356.30
	LESS 10% 20%		\$ (535.63)
	TOTAL AMOUNT		\$ 4,820.67

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	RESERVE SENSOR / Sparked	1PC	\$ 200 / 280.00
2	BOOT LID LOGO SUTTLE / n/c	1PC	\$ 55.90 ✓
3	BOOT LID LOGO HYBRID / n/c	1PC	\$ 65.00 ✓
5	NUMBER PLATE x n	1PC	\$ 30.00
6	W/S SEALAND / n/c	1PC	\$ 50 / 80.00
	TOTAL SPECIAL NETT PRICE		\$ 510.90
	TOTAL AMOUNT		\$ 5,331.57

	LABOUR :			
1	LABOUR TO SPRAY PAINT	\$	500	750.00
2	LABOUR TO PANEL BEATING	\$	400	600.00
3	TO DISMANTLE AND ASSEMBLE REAR W/H	\$	120	180.00
	TOTAL LABOUR	\$		1,490.00
	TOTAL AMOUNT	\$		6,821.57

THANK YOU

FROM:

Twin Wheels Auto Trading Enterprise
TEL : 6765 2616

Sen (LKK)
31/7/74 1:30pm
m n
L/H
by AL by
4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: