

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 01 Aug 2024

Preliminary Advice

Insured Vehicle No	: GBF6463C	Accident Date	: 27/07/2024
TP Vehicle No	: SMG7274P	Assignment Date	: 29/07/2024
Make	: HONDA SHUTTLE HYBRID	Est. Duration of Repair	: 4
Date of Inspection	: 31/07/2024		
Inspection At	: TWIN WHEEL AUTO TRADING ENTERPRISE (HQ) 38 WOODLANDS ROAD, #03-14 WOODLANDS INDUSTRIAL PARK E1 SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,821.57
Revised Amount	:S\$	3,466.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,466.50

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
 () The vehicle is not economical for repair
 () Part-by-Part repair
 () Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.
 Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.