

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

TP Budget Direct.
Xiao Chen.

MK CARS LEASING PTE LTD
210 TURF CLUB ROAD #0B-46 THE
GRANDSTAND
SINGAPORE 287995

TAX INVOICE

Repair Code : CLM16374

Date in : 29/07/2024

Vehicle Num. : SLW9477K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261624/LEB5961641

Contact : 82230806 89001719

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Deled</i>	1	762.70	762.70 <i>-</i>
REAR BUMPER LOWER COVER <i>new Deled</i>	1	250.00	250.00 <i>✓</i>
REAR BUMPER REFLECTOR L/R <i>LH canel d</i>	2	141.10	282.20 <i>141.10</i>
REAR BUMPER SIDE L/R <i>new RH torn</i>	2	195.00	390.00 <i>+ 155</i>
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	23.00	46.00 <i>+</i>
REAR END PANEL <i>Deled</i>	1	415.60	415.60 <i>✓</i>
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	60.10	60.10 <i>+</i>
REAR END PANEL BUZZLE SENSOR <i>canel d</i>	1	85.20	85.20 <i>✓</i>
REAR END PANEL INNER TOP GARNISH <i>Deled</i>	1	98.00	98.00 <i>✓</i>
REAR EXHAUST CHROME TAIL PIPE <i>cut</i>	1	135.00	135.00 <i>✓</i>
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	16.50	33.00 <i>+</i>
REAR EXHAUST SILENCER BOX <i>new</i>	1	517.70	517.70 <i>+</i>
REAR FENDER INNER TRIM GARNISH L/R <i>new</i>	2	295.00	590.00 <i>+</i>
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH <i>Deled</i>	1	485.30	485.30 <i>✓</i>
X REAR FLOOR PANEL INNER TOP BOARD COVER <i>new</i>	1	430.30	430.30 <i>+</i>
REAR RH FENDER ARCH GARNISH <i>new RH canel d</i>	1	195.00	195.00 <i>✓</i>
REAR TAILGATE <i>Deled</i>	1	953.30	953.30 <i>-</i>
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	75.80	75.80 <i>✓</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MK CARS LEASING PTE LTD
210 TURF CLUB ROAD #0B-46 THE
GRANDSTAND
SINGAPORE 287995

TAX INVOICE

Repair Code : CLM16374

Date in : 29/07/2024

Vehicle Num. : SLW9477K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261624/LEB5961641

Contact : 82230806 89001719

REAR TAILGATE 'VEZEL' EMBLEM <i>new</i>	1	56.20	56.20 ✓
REAR TAILGATE HINGES L/R <i>new</i>	2	50.00	100.00 ✗
REAR TAILGATE INNER PULL GARNISH <i>new</i>	1	27.50	27.50 ✗
REAR TAILGATE INNER TRIM GARNISH <i>could</i>	1	153.40	153.40 ✓
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	180.00	180.00 ✓
REAR TAILGATE MECHANISM LOCK STRIKER <i>new</i>	1	27.50	27.50 ✗
REAR TAILGATE RH REFLECTOR <i>new</i>	1	413.20	413.20 ✗
REAR TAILGATE RUBBER GUIDE STOPPER L/R <i>new</i>	2	18.50	37.00 ↓
REAR TAILGATE WEATHER STRIP <i>lit</i>	1	96.80	96.80 ✓
REAR TAILGATE WINDSCREEN INNER SEAL <i>new</i>	2	50.00	100.00 40
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	2	50.00	100.00 30
Subtotal before discount			7,096.80
Percentage discount 20%			1,419.36
Sub-total 1			5,677.44
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	80.00 30
REAR BUMPER REVERSE SENSOR <i>new</i>	1	280.00	280.00 20
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	30.00	30.00 20
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET <i>new</i>	2	30.00	60.00 ✗

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MK CARS LEASING PTE LTD
210 TURF CLUB ROAD #0B-46 THE
GRANDSTAND
SINGAPORE 287995

TAX INVOICE

Repair Code : CLM16374

Date in : 29/07/2024

Vehicle Num. : SLW9477K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261624/LEB5961641

Contact : 82230806 89001719

REAR NUMBER PLATE <i>me m</i>	1	25.00	25.00 +
REAR NUMBER PLATE HOLDER <i>me m</i>	1	50.00	50.00 +
REAR RH FENDER ARCH GARNISH CLIPS - SET <i>me m</i>	1	40.00	40.00 +
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET <i>me m</i>	1	50.00	50.00 <i>50</i>
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>me m</i>	1	40.00	40.00 +
REAR TAILGATE SPOILER CLIPS - SET <i>me m</i>	1	50.00	50.00 +
REAR TAILGATE WINDSCREEN SEALANT <i>me</i>	1	60.00	60.00 ✓
Subtotal before discount			765.00
Percentage discount 0%			0.00
Sub-total 2			765.00
Parts-total			6,442.44

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

80.00 ✓
150.00 *120*
100.00 *60*
1,000.00 *600*
100.00 X
1,000.00 *600*
120.00 *60*

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

MK CARS LEASING PTE LTD
210 TURF CLUB ROAD #0B-46 THE
GRANDSTAND
SINGAPORE 287995

Contact : 82230806 89001719

TAX INVOICE

Repair Code : CLM16374

Date in : 29/07/2024

Vehicle Num. : SLW9477K

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31261624/LEB5961641

To remove, reinstall tailgate mechanism and check for function

Labour Total	1580	80.00
		2,630.00
Parts & Labour Total		9,072.44

*** This is a computer-generated document which requires no signature.***

page 4

Adrian L
w/c 30/07/24
ru of 4p 06
total: 5398.72
L/S : 4.3K ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: