

JL Perfect Autowork Pte Ltd
Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 24.07.2024

TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SLS5148H**
MODEL : **MERCEDES CLA180**
DATE OF ACCIDENT : 24.07.2024
TIME OF ACCIDENT : 11:50 HOURS

2017
Yan. WDD1173422X496882

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SIDE SKIRT <i>Disp new</i>	2	\$ 1,486.00	\$ 2,972.00
2	REAR DOOR RH <i>Dented</i>	1	\$ 2,452.00	\$ 2,452.00
3	REAR DOOR CHROME MOULDING RH <i>new</i>	1	\$ 415.00	\$ 415.00
4	REAR DOOR FRAME WEATHERSTRIP RH <i>new</i>	1	\$ 255.00	\$ 255.00
5	REAR DOOR HINGE RH <i>new</i>	2	\$ 196.00	\$ 392.00
6	REAR DOOR INNER LOCK RH <i>new</i>	1	\$ 805.00	\$ 805.00
7	REAR DOOR INNER TRIM RH <i>new</i>	1	\$ 1,723.00	\$ 1,723.00
8	REAR DOOR LOCK CATCHER RH <i>new</i>	1	\$ 70.00	\$ 70.00
9	REAR DOOR WEATHER STRIP RH <i>new</i>	1	\$ 409.00	\$ 409.00
10	REAR DOOR WATER SHIELD RH <i>new</i>	1	\$ 280.00	\$ 280.00
11	REAR DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 745.00	\$ 745.00
12	REAR DOOR REGULATOR RH <i>new</i>	1	\$ 884.00	\$ 884.00
13	REAR DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 138.00	\$ 138.00
14	REAR DOOR SPEAKER RH <i>new</i>	1	\$ 188.00	\$ 188.00
15	REAR DOOR FRAME STEP GARNISH RH <i>new</i>	1	\$ 180.00	\$ 180.00
16	REAR DOOR OUTER HANDLE RH <i>new</i>	1	\$ 631.00	\$ 631.00
17	REAR SEAT SIDE GARNISH RH <i>new</i>	1	\$ 122.00	\$ 122.00
18	REAR FENDER RH <i>Dented</i>	1	\$ 3,217.00	\$ 3,217.00
19	REAR FENDER INNER COWLING <i>new</i>	2	\$ 243.00	\$ 486.00
20	REAR WINDSCREEN GLASS C/W MOULDING <i>new</i>	1	\$ 1,308.00	\$ 1,308.00
21	REAR WHEEL SPORT RIM <i>new</i>	2	\$ 2,100.00	\$ 2,100.00

new/old

2010
549.
1180
310
695
391
2290
850(SN)

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS5148H**
 MODEL : **MERCEDES CLA180**
 DATE OF ACCIDENT : 24.07.2024
 TIME OF ACCIDENT : 11:50 HOURS

22	REAR ABS SENSOR <i>3pc</i>	2	\$	390.00	\$	390.00	+
23	REAR SHOCK ABSORBER <i>3pc</i>	2	\$	568.00	\$	670.00	+
24	REAR LOWER ARM <i>Best</i>	2	\$	388.00 <i>540</i>	\$	540.00	✓
25	REAR KNUCKLE ARM <i>Best</i>	2	\$	1,509.00	\$	<i>1509</i>	✓
26	REAR WHEEL HUB WITH BEARING <i>Best</i>	2	\$	515.00	\$	<i>515</i>	✓
27	REAR UPPER ARM <i>Best</i>	2	\$	571.00	\$	<i>571</i>	+
28	REAR ADJUSTABLE ARM <i>Best</i>	2	\$	420.00	\$	420.00	+
29	REAR CONTROL ARM <i>Best</i>	2	\$	219.00	\$	<i>219</i>	+
30	REAR LINKAGE <i>3pc</i>	2	\$	105.00	\$	<i>105</i>	+
31	REAR CROSSMEMBER <i>3pc</i>	1	\$	3,648.00	\$	<i>3648</i>	+
32	REAR BUMPER <i>Repair</i>	1	\$	2,008.00	\$	2,008.00	+
33	REAR BUMPER CORNER BRACKET <i>2</i>	2	\$	187.00	\$	374.00	+
34	REAR BUMPER SIDE RETAINER <i>2</i>	2	\$	127.00	\$	254.00	+
35	REAR BUMPER BRACKET (CENTER) <i>1pc</i>	1	\$	345.00	\$	345.00	+
36	REVERSE SENSOR RH <i>1pc</i>	1	\$	217.00	\$	217.00	+
37	REVERSE SENSOR HOLDER <i>1pc</i>	4	\$	65.00	\$	260.00	+
38	TAILLAMP <i>2</i>	2	\$	945.00	\$	1,890.00	+

11577 3-N:80
 10419.30
 TOTAL PRICE \$ 29,650.00
 LESS 10% \$ 2,965.00
 SUB TOTAL PRICE \$ 26,685.00

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	SIDE SKIRT CLIP (SET) <i>new</i>	1	\$ 120.00	\$ 120.00
2	REAR BUMPER CLIP (SET) <i>new</i>	1	\$ 80.00	\$ 80.00
3	REAR DOOR SEALANT RH <i>new</i>	1	\$ 150.00	\$ 150.00
4	REAR DOOR INNER TRIM CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
5	REAR DOOR FRAME STEP GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
6	REAR SEAT SIDE GARNISH CLIP RH (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
7	REAR WINDSCREEN INNER SEAL <i>3pc</i>	1	\$ 80.00	\$ 80.00
8	REAR WINDSCREEN SEALANT <i>3pc</i>	1	\$ 60.00	\$ 60.00
9	REAR WINDSCREEN GLASS SOLAR FILM <i>new</i>	1	\$ 650.00	\$ 650.00
10	TAIL LAMP CLIP (SET) <i>2 Not</i>	1	\$ 30.00	\$ 30.00
11	WHEEL TYRE <i>Not</i>	4	\$ 680.00	\$ 2,720.00
12	WHEEL CAP (SET) <i>1pc</i>	1	\$ 120.00	\$ 120.00

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS5148H**
 MODEL : **MERCEDES CLA180**
 DATE OF ACCIDENT : 24.07.2024
 TIME OF ACCIDENT : 11:50 HOURS

13	BRAKE OIL <i>Abel New</i>	1	\$ 60.00	\$ 60.00
----	---------------------------	---	----------	----------

120

TOTAL \$ 4,270.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 650.00	<i>30</i>
5	FOUR WHEEL ALIGNMNET	\$ 180.00	<i>80</i>
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	<i>X</i>
7	TRANFER REAR DOOR MECHANISM	\$ 80.00	<i>40</i>
8	REMOVE & REINSTALL REAR WINDOW GLASS RH	\$ 80.00	<i>40</i>
9	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
10	REMOVE & REINSTALL & RESET REVERSE SENSOR	\$ 200.00	<i>X</i>
11	REMOVE & REFIX REAR WINSCREEN	\$ 150.00	<i>120</i>
12	CONDUCT WATER LEAKAGE TEST	\$ 100.00	<i>X</i>

To remove rear undercarn'ge ~~380~~ 220.

To perform wheel alignment ~~150~~ 80.

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLS5148H**
 MODEL : **MERCEDES CLA180**
 DATE OF ACCIDENT : 24.07.2024
 TIME OF ACCIDENT : 11:50 HOURS

13	REMOVE AND REFIX REAR REVERSE SENSOR	\$ 80.00	+
14	RESET ABS LIGHT	\$ 600.00	+
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 850.00	180

2210

TOTAL \$ 6,990.00

TOTAL PARTS COST : \$ 30,955.00
 TOTAL LABOUR COST : \$ 6,990.00
 TOTAL REPAIR COST : \$ 37,945.00

Admin L
 2/s 25/07/24

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

08 Days

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

Total: 13549.30
 L/S: 10.8K

10850

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: