



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24070450/Unp3
16 RAFFLES QUAY	Date:	02/08/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHB 4673B	Veh. Inspected	SGS 6622H
Policy No.	D-24101860MFCT	Coverage	0
Claim No.	D24006539MFCT	Excess	\$0.00
Assign From	-	Assign Date	29/07/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200 (A)	C.C	1991
Engine No.	27492031682132	Year of Reg.	31/01/2019
Chassis No.	WDD2130422A567430	Colour	BLACK
Odometer	95840 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/45R18	PIRELLI	7
L/H Front Tyre	245/45R18	PIRELLI	7
R/H Rear Tyre	245/45R18	PIRELLI	7
L/H Rear Tyre	245/45R18	PIRELLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/07/2024	Inspection Date	31/07/2024
Survey held at	CARSMITH PTE LTD - 8 KAKI BUKIT AVE 4 #04-35 SINGAPORE 415875		

5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT.
B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days