



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 280724

Date: 28.07.2024

Lim Joon Kang
13 Verde Place
Singapore 688622.

Mercedes Benz E200 CGI

Estimate Repair Cost for Vehicle Reg. No: SKQ 8303 D

		Nett Price	
1 Pc. Rear Bumper <i>crack</i>		1,990.00	✓ 1685.00
1 Pc. Rear Bumper Centre Chrome Moulding <i>distorted</i>		499.00	✓ 323.00
2 Pcs. Rear Bumper Side Chrome Moulding <i>new</i>	@ 398.00	796.00	✓ 278.00
1 Pc. Rear Bumper Towing Cover <i>SVU</i>		91.00	X
2 Pcs. Rear Bumper Corner Garnish <i>HH</i>	@ 256.00	512.00	X
2 Pcs. Rear Bumper Retainer <i>broken</i>	@ 289.00	578.00	✓ 172.00
1 Pc. Rear Bumper Inner Centre Garnish <i>HH</i>		498.00	X
1 Pc. Rear Bumper Harness Wire <i>HH</i>		532.10	X
1 Pc. Rear Bumper Exhaust Chrome <i>HH</i>		480.00	X
2 Pcs. Rear Bumper Exhaust Bracket <i>HH</i>	@ 110.00	220.00	X
2 Pcs. Rear Bumper Lower Bracket <i>HH</i>	@ 126.00	252.00	X
10 Pcs. Rear Bumper Clips <i>new</i>	@ 8.00	80.00	201-SH
10 Pcs. Rear Bumper Rebit <i>HH</i>	@ 10.00	100.00	X
1 Pc. Rear Bumper Reinforcement <i>Double</i>		1,089.00	✓ 678.00
2 Pcs. Rear Bumper Corner Top Garnish <i>HH</i>	@ 205.00	410.00	X
8 Pcs. Rear Top Garnish Clips <i>HH</i>	@ 8.00	64.00	X
6 Pcs. Rear Parking Sensor <i>2pc HH 4pc HH 280.00</i>	@ 398.20	2,389.20	✓ 560.00
6 Pcs. Rear Parking Sensor Ring <i>SH</i>	@ 39.10	234.60	X
1 Pc. Rear Boot <i>new</i>		1,351.00	X
2 Pcs. Rear Boot Lamp <i>HH</i>	@ 640.00	1,280.00	X
1 Pc. Rear Boot Centre Chrome <i>HH</i>		499.00	X
1 Pc. Rear Logo <i>HH</i>		99.10	X
1 Pc. E200 Emblem <i>HH</i>		90.00	X
1 Pc. CGI Emblem <i>HH</i>		89.00	X
2 Pcs. Rear Lamp <i>HH</i>	@ 690.00	1,380.00	X

Total (Panels / Parts): **15,603.00 (SGD)**

SH 20.00

list 3696.00

107. 3326.40



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit all wiring & check wiring.	120.00 30/-
To knocking, straightening, repair & renew all accident Affected area.	1,000.00 700/-
To respray painting inner & outer parts & all accident Affected area.	1,000.00 600/-
To remove & refit inner garnish, carpet & affected area.	280.00 60/-
To using Xentry Diagnostic to check control unit, reset Memory to identification standard.	380.00 NW

Total (Labor Charges): **2,780.00 (SGD)**

TOTAL COST SUMMARY

PANELS / PARTS
LABOR CHARGES

15,603.00
2,780.00

Grand Total: **18,383.00 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		Alfred Quah

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 280724

Date: 28.07.2024

Lim Joon Kang
13 Verde Place
Singapore 688622.

Mercedes Benz E200 CGI

Supplementary Repair Cost for Vehicle Reg. No: SKQ 8303 D

	Nett Price
1 Pc. Rear End Panel <i>regr</i>	989.00 X
1 Pc. Rear End Panel Garnish <i>mondy broken</i>	495.50 ✓ 364.50
1 Pc. Rear Bumper Lower Cover <i>distorted / mondy broken</i>	489.90 ✓ 369.00
1/2 Pcs. Rear Bumper Centre Bracket <i>broken</i>	380.00 ✓ 309.60

regr
2 Kic stud
Total (Panels / Parts): 2,354.40 (SGD)

We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

Payment Method

1. PAYNOW via UEN 39108900E
2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG