

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

car in workshop



GST REG. NO : M2 - 0020081 - X

ESTIMATE

*→ China
 26 July 2024*

Estimate No. : **b1 70626** Page No. : 1 of 5
 Date Estimated : **25/07/2024**
 Prepared By : **Tee Hong Da**

<p>- ESTIMATE REPAIR FOR - Chan Ee-Chong Eugene 59 East Coast Terrace #05-03 Singapore 458950</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND2146M	WBATY120509H89721	14/12/2021	X3 xDrive20i	33359

DESCRIPTION	VALUE
To replace bumper and attachment	850 1,278.00
To respray rear bumper and attachment	1038 1,550.00
To remove and install exhaust pipe, heat shield and propeller shaft to facilitate repairs.	3 531.00
To check electrical wiring system and lighting at the rear section for proper function.	177.00
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct check for proper function.	177.00
Sundries. nec	150 80.00
Total Labour 1:	3,785.00

DESCRIPTION	QTY	PRIC	VALUE
PLASTIC NUT <i>? x m</i>	1	2.90	2.90
RUBBER MOUNTING <i>? x su</i>	2	36.85	73.70
REAR SILENCER LH BRACKET <i>bt</i>	1	28.15	28.15
RR SILENCER BRACKET <i>bt</i>	1	28.15	28.15
SWING SUPPORT <i>? x su</i>	1	49.95	49.95
TAILPIPE TRIM CHROME D=90MM <i>? bt</i>	2	136.15	272.30
REAR SILENCER <i>? bt</i>	1	1,306.75	1,306.75
REAR BUMPER CARRIER <i>? bt</i>	1	832.45	832.45
LH SIDE GUIDE FOR BUMPER <i>? ca</i>	1	143.85	143.85
RH SIDE GUIDE FOR BUMPER <i>? x su</i>	1	143.85	143.85
REAR BUMPER BOTTOM REINFORCEMENT <i>? bt</i>	1	123.85	123.85
REAR BUMPER PANEL PRIMED (M/PMA) <i>form</i>	1	1,598.75	1,598.75
SET MOUNTING PDC/PMA SENSOR REAR(M) <i>ne</i>	1	135.20	135.20
REAR BUMPER BOTTOM TRIM PANEL (M) <i>de</i>	1	380.65	380.65
HOOK AND LOOP FASTENER (10X20) <i>? x m</i>	2	3.00	6.00
SET OF INSERT (EDELSTAHL) <i>? x su</i>	1	171.10	171.10
REAR SILENCER CENTRE HEAT INSULATIO <i>bt x su</i>	1	86.55	86.55

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)



303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : **b1 70626**
 Date Estimated : **25/07/2024**
 Prepared By : **Tee Hong Da**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SND2146M	WBATY120509H89721	14/12/2021	X3 xDrive20i	33359

DESCRIPTION	QTY	PRIC	VALUE
REAR SILENCER LH INSULATION <i>7bt / XSUC</i>	1	86.55	86.55
REAR SILENCER RH INSULATION <i>7. XSUC</i>	1	86.55	86.55
LOADING SILL COVER (EDELSTAHL) <i>7. XSUC</i>	1	237.35	237.35
REAR SILENCER HEAT INSULATION <i>7. 7bt /</i>	1	86.55	86.55
ULTRASONIC SENSOR BLACK <i>7. XSUC</i>	2	269.65	539.30
DECOUPLING RING PDC TORQUE CONVERTER <i>XSUC</i>	2	5.65	11.30
Total Parts :			6,431.75

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resue
Hp 90012068
3 days
30/07/24
Res by part

Labour 1	:	3,785.00
Parts	:	6,431.75
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 9%	:	919.51
Grand Total	:	11,136.26



Performance Motors

BMW Dealer



Supplementary

Estimate No. : b1 70626
 Date Estimated : 25/07/2024
 Prepared By : Tee Hong Da

Page No. :

- ESTIMATE REPAIR FOR -

Chan Ee-Chong Eugene
 59 East Coast Terrace
 #05-03

Singapore 458950

- ACCOUNT -

135

China Taiping Insurance (S) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	M LEAGE
SND2146M	WBATY120509H89721	14/12/2021	X3 xDrive20i	40836

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

* To replace RP petrol particulate filter include alignment of system and conducting checks for leak and harmful pollutants	664.00		664.00
---	--------	--	--------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING RIVET <i>neu</i>	2.70	10.00	0.00	27.00
# VIBRATION ABSORBER 38 HZ <i>de</i>	118.65	1.00	0.00	118.65
# CLAMPING BUSH <i>neu</i>	68.95	1.00	0.00	68.95
# EXHAUST SYSTEM HOLDER <i>neu</i>	28.15	1.00	0.00	28.15
# RP PETROL PARTICULATE FILTER W/SILE <i>bf</i>	3,815.75	1.00	0.00	3,815.75
# COLLAR SCREW <i>neu</i>	50.50	1.00	0.00	50.50
# EXPANDING RIVET BLACK <i>neu</i>	1.50	10.00	0.00	15.00
# SENSOR WIRE FOR SMART OPENER TOP <i>at</i>	50.60	1.00	0.00	50.60

SUPPLEMENTARY ITEMS

Total Labour :	664.00
Total Parts :	4,174.60
Total Labour & Parts (before GST) :	4,838.60

Performance Motors Limited.

Sime Darby Performance Centre, 303 Alexandra Road

Tel: 1800-2255-269

Co Reg No. 197401559W

A Sime Darby Motors Company

Finalised by: Cindy/CT DID: 63190175 Fax: 64794601